

HD Perfect Autowork Pte Ltd

Company Reg No: 202136904Z

8 Kaki Bukit Ave 4, #08-09 Premier@Kaki Bukit
Singapore 415875

Tel : 6341 6789 Fax: 6341 6778

E-mail: hdperfectautowork@gmail.com



HD PERFECT
AUTOWORK PTE LTD

DATE : 31.10.2022

TO : UOI MOTOR CLAIMS DEPTS
VEHICLE NO : SMT3141Y
MODEL : MERCEDES CLA200
DATE OF ACCIDENT : 28.10.2022
TIME OF ACCIDENT : 08:25 HRS

WDD1173432X074531
Hui Rong

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	REAR BUMPER <i>Dehd</i>	1	\$ 1,182.00	\$ 1,182.00
2	REAR BUMPER LOWER LIP (CHROME) <i>lit</i>	2	\$ 165.00	\$ 330.00
3	REAR BUMPER CENTER UPPER BEAM <i>Replaced</i>	1	\$ 178.30	\$ 178.30
4	REAR BUMPER BOTTOM CENTER GARNISH <i>new</i>	1	\$ 185.00	\$ 185.00
5	REAR BUMPER LOWER DIFFUSER <i>Deformed</i>	1	\$ 300.00	\$ 300.00
6	REAR BUMPER CORNER BRACKET <i>Replaced</i>	2	\$ 179.00	\$ 358.00
7	REAR BUMPER SIDE RETAINER <i>new</i>	2	\$ 74.00	\$ 148.00
8	REAR BUMPER EXHAUST INSULATOR <i>new</i>	2	\$ 297.00	\$ 594.00
9	REAR BUMPER REINFORCEMENT <i>Dehd</i>	1	\$ 658.00	\$ 658.00
10	TAILLAMP <i>Replaced</i>	2	\$ 825.00	\$ 1,650.00
11	REAR FENDER COWLING <i>new</i>	2	\$ 198.00	\$ 396.00
12	REAR FENDER INNER TRIM <i>new</i>	2	\$ 275.00	\$ 550.00
13	BOOTLID WEATHER STRIP <i>new</i>	1	\$ 192.00	\$ 192.00
14	REAR END PANEL <i>Dehd</i>	1	\$ 985.00	\$ 985.00
15	REAR END INNER PANEL <i>new</i>	1	\$ 764.00	\$ 764.00
16	REAR END PANEL INNER GARNISH <i>Replaced</i>	1	\$ 398.00	\$ 398.00
17	REAR FLOOR PANEL COVER BOARD <i>new</i>	1	\$ 649.00	\$ 649.00
18	REVERSE SENSOR <i>3 pieces damaged</i>	4	\$ 265.00	\$ 1,060.00
19	REVERSE SENSOR HOLDER <i>new</i>	6	\$ 64.00	\$ 384.00

TOTAL PRICE \$ 10,961.30

Handwritten notes and checkmarks:
✓
✓
✓
✓
✓
179
✓
825
755
✓
✓
223
530
150-

TO : UOI MOTOR CLAIMS DEPTS
 VEHICLE NO : SMT3141Y
 MODEL : MERCEDES CLA200
 DATE OF ACCIDENT : 28.10.2022
 TIME OF ACCIDENT : 08:25 HRS

5662.30
 5096.07

LESS 10% \$ 1,096.13
SUB TOTAL PRICE \$ 9,865.17

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	REAR BUMPER CLIP (SET) <i>nee</i>	1	\$ 80.00	\$ 80.00
2	REAR BUMPER BOTTOM CENTER GARNISH CLIP (SET) <i>nee</i>	1	\$ 80.00	\$ 80.00
3	REAR BUMPER LOWER GARNISH CLIP (SET) <i>nee</i>	1	\$ 80.00	\$ 80.00
4	TAILLAMP CLIP (SET) <i>nee</i>	1	\$ 50.00	\$ 50.00
5	REAR FENDER COWLING CLIP (SET) <i>nee</i>	1	\$ 80.00	\$ 80.00
6	REAR FENDER INNER TRIM CLIP (SET) <i>nee</i>	1	\$ 80.00	\$ 80.00
7	REAR END PANEL INSULATION SEAL <i>nee</i>	1	\$ 150.00	\$ 150.00
8	REAR END INNER PANEL SEALANT <i>nee</i>	1	\$ 150.00	\$ 150.00
9	REAR END PANEL INNER GARNISH CLIP (SET) <i>nee</i>	1	\$ 80.00	\$ 80.00

30
 +
 30
 10
 +
 +
 60
 + 130
 +

TOTAL \$ 880.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	PANEL BEATING, REMOVAL AND REPLACING PARTS	\$ 1,800.00	600
2	TO SPRAY PAINT AFFECTED AREA	\$ 1,400.00	400
3	TUFF COAT	\$ 350.00	60
4	WIRING CHECK	\$ 180.00	30
5	REMOVE AND REFIX CUSHION SEAT/ UPHOLSTRY AND ROOF LINNING TO FACILITATE REPAIR	\$ 380.00	50
6	CONDUCT WATER LEAKAGE TEST	\$ 100.00	X
7	REMOVE, REFIX AND RESET REVERSE SENSOR	\$ 350.00	50

TO : UOI MOTOR CLAIMS DEPTS
 VEHICLE NO : SMT3141Y
 MODEL : MERCEDES CLA200
 DATE OF ACCIDENT : 28.10.2022
 TIME OF ACCIDENT : 08:25 HRS

8	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 650.00	K 120
---	--	-----------	-------

1310

TOTAL \$5,210.00

TOTAL PARTS COST : \$ 10,745.17
 TOTAL LABOUR COST : \$ 5,210.00
 TOTAL REPAIR COST : \$ 15,955.17

Adrian G
H/S 31/10/22
04 Days

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.
PARTS PRICES ARE SUBJECT TO CHANGES.

Total: 6536.07.
H/S: 5.21K

YOURS FAITHFULLY,

IRENE

SERVICE ADVISOR
 IRENE
 HP : 8297 9787

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: