

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG22010776/APA3Q2**Date:** 14/04/2023**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900234866
Claimant Vehicle No :	SDZ987T	Insured Vehicle No :	SMQ2017X
Date of Loss:	18/10/2022	Nature of Claim:	TP
		Claim No:	6750137114SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SDZ987T		
Make & Model:	BMW X3, 2.0 SDRIVE 20I LED SR NAV (A)	Engine No:	B6960846N20B20A
Reg. Date:	09/01/2015 (Man. Year: 2014)	Chassis No:	WBAWY92060LE00860
Colour:	White	Odometer:	135057 km
Engine Capacity:	1997 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	245/40 R20	Rear Tyre Size:	245/40 R20
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,459.90	4,846.81	2,613.09	35.03
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,450.00	1,280.00	2,170.00	62.90
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	10,909.90	6,126.81	4,783.09	43.84
Approved Total (Overridden) (S\$)		4,900.00		
(S\$)	10,909.90	4,900.00	6,009.90	55.09
+ GST 8.00/8.00% (S\$)	872.79	392.00	480.79	55.09
Nett Amount (S\$)	11,782.69	5,292.00	6,490.69	55.09
+ Loss of Use (4.0 x S\$100.00/day) (S\$)		400.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		5,694.00		

INSPECTION

Date of Assignment:	25/10/2022	
Date Inspected:	25/10/2022	Inspected At: Success United Pte Ltd (HQ) 2 Kaki Bukit Ave 2 #01-33, Kaki Bukit AutoHub Singapore 417921
Estimated Period of Repair:	4.0 days	

Adjuster: ADRIAN LING**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TAILGATE	Dented	2,398.10 FL	*2,398.10 FL
2	1		*REAR TAILGATE WEATHERSTRIP	Not Necessary	169.00 FL	*- FL
3	1		*REAR TAILGATE MECHANISM LOCK	Not Necessary	177.50 FL	*- FL
4	1		*REAR X3 EMBLEM	Necessary	89.60 FL	*89.60 FL
5	1		*REAR BMW LOGO	Necessary	91.80 FL	*91.80 FL
6	1		*REAR BOOT LAMP RH	Cracked	455.90 FL	*455.90 FL
7	1		*REAR OUTER LAMP RH	Not Necessary	497.80 FL	*- FL
8	1		*REAR BUMPER ASSY (TOP)	Defaced	1,750.90 FL	*1,750.90 FL
9	1		*SET REAR BUMPER CLIPS	Necessary	30.00 FL	*30.00 FL
10	1		*REAR LOWER BUMPER	Deformed	524.60 FL	*524.60 FL
11	1		*REAR BUMPER EXHAUST GUARD	Repair	399.75 FL	*- FL
12	1		*REAR BUMPER INNER SPONGE	Not Necessary	289.90 FL	*- FL
13	1		*REAR BUMPER REINFORCEMENT	Not Necessary	830.80 FL	*- FL
14	1		*REAR BUMPER TOW HOOK COVER	Not Necessary	57.40 FL	*- FL
15	1		*REAR NO PLATE	Not Necessary	45.00 FS	*- FS
16	1		*REAR WINDSCREEN MOULDING	Necessary	40.00 FS	*40.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	7,848.05	5,380.90
- List Item Discount on L Items 5.00/10.00% (S\$)	388.15	534.09
Total Parts (S\$)	7,459.90	4,846.81

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE ,REPAIR AND REPLACED DAMAGED BODYPARTS ,REALIGN BODYWORKS & WHERE CONSISTENT TO THE ACCIDENT	New	1,600.00	450.00
2	TO REMOVE ,REARRANGE ELECTRICAL WIRINGS ,CHECK LIGHTING	New	150.00	30.00
3	LABOUR TO REMOVE ,REPLACE REAR WINDSCREEN	New	200.00	120.00
4	TO REMOVE ,REPLACE & TRANSFER REAR BOOT LID COMPONENTS	New	300.00	80.00
5	TO PUTTY & RESPRAY BOOTLID,BUMPER ,EXHAUST GUARD	New	1,200.00	600.00
Gross Labour Cost (\$\$)			3,450.00	1,280.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >