

SUCCESS UNITED PTE LTD

2 Kaki Bukit Ave 2, #01-33 / #02-29

Kaki Bukit Autohub, Singapore 417921

Tel No. : 67461515 / 67471787 Fax No. : 67485015

Website : www.successunited.com.sg

Buss. Reg. No. : GST No. 200402570G

AIG Asia Pacific Insurance Pte Ltd

AIG Building

78 Shenton Way, #07-16

Singapore 079120

Attention : Motor Claim Department

Contact : 64191053 Fax No. : 68357416

Xiao Tony

Estimate : TP22-129

Date : 19/10/2022

Vehicle Num. : SDZ987T

Make/Model : BMW X3-2014

Chassis/Eng# : WBAWY92060LE00860/B6960846N20B21

Accident Date : 18/10/2022

Claim No. :

Reference :

Policy No. : (08/07/2023)

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

1.	1 pc	LIST ITEMS :		
2.	1 pc	Rear Tailgate <i>Deletd</i>		2,398.10 ✓
3.	1 pc	Rear Tailgate Weatherstrip <i>Great New</i>		169.00 +
4.	1 pc	Rear Tailgate Mechanism Lock		177.50 +
5.	1 pc	Rear 'X3' Emblem		89.60 ✓
6.	1 pc	Rear 'BMW' Logo <i>free</i>		91.80 ✓
7.	1 pc	Rear Boot Lamp RH <i>cracked</i>		455.90 ✓
8.	1 pc	Rear Outer Lamp RH <i>new</i>		497.80 +
9.	1 pc	Rear Bumper Assy (Top) <i>Deletd</i>		1,750.90 ✓
10.	1 set	Rear Bumper Clips <i>new</i>		30.00 ✓
11.	1 pc	Rear Lower Bumper <i>Deletd</i>		524.60 ✓
12.	1 pc	Rear Bumper Exhaust Guard <i>new Repair</i>		399.75 +
13.	1 pc	Rear Bumper Inner Sponge <i>new</i>		289.90 +
14.	1 pc	Rear Bumper Reinforcement <i>Blue new</i>		830.80 +
		Rear Bumper Tow Hook Cover <i>new</i>		57.40 ✓

List TotalSS :

5.00% Discount S\$:

7,763.05

388.15

7,374.90

SPECIAL NETT ITEMS :

1.	1 pc	Rear No Plate <i>new</i>		45.00 +
2.	1 pc	Rear Windscreen Moulding <i>new</i>		40.00 ✓

Special Nett Total S\$:

85.00

LABOUR :

To remove, repair and replaced damaged bodyparts,
realign bodyworks & where consistent to the accident

1,600.00

450

CONTINUE / ...

SUCCESS UNITED PTE LTD

2 Kaki Bukit Ave 2, #01-33 / #02-29

Kaki Bukit Autohub, Singapore 417921

Tel No. : 67461515 / 67471787 Fax No. : 67485015

Website : www.successunited.com.sg

Buss. Reg. No. : GST No. 200402570G

AIG Asia Pacific Insurance Pte Ltd

AIG Building

78 Shenton Way, #07-16

Singapore 079120

Attention : Motor Claim Department

Contact : 64191053 Fax No. : 68357416

Estimate : TP22-129

Date : 19/10/2022

Vehicle Num. : SDZ987T

Make/Model : BMW X3-2014

Chassis/Eng# : WBAWY92060LE00860/B6960846N20B21

Accident Date : 18/10/2022

Claim No. :

Reference :

Policy No. : (08/07/2023)

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

To remove, rearrange electrical wirings, check lighting

150.00

Labour to remove, replace rear windscreen.

200.00

To remove, replace & transfer rear boot lid components.

300.00

To putty & respray bootlid, bumper, exhaust guard

1,200.00

Labour Total S\$:

3,450.00

Adrian Lj
H/S 25/10/22

04 Days

total: 6126.54

H/S: A.91K ✓

Total S\$: 10,909.90

=====

SUCCESS UNITED PTE LTD

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: