

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG22010777/APA3Q2**Date:** 10/01/2023**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900249077
Claimant Vehicle No :	SJU1933Y	Insured Vehicle No :	SMQ4826P
Date of Loss:	26/09/2022	Nature of Claim:	TP
		Claim No:	8949213354SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJU1933Y	Engine No:	3ZZ4941187
Make & Model:	TOYOTA COROLLA ALTIS, 1.6 (A)	Chassis No:	MR053ZEE106158021
Reg. Date:	23/11/2009 (Man. Year: 2009)	Odometer:	179496 km
Colour:	Silver		
Engine Capacity:	1598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Habilead 6 mm	Rear Left Side:	Habilead 6 mm
Front Right Side:	Habilead 6 mm	Rear Right Side:	Habilead 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,706.02	1,101.90	7,604.12	87.34
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,430.00	640.00	1,790.00	73.66
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	11,136.02	1,741.90	9,394.12	84.36
Approved Total (Overridden) (S\$)		1,300.00		
(S\$)	11,136.02	1,300.00	9,836.02	88.33
+ GST 7.00/7.00% (S\$)	779.52	91.00	688.52	88.33
Nett Amount (S\$)	11,915.54	1,391.00	10,524.54	88.33
+ Loss of Use (3.0 x S\$60.00/day) (S\$)		180.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		1,573.00		
Global Sum Settlement (S\$)		1,550.00		

INSPECTION

Date of Assignment:	25/10/2022	
Date Inspected:	25/10/2022	Inspected At: SM Automotive (HQ) 756 JURONG WEST STREET 74, #12-60 Singapore 640756
Estimated Period of Repair:	3.0 days	

Adjuster: ADRIAN LING**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*RH FRONT FENDER	Repair	650.10 FL	*- FL
2	1		*RH FRONT FENDER EMBLEM	Not Necessary	61.30 FL	*- FL
3	1		*RH FRONT FENDER INNER SEAL	Not Necessary	143.60 FL	*- FL
4	1		*RH FRONT DOOR	Not Necessary	1,141.30 FL	*- FL
5	1		*RH FRONT DOOR WEATHERSTRIPE	Not Necessary	278.90 FL	*- FL
6	1		*RH FRONT DOOR POWER WINDOW MOTOR	Not Necessary	789.10 FL	*- FL
7	1		*RH FRONT DOOR POWER WINDOW REGULATOR GEAR	Not Necessary	270.10 FL	*- FL
8	1		*RH FRONT WIND MIRROR	Damaged	978.10 FL	*698.00 FL
9	1		*RH FRONT WIND MIRROR COVER	Cut	131.20 FL	*131.20 FL
10	1		*RH FRONT HEADLAMP	Not Necessary	780.60 FL	*- FL
11	1		*RH FRONT HEADLAMP LOWER BRACKET	Not Necessary	121.30 FL	*- FL
12	1		*FRONT BUMPER	Not Necessary	478.90 FL	*- FL
13	1		*RH FRONT BUMPER SIDE RETAINER	Not Necessary	121.30 FL	*- FL
14	1		*RH FRONT SHOCK ABSORBER	Not Necessary	570.90 FL	*- FL
15	1		*RH FRONT LOWER ARM	Not Necessary	470.90 FL	*- FL
16	1		*RH FRONT KNUCKLE ARM	Not Necessary	279.10 FL	*- FL
17	1		*RH FRONT KNUCKLE ARM BEARING	Not Necessary	230.10 FL	*- FL
18	1		*STEERING RACK & PINION	Not Necessary	1,817.90 FL	*- FL
19	1		*RH FRONT TYRE	Not Necessary	380.00 FS	*- FS
20	1		*RH FRONT SPORT RIM	Cut	1,200.00 FS	*480.00 FS
21	1		*FRONT BUMPER CLIPS	Not Necessary	80.00 FS	*- FS
22	1		*RH FRONT FENDER INNER SEAL CLIPS	Not Necessary	60.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	11,034.70	1,309.20
- List Item Discount on L Items 25.00/25.00% (\$\$)	2,328.68	207.30
Total Parts (\$\$)	8,706.02	1,101.90

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR FOR PANEL BEATING	New	1,000.00	200.00
2	LABOUR FOR SPRAYPAINTING	New	800.00	300.00
3	WIRING CHECK	New	80.00	30.00
4	TO APPLY TUFF COATING /RUST PROOF ACCIDENT AREAS	New	200.00	30.00
5	TO CONDUCT WHEEL ALIGNMENT	New	150.00	80.00
6	LABOUR FOR REMOVE & RENEW RH FRONT UNDERCARRIAGE	New	200.00	0.00
Gross Labour Cost (S\$)			2,430.00	640.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >