

SM AUTOMOTIVE

Block C, 1 Kaki Bukit Avenue 6 #01-43 Singapore 417883

Email: SM_AUTOMOTIVE@HOTMAIL.COM

Tel: (65) 6747 9241

Fax: (65) 6741 7276

RCB No: 53231488C

GST Reg No : 53231488C

Blk 1 Kaki Bukit Ave 6

01-43

Singapore 417883

Accident date : 27/09/2022

20/10/2022

TP AG.

Xiao Tong.

Estimated repair cost for vehicle no: SJU1933Y TOYOTA COROLLA ALTIS 1.6 AUTO

CHASSIS: MR053ZEE106158021 (2009)

S/N	Qty	Items	U/price	Amount
1	1	RH FRONT FENDER <i>Repair</i>	\$650.10	\$650.10 <i>X</i>
2	1	RH FRONT FENDER EMBLEM <i>new</i> NN	\$61.30	\$61.30 <i>X</i>
3	1	RH FRONT FENDER INNER SEAL <i>new</i>	\$143.60	\$143.60 <i>+</i>
4	1	RH FRONT DOOR <i>new</i>	\$1,141.30	\$1,141.30 <i>+</i>
5	1	RH FRONT DOOR WEATHER STRIPE <i>new</i>	\$278.90	\$278.90 <i>+</i>
6	1	RH FRONT DOOR POWER WINDON MOTOR <i>new</i>	\$789.10	\$789.10 <i>+</i>
7	1	RH FRONT DOOR POWER WINDON REGELATOR GEAR <i>new</i>	\$270.10	\$270.10 <i>+</i>
8	1	RH FRONT WIND MIRROR <i>new</i>	\$978.10	\$978.10 <i>✓</i>
9	1	RH FRONT WIND MIRROR COVER <i>new</i>	\$131.20	\$131.20 <i>✓</i>
10	1	RH FRONT HEADLAMP <i>new</i>	\$780.60	\$780.60 <i>+</i>
11	1	RH FRONT HEADLAMP LOWER BRACKET <i>new</i>	\$121.30	\$121.30 <i>+</i>
12	1	FRONT BUMPER <i>new</i>	\$478.90	\$478.90 <i>+</i>
13	1	RH FRONT BUMPER SIDE RETAINER <i>new</i>	\$121.30	\$121.30 <i>+</i>
14	1	RH FRONT SHOCK ABSORBER <i>new</i>	\$570.90	\$570.90 <i>+</i>
15	1	RH FRONT LOWER ARM <i>new</i>	\$470.90	\$470.90 <i>+</i>
16	1	RH FRONT KNUCKLER ARM <i>new</i>	\$279.10	\$279.10 <i>+</i>
17	1	RH FRONT KNUCKLER ARM BEARING <i>new</i>	\$230.10	\$230.10 <i>+</i>
18	1	STEERING RACK & PINION <i>new</i>	\$1,817.90	\$1,817.90 <i>+</i>

TOTAL : \$9,314.70

LESS 25 % \$2,328.68

SUB-TOTAL : \$6,986.03

829.20

621.90

688

SJU1933Y TOYOTA COROLLA ALTIS

S/N	Qty	ITEMS / SPECIAL NETT	U/price	Amount
1	1	RH FRONT TYRE <i>new</i>	\$ 380.00	\$ 380.00 <i>+</i>
2	1	RH FRONT SPORT RIM <i>new</i>	\$1,200.00	\$1,200.00 <i>480</i>
3	1	FRONT BUMPER CLIPS <i>new</i>	\$ 80.00	\$ 80.00 <i>+</i>
4	1	RH FRONT FENDER INNER SEAL CLIPS <i>new</i>	\$ 60.00	\$ 60.00 <i>+</i>

480

TOTAL: \$1,720.00

TOTAL PARTS: \$8,706.03

Labour charges

- 1 LABOUR FOR PANEL BEATING
- 2 LABOUR FOR SPRAYPAINTING
- 3 WIRING CHECK
- 4 TO APPLY TUFF COATING/RUST PROOF ACCIDENT AREAS
- 5 TO CONDUCT WHEEL ALIGNMENT
- 6 LABOUR FOR REMOVE & RENEW RH FRONT UNDERCARRIAGE

200
\$1,000.00
300
\$800.00
30
\$80.00
30
\$200.00
80
\$150.00
+
\$200.00

Subtotal :- \$2,430.00

Total:- \$11,136.03

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Adnan Ly
L/S 25/10/22
03 Days

total: 174190
L/S: 1.31K ✓