

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

GBF3748 B
OD/sompo

M/S : SOMPO INSURANCE SINGAPORE PTE LTD
50 RAFFLES PLACE
#05-01/06 SINGAPORE LAND TOWER
SINGAPORE 048623

TEL: 64616555

FAX: 62213302

ATTN: Motor Claim Department

Claim No: ES2291117

Estimate No: ES2291117/YISHUN

Date: 31 Oct 2022

Policy No: D22MTPCVE002416

Veh Reg No: GBF3748B

Make/Model: NISSAN NISSAN
CABSTAR 3.0 5M/T ABS
2DR 2WD EURO

Chassis No: JN1SC2F24Z0858963

Engine No: ZD30013890N

Reg. Date: 27/09/2016

WS Ref: OD/SOMPO

Claim Type: Own Damage

Accident Date: 24/10/2022

Not Authorised

1/1 Rng B

Returning After Paint

6 days

Estimate Repair Cost to Vehicle No : GBF3748B

Description	U/Price	Quantity	Cost	Amount
			SS	SS
Cost Plus				
1 FRONT BUMPER	450.00	1 PC	450.00	✓
2 LH HEADLAMP	280.00	1 PC	280.00	✓
3 LH HEADLAMP LOWER GARNISH	60.00	1 PC	60.00	✓
4 FRONT GRILLE	275.00	1 PC	275.00	✓
5 FRONT GRILLE LOGO	65.00	1 PC	65.00	✓
6 FRONT PANEL	650.00	1 PC	650.00	✓
7 WIPER PANEL	290.00	1 PC	290.00	✓
8 LH WIPER ARM CAP	10.00	1 PC	10.00	✓
9 FRONT WINDSCREEN GLASS	480.00	1 PC	480.00	✓
10 FRONT WINDSCREEN GLASS MOULDING	210.00	1 PC	210.00	✓
11 AIRCON EVAPORATOR	1,350.00	1 PC	1,350.00	✓
12 FRONT RH MIRROR	120.00	1 PC	120.00	✓
13 FRONT RH MIRROR STAY	140.00	1 PC	140.00	✓
14 FRONT LH MIRROR	110.00	1 PC	110.00	✓
15 FRONT LH MIRROR STAY	140.00	1 PC	140.00	✓
16 FRONT LH MIRROR COVER (ROUND)	18.00	1 PC	18.00	X
17 FRONT LH MIRROR COVER (RECTANGLE)	68.00	1 PC	68.00	?
				4,716.00

Special Net				
18 FRONT NUMBER PLATE	20.00	1 PC	20.00	✓
19 FRONT WINDSCREEN GLASS GUM	40.00	1 PC	40.00	✓
20 ERP BRACKET	20.00	1 PC	20.00	✓
				80.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
 TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
 GST:201001158E RCB NO:201001158E

M/S : SOMPO INSURANCE SINGAPORE PTE LTD
 50 RAFFLES PLACE
 #05-01/06 SINGAPORE LAND TOWER
 SINGAPORE 048623
 TEL: 64616555 FAX: 62213302
 ATTN: Motor Claim Department

Claim No: ES2291117
 Estimate No: ES2291117/YISHUN
 Date: 31 Oct 2022
 Policy No: D22MTPCVE002416
 Veh Reg No: GBF3748B
 Make/Model: NISSAN NISSAN
 CABSTAR 3.0 5M/T ABS
 2DR 2WD EURO
 Chassis No: JN1SC2F24Z0858963
 Engine No: ZD30013890N
 Reg. Date: 27/09/2016

WS Ref: OD/SOMPO
 Claim Type: Own Damage
 Accident Date: 24/10/2022

Estimate Repair Cost to Vehicle No : GBF3748B

Description	U/Price	Quantity	Cost S\$	Amount S\$
Labour				
21 REMOVE AND REFIX FRONT WINDSCREEN GLASS	100.00	1 LA	100.00	✓
22 REMOVE AND REFIX AIRCON,CHECK,VACUUM & REFILL GAS	100.00	1 LA	100.00	✓
23 REMOVE & REFIX DASHBOARD	280.00	1 LA	280.00	2501
24 REMOVE & REFIX FRT BUMPER,HEADLAMPS,GRILLE & ATTACHMENT,REPAIR FRT INNER LFOOR PANEL,DASH PANEL,FRT CROSS MEMBER,CUT,WELD & RENEW FRT BODY PARTS	900.00	1 LA	900.00	7001
25 TO STRAIGHTEN FRT LH CHASSIS,REPAIR & REALIGN CABIN POSITION	300.00	1 LA	300.00	?
26 PUTTY & RESPRAY PAINT FRT GRILLE,FRT PANEL,WIPER PANEL,CORNAL PANEL,INNER FLOOR PANEL,DASH PANEL	950.00	1 LA	950.00	7001
27 TO REWRITE ADVERTISEMENT	120.00	1 LA	120.00	?
28 TO WRAPPING ON FRT PORTION	600.00	1 LA	600.00	?
				3,350.00

* Airbag Light 'ON' - to further check ?

Total S\$ 8,146.00
 Add GST @ 7% 570.22
 Total Amount payable S\$ 8,716.22

For Cheng Hoe Motor Pte Ltd

AUTHORISED SIGNATURE