

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22010786/SQY3Q2**Date:** 08/12/2022**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSNW00156452100	
Claimant Vehicle No :	GBF8296E	Insured Vehicle No :	YQ5011A	
Date of Loss:	25/10/2022	Nature of Claim:	TP	Claim No: SNM22D207740/C02/KHONGLH

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBF8296E			
Make & Model:	MITSUBISHI CANTER, 3.0 D FEA01BR1SDEB (M)		Engine No:	4P10C42610
Reg. Date:	20/03/2017 (Man. Year: 2016)		Chassis No:	FEA01BA20499
Colour:	Blue	Odometer:	162378 km	
Engine Capacity:	2998 cc			
Market Value/New Car Price:	N/A			
Sum Insured (S\$):	Market Value/New Car Price			

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/75 R15	Rear Tyre Size:	185/75 R15
Front Left Side:	Yokohama 5 mm	Rear Left Side:	Yokohama 5 mm
Front Right Side:	Yokohama 5 mm	Rear Right Side:	Yokohama 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,682.30	1,540.69	2,141.61	58.16
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,220.00	630.00	590.00	48.36
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,902.30	2,170.69	2,731.61	55.72
Approved Total (Overridden) (S\$)		1,700.00		
(S\$)	4,902.30	1,700.00	3,202.30	65.32
+ GST 7.00/7.00% (S\$)	343.16	119.00	224.16	65.32
Nett Amount (S\$)	5,245.46	1,819.00	3,426.46	65.32

INSPECTION

Date of Assignment:	31/10/2022	Kan Fook Sing Motor Workshop (Defu)
Date Inspected:	23/11/2022 Inspected At:	Blk 8 Defu South Street 1, Defu Industrial City #04-29
Estimated Period of Repair:	3.0 days	Singapore 533758

Adjuster: S Mohamed Irfan Bin Mohamed Iqbal**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 08 Dec 2022)	
Parts:	N/A	mitsubishi canter 3.0 D FEA01BR1SDEB (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBF8296E)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT CORNER PANEL LH	Cracked	524.54 F	*420.00 FL
2	1		*FRONT SIDE LAMP LH	Cracked	222.53 F	*180.00 FL
3	1		*FRONT SIGNALLAMP LH	Cracked	266.36 F	*250.00 FL
4	1		*FRONT HEADLAMP LH	Cracked	501.40 F	*501.40 FL
5	1		*FRONT BUMPER PAD LH	Scratched	353.71 F	*200.00 FL
6	1		*FRONT SIDE MIRROR STAY LH	Not Necessary	475.20 F	*- FL
7	1		*FRONT SIDE MIRROR ROUND LH	Cracked	58.79 F	*58.79 FL
8	1		*FRONT SIDE MIRROR SQUARE LH	Scratched	101.69 F	*101.69 FL
9	1		*FRONT GRILLE	Not Necessary	1,178.08 F	*- FL
						F=Franchise part. L=ListItemDisc.
					Sub Total (\$\$)	3,682.30 1,711.88
					- List Item Discount on L Items 0.00/10.00% (\$\$)	0.00 171.19
					Total Parts (\$\$)	3,682.30 1,540.69

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING SYSTEM	New	50.00	30.00
2	TO REMOVE ALL NECESSARY AFFECTED PARTS WELD CUT PANEL BEAT AND FITTING NEW PARTS	New	550.00	400.00
3	SPRAYPAINTING CHARGES	New	620.00	200.00
Gross Labour Cost (S\$)			1,220.00	630.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >