



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623			Ref: CS/SMO22010796/Uny3e2	
			Date: 13/12/2022	
			Code: SMO	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	SJE 8807S	Veh. Inspected	SLP 2581A	
Policy No.	D22MTPV01006163	Coverage (\$)	0.00	
Claim No.	CMTD2203753/MYE	Excess (\$)	0.00	
Assign From	MELVIN YE	Assign Date	31/10/2022	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	MAZDA 6 (A)	c.c	2488	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	JM6GL1031H0120685	Colour	GREY	
Odometer	71449 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	225/45 R19	BRIDGESTONE	6 mm	
L/H Front Tyre	225/45 R19	BRIDGESTONE	6 mm	
R/H Rear Tyre	225/45 R19	BRIDGESTONE	6 mm	
L/H Rear Tyre	225/45 R19	BRIDGESTONE	6 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	15/10/2022	Inspection Date	31/10/2022	
Survey held at	ETHOZ GROUP LTD 22 TAMPINES STREET 92 SINGAPORE 528876			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:			<b>4 Working Days</b>	