

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

CS/SMO22010796/Uny3

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

4 days

Res.: Yes or No

Lum Sum:

18.1 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

L1A 44983

Veh No:

SLP 2581A

Yr Regn:

30/05/17

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

CA/

Make:

Mazda

6

c.c

2488

Colour:

Grey

A/C:

Insured / Std / NI / NA

Sp. Reading

71449

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

JM 66 L103 1H10120685

Gen. Cond:

Good / Fair / Poor / Burnt

Steering:

In order / Jammed / Leaked / Burnt or

Brake:

In order / Jammed / Leaked / Burnt or

Modi:

Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

225/45R19

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

0

mm

L/Bal.

6

mm

D.O.A.

15/10/22

D.O.I.

31/10/22

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Dep 14k.

check ins cost plus how much? No second hand parts use cost price
 cost plus 25% for car.

12/12/22 P/P \$ 4047.50 informed Sha kh.
 (Red, \$2713.75, 40%)

Date/Time, File Pass to?

☐

: Preli. Report

1) 12/12/22

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

4

Resurvey No. of Trip:

3

Survey Fee:

Transportation:

Report Format :

TP

Lump Sum / I.B.I: (\$

4047.50

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

) S + RS, SI

) Photos

) Others

TOTAL

> **Back to OneMotoring****Enquire PARF/COE Rebate for Registered Vehicle**

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	979A
Vehicle Details	
Vehicle No.:	SLP2581A
Vehicle to be Exported:	No
Intended Deregistration Date:	31 Oct 2022
Vehicle Make:	MAZDA
Vehicle Model:	MAZDA6 4-DOOR SEDAN 2.5L SP.6EAT SR LED
Primary Colour:	Grey
Manufacturing Year:	2017
Engine No.:	PY20943758
Chassis No.:	JM6GL1031H0120685
Maximum Power Output:	141.0 kW (189 bhp)
Open Market Value:	\$26,201.00
Original Registration Date:	30 May 2017
First Registration Date:	30 May 2017
Transfer Count:	0
Actual ARF Paid:	\$28,682.00 14341
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	29 May 2027
PARF Rebate Amount:	\$20,077.00
Intended COE Rebate Details	
COE Expiry Date:	29 May 2027
COE Category:	E - Open Category
COE Period(Years):	10
QP Paid:	\$54,556.00
COE Rebate Amount:	\$24,906.00
Total Rebate Amount:	\$44,983.00

The information contained herein is correct as at 31 Oct 2022

OK

Search Jobs Vacancies

Let JobStreet fulfil your dreams of a better job.

Open

Post an Advertisement
Sell it yourself! Advertise it at just
\$68 until it's SOLD!

Post an Ad Advertiser Login Ways of Selling

Attrage 1.2A , 100% Loan by GV CARS FINANCING



Secured Loan by In house
finance , Warranty packages and
services available.
GV Automobile Centre StarAd

KA-HUP

HOTLINE: 6741 9997

VALUE FOR MONEY
VALUE FOR TIME
A PEACE OF MIND

view our cars

Sort by Date Posted 20 results/page

7 vehicles

<

PLEASE ARRANGE TO SURVEY
VEHICLE AT 30 BUKIT BATOK
CRESCENT (S 658075)

Selamatshahh
CLAIM DEPARTMENT
DID : 66547519
FAX :

Date : 27/10/2022

To : SOMPO INSURANCE SINGAPORE PTE. LTD.

ESTIMATION

Attn : Motor Claim Department

FAX :

Owner : ROY YONG KEN KOK

: SOMPO INSURANCE SINGAPORE PTE. LTD.

Certificate No : D22MTPV01006739

Accident Date : 15/10/2022

Vehicle No : SLP-2581-A

Make & Model : MAZDA MAZDA6 4-DOOR SEDAN 2.5L SP.6E

ESTIMATED REPAIR COST DETAILS

Excess : 0.00

Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
<u>List Item</u>			
1	REAR BUMPER <i>DD</i>	1,350.00	<i>—</i>
1	REAR BUMPER REINFORCEMENT <i>R</i>	520.00	<i>X</i>
2	REAR BUMPER REFLECTOR <i>17</i>	90.00	<i>X</i>
2	REAR BUMPER TOW COVER. <i>M.S</i>	96.00	<i>—</i>
2	REAR BUMPER RETAINER <i>sent/re</i>	110.00	<i>—</i>
10	REAR BUMPER CLIPS <i>ner</i>	30.00	<i>—</i>
1	END PANEL <i>R</i>	760.00	<i>X</i>
1	END PANEL TOP GARNISH <i>17</i>	120.00	<i>X</i>
1	BOOT LID <i>R</i>		<i>X</i>
	RESTORE		

Date : 27/10/2022

To : SOMPO INSURANCE SINGAPORE PTE. LTD.

ESTIMATION

Attn : Motor Claim Department

FAX :

Owner : ROY YONG KEN KOK

: SOMPO INSURANCE SINGAPORE PTE. LTD.

Certificate No : D22MTPV01006739

Accident Date : 15/10/2022

Vehicle No : SLP-2581-A

Make & Model : MAZDA MAZDA6 4-DOOR SEDAN 2.5L SP.6E

ESTIMATED REPAIR COST DETAILS

Excess : 0.00

Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
1	BOOT LID LOCK <i>17</i>	110.00	<i>X</i>
1	REAR LOGO <i>17</i>	38.00	<i>X</i>
1	EMBLEM - MAZDA 6 <i>17</i>	50.00	<i>X</i>
1	EMBLEM - SKYACTIV <i>17</i>	55.00	<i>X</i>
	Sub Total	3329.00	
	Add 25% On Parts <i>0</i>	832.25	
	<u>Special Nett Item</u>		
<i>2</i>	REVERSE SENSOR <i>shock/turn @ 160 x 2 = 320</i>	220.00	<i>✓</i>

Date : 27/10/2022

To : SOMPO INSURANCE SINGAPORE PTE. LTD.

ESTIMATION

Attn : Motor Claim Department

FAX :

Owner : ROY YONG KEN KOK

: SOMPO INSURANCE SINGAPORE PTE. LTD.

Certificate No : D22MTPV01006739 Accident Date : 15/10/2022

Vehicle No : SLP-2581-A Make & Model : MAZDA MAZDA6 4-DOOR SEDAN 2.5L SP.6E

ESTIMATED REPAIR COST DETAILS

Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
	Sub Total	220.00	
Labour & Misc			
	LABOUR TO FACILITATE REPAIR	800.00	500
	TO RESPRAY AFFECTED AREAS	800.00	600
	TO CHECK AND RECONNECT ALL NECESSARY WIRINGS	30.00	30
	Sub Total	1630.00	

Remarks:

not Authorized WP

maruschus@lkkauto.com

Surveyor's name: Marcus LKH HP90296608

Principal's name: ROY YONG KEN KOK

Survey Date & Time: 31/10/22 @ 11.45am

take photo before painting

SUB TOTAL

GST 7.0 %

TOTAL

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: 6,432.04
Date:

PLEASE ARRANGE TO SURVEY
VEHICLE AT 30 BUKIT BATOK
CRESCENT (S 658075)

Selamatshahh
CLAIM DEPARTMENT
DID : 66547519
FAX :

Date : 08/12/2022

To : SOMPO INSURANCE SINGAPORE PTE. LTD.

SUPPLEMENTARY

Attn : Motor Claim Department

FAX :

Owner : ROY YONG KEN KOK

: SOMPO INSURANCE SINGAPORE PTE. LTD.

Certificate No : D22MTPV01006739 Accident Date : 15/10/2022

Vehicle No : SLP-2581-A Make & Model : MAZDA MAZDA6 4-DOOR SEDAN 2.5L SP.6E

ESTIMATED REPAIR COST DETAILS

Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
List Item			
1	REAR FENDER LH <i>~</i>	RESTORE <i>X</i>	
1	REAR FENDER RH <i>~</i>	RESTORE <i>X</i>	
4	SENSOR HOLDER <i>del</i>		120.00 <i>60</i>
	Sub Total	120.00	
	Add 25% On Parts	30.00	
Labour & Misc			
	TO REPAIR REAR FENDER RH/LH	200.00	<i>100</i>
	TO RESPRAY REAR FENDER RH/LH	400.00	<i>360</i>

Date : 08/12/2022

To : SOMPO INSURANCE SINGAPORE PTE. LTD.

SUPPLEMENTARY

Attn : Motor Claim Department

FAX :

Owner : ROY YONG KEN KOK

: SOMPO INSURANCE SINGAPORE PTE. LTD.

Certificate No : D22MTPV01006739 Accident Date : 15/10/2022

Vehicle No : SLP-2581-A Make & Model : MAZDA MAZDA6 4-DOOR SEDAN 2.5L SP.6E

ESTIMATED REPAIR COST DETAILS

Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
	Sub Total	600.00	

Remarks:

SUB TOTAL	750.00
GST 7.0 %	52.50
TOTAL	802.50

Surveyor's name: _____

Principal's name: ROY YONG KEN KOK

Survey Date & Time: _____

Date : 08/12/2022
To : SOMPO INSURANCE SINGAPORE PTE. LTD.

Attn : Motor Claim Department FAX :

Owner : ROY YONG KEN KOK
Insured By : SOMPO INSURANCE SINGAPORE PTE. LTD.
Certificate No : D22MTPV01006739 Accident Date : 15/10/2022
Vehicle No : SLP-2581-A Make & Model : MAZDA MAZDA6 4-DOOR SEDAN 2.5L SP.6E

FINAL ESTIMATED REPAIR COST DETAILS Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR AMT (\$)
List Item			
1	REAR FENDER LH RESTORE	0.00	0.00
1	REAR FENDER RH RESTORE	0.00	0.00
4	SENSOR HOLDER	120.00	60.00
1	REAR BUMPER	1350.00	1350.00
1	REAR BUMPER REINFORCEMENT	520.00	0.00
2	REAR BUMPER REFLECTOR	90.00	0.00
2	REAR BUMPER TOW COVER.	96.00	96.00
2	REAR BUMPER RETAINER	110.00	110.00
10	REAR BUMPER CLIPS	30.00	30.00
1	END PANEL RESTORE	760.00	0.00
1	END PANEL TOP GARNISH	120.00	0.00
1	BOOT LID RESTORE	0.00	0.00
1	BOOT LID LOCK	110.00	0.00
1	REAR LOGO	38.00	0.00

PAGE : 1



Date : 08/12/2022
To : SOMPO INSURANCE SINGAPORE PTE. LTD.

Attn : Motor Claim Department FAX :

Owner : ROY YONG KEN KOK

Insured By : SOMPO INSURANCE SINGAPORE PTE. LTD.

Certificate No : D22MTPV01006739 Accident Date : 15/10/2022

Vehicle No : SLP-2581-A Make & Model : MAZDA MAZDA6 4-DOOR SEDAN 2.5L SP.6E

FINAL ESTIMATED REPAIR COST DETAILS Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR AMT (\$)
1	EMBLEM - MAZDA 6	50.00	0.00
1	EMBLEM - SKYACTIV	55.00	0.00
2	REVERSE SENSOR	320.00	320.00
Sub Total		3009.00	1966.00
Add 25% On Parts		0.00	491.50
Labour & Misc			
TO REPAIR REAR FENDER RH/LH		200.00	100.00
TO RESPRAY REAR FENDER RH/LH		400.00	360.00
LABOUR TO FACILITATE REPAIR		800.00	500.00
TO RESPRAY AFFECTED AREAS		800.00	600.00
TO CHECK AND RECONNECT ALL NECESSARY WIRINGS		30.00	30.00

PAGE : 2



Date : 08/12/2022

To : SOMPO INSURANCE SINGAPORE PTE. LTD.

Attn : Motor Claim Department

FAX :

Owner : ROY YONG KEN KOK

Insured By : SOMPO INSURANCE SINGAPORE PTE. LTD.

Certificate No : D22MTPV01006739 Accident Date : 15/10/2022

Vehicle No : SLP-2581-A Make & Model : MAZDA MAZDA6 4-DOOR SEDAN 2.5L SP.6E

FINAL ESTIMATED REPAIR COST DETAILS Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR AMT (\$)
	Sub Total	2230.00	1590.00
	Sub Total	6,941.25	4,047.50
	GST 7.0 %	485.89	283.32
	Total	7,427.14	4,330.82

Surveyor Name : MARCUS - LKK

Date & Time : 31/10/2022 11:45:00 am

Salamatshahh

PAGE : 3

CLAIM DEPARTMENT

DID : 66547519

FAX :

