



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

LONPAC INSURANCE BHD

300 BEACH ROAD
#17-04/07 THE CONCOURSE
SINGAPORE 199555

INV No. AC2303831

INV Date 16/06/2023

Reference CC4/LPC22010797/Apa3q2

Code LPC2

PROFESSIONAL SERVICE FEE

Vehicle No. SJT 8887G
Insured Veh. GY 6545R
Claim No. 22/22/22/VC05/026492
Policy No. Z22VCO5011961
Accident Date 29/10/2022
Inspection Date 04/11/2022

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (8%)	32.00
Grand Total	432.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSE SINGAPORE 199555			Ref: CC4/LPC22010797/Apa3q2 Date: 16/06/2023 Code: LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GY 6545R	Veh. Inspected	SJT 8887G	
Policy No.	Z22VCO5011961	Coverage (\$)	0.00	
Claim No.	22/22/22/VC05/026492	Excess (\$)	0.00	
Assign From	CHARMAINE KONG	Assign Date	31/10/2022	
2. Vehicle Particulars & Condition				
Make & Model	AUDI A6	c.c	1984	
Engine No.	HIDDEN	Year of Reg.	2008	
Chassis No.	WAUZZZ4F68N060649	Colour	SILVER	
Odometer	173648 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	225/55 R16	MICHELIN	6 mm	
L/H Front Tyre	225/55 R16	MICHELIN	6 mm	
R/H Rear Tyre	225/55 R16	MICHELIN	6 mm	
L/H Rear Tyre	225/55 R16	MICHELIN	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	29/10/2022	Inspection Date	04/11/2022	
Survey held at	PREMIUM AUTOMOBILES PTE LTD 55 UBI ROAD 1 . SINGAPORE 408699			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		11 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJT 8887G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR BUMPER (SN)	DEFORMED	2,725.00	2,725.00
1	REAR BUMPER SPOILER (SN)	DEFORMED	235.00	234.50
1	REAR BUMPER REINFORCEMENT BEAM (SN)	NOT NECESSARY	1,073.00	-
2	REAR BUMPER HOLDER BRACKET -LH/RH (SN)	NOT NECESSARY	440.00	-
1	REAR BUMPER HOLDING STRAP (SN)	NECESSARY	95.00	94.40
2	REAR BUMPER ADJUSTMENT PART-LH/RH (SN)	NOT NECESSARY	150.00	-
2	REAR BUMPER GUIDE SECTION -LH/RH	O/S DAMAGED	122.00	60.20
1	REAR LID (SN)	DENTED	4,032.00	4,032.00
2	REAR LID HINGE -LH/RH (SN)	NOT NECESSARY	458.00	-
1	REAR LID LOCK (SN)	DAMAGED	212.00	212.00
1	REAR LID LOCK COVER (SN)	NOT NECESSARY	21.00	-
1	REAR LID LOCK STRIKER (SN)	NOT NECESSARY	61.00	-
1	REAR LID FLAP LOCK COVER CAP (SN)	NOT NECESSARY	13.00	-
1	REAR LID GRIP MOLDING (SN)	NOT NECESSARY	455.00	-
1	REAR LID FLAP GASKET (SN)	NOT NECESSARY	431.00	-
2	REAR LID GRAB HANDLE -LH/RH (SN)	NOT NECESSARY	28.00	-
2	REAR LID HANDLE RETAINING BAR -LH/RH (SN)	NOT NECESSARY	14.00	-
2	REAR LID ADJUSTABLE STOP BUFFER-LH/RH	NOT NECESSARY	61.00	-
1	AUDI EMBLEM (SN)	NECESSARY	144.00	143.50
1	'A6' INSCRIPTION (SN)	NECESSARY	104.00	103.50
1	'2.0T' INSCRIPTION (SN)	NECESSARY	104.00	103.50
1	REAR LID CHROME DECORATIVE TRIM (SN)	NECESSARY	391.00	391.00
2	REAR PARKING AID SENSOR -INNER /OUTER (SN)	MISSING (1 PCS ONLY)	531.00	265.50
2	REAR TAIL LIGHT -LH/RH (SN)	CRACKED	1,402.00	1,402.00
2	REAR LICENCE PLATE LIGHT -LH/RH (SN)	NOT NECESSARY	82.00	-
1	REAR CROSS PANEL TRIM (SN)	NOT NECESSARY	290.00	-
1	REAR LID TRIM PANEL (SN)	NOT NECESSARY	428.00	-
1	REAR NO PLATE (SN)	DENTED	60.00	60.00
1	SUNDRIES (SN)	NECESSARY	400.00	21.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FRONT BUMPER (SN) (ADDITIONAL)	TO REPAIR SEE LABOUR	2,664.00	-
1	FRONT BUMPER COVER (SN) (ADDITIONAL)	NOT NECESSARY	126.00	-
1	RADIATOR GRILLE LISENCE PLATE TRIM (SN) (ADDITIONAL)	NECESSARY	217.00	217.00
1	RADIATOR GRILLE (SN) (ADDITIONAL)	CRACKED	905.00	905.00
1	'CAUTION SIGN' (SN) (ADDITIONAL)	NECESSARY	15.50	15.50
1	RHS REAR EXHAUST SILENCER (SN) (ADDITIONAL)	BENT	1,396.00	1,396.00
1	DUAL CLIP (SN) (ADDITIONAL)	NECESSARY	66.00	66.00
1	FRONT NUMBER PLATE (SN) (ADDITIONAL)	DENTED	60.00	60.00
			20,011.50	12,507.60
	LABOUR			
	TO REMOVE AND TRANSFER REAR PARKING AID.CHECK FUNCTION.		280.00	280.00
	TO REMOVE AND TRANSFER REAR LID'S CONVENIENCE LOCK SYSTEM AND WIRE HANRNESS FOR TAIL LIGHTS .		280.00	280.00
	TO DISMANTLE AND RENEW REAR BUMPER AND REAR LID.TO REPAIR REAR END PANELLING.RE-ORGANIZE CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED .		2,500.00	2,000.00
	TO RESPRAY REAR BUMPER ,REAR LID ,HINGES AND REAR END PANELLING.		3,500.00	2,400.00
	TO CARRY OUT DIAGNOSTIC CHECK .		192.00	192.00
	TO REMOVE ,CHECK AND TRANSFER FRONT WIRE HARNESS HORNS ,OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY . (ADDITIONAL)		360.00	360.00
	TO DISMANTLE AND RENEW FRONT BUMPER ,RE-ORGANIZE CRASH MANAGEMENT COMPONENTS REINSTALL ALL PARTS REMOVED. (ADDITIONAL)		1,200.00	800.00
	TO RESPRAY FRONT BUMPER . (ADDITIONAL)		1,000.00	800.00
	TO REMOVE AND RENEW RHS REAR EXHAUST SILENCER AND ALIGN TO POSITION. (ADDITIONAL)		480.00	480.00
	TO REPAIR SPARE WHEEL HOUSING. (ADDITIONAL)		400.00	400.00
	TO RESPRAY SPARE WHEEL HOUSING. (ADDITIONAL)		800.00	800.00
			10,992.00	8,792.00
	GRAND TOTAL		31,003.50	21,299.60

Report Ref No. CC4/LPC22010797/Apa3q2



RECOMMENDED COST OF REPAIRS			21,299.60
-----------------------------	--	--	-----------

Report Ref No. CC4/LPC22010797/Apa3q2

A handwritten signature in black ink, appearing to read 'A. Ling'.

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SJT 8887G

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SJT 8887G

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SJT 8887G

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SJT 8887G

RE-INSPECTION

