

PREMIUM AUTOMOBILES

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg



TP Con Pac.
Xiao Tony.

Supplementary Estimate

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 / Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PA/TP/0958/2022/EQ 21-Dec-22 Kee Siang 1 of 1 SJT 8887 G AUDI A6 2.0T FSI 4F208H
Quantity	Description	Unit Price	Amount
Labours			
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHHER ASSY. S/N	\$ 360.00	X.
2	TO DISMANTLE AND RENEW FRONT BUMPER, RE-ORGANIZE CRASH MANAGEMENT COMPONENTS, REINSTALL ALL PARTS REMOVED.	\$ 1,200.00	500
3	TO RESPRAY FRONT BUMPER	\$ 1,000.00	550.
Parts			
1	FRONT BUMPER <i>Renew</i>	\$ 2,664.00	X
2	FRONT BUMPER COVER <i>new</i>	\$ 126.00	X
3	RADIATOR GRILLE LISENCE PLATE TRIM <i>new</i>	\$ 217.00	✓
4	RADIATOR GRILLE <i>new</i>	\$ 905.00	✓
5	"CAUTION SIGN" <i>new</i>	\$ 16.00	✓
6			
GRAND TOTAL		\$ 6,488.00	

For Premium Automobiles Pte Ltd



Authorised Signature

Adrian Ling
21/12/22

SLG

Add 3 Days. for the repairs to the front portion.