

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/TP/0958/2022/EQ
DATE : 2-Nov-22
WIP : 48359

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 4/11/2022

YOUR INSURED VEH NO : GY 6545 R

Lonpac Insurance BHD

300 Beach Road

#17-04/07, The Concourse

Singapore 199555

Attn: Motor Claims Dept

OWNER'S NAME : MR YANG YAO CHUAN GARY
ADDRESS : 29B WEST COAST PARK
#11-20
SINGAPORE 127724
TELEPHONE : HP +65 94313408
TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : 2100205767-12
VEHICLE NO : **SJT 8887 G**
MODEL CODE : AUDI A6 2.0T FSI 4F208H
MODEL YEAR : 27/3/2008
ENGINE NO : BPJ074925
CHASSIS NO : WAUZZZ4F68N060649
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 29-Oct-22
PLACE OF ACCIDENT : ALONG COMMONWEALTH AVENUE NEXT
TO BUS STOP

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SJT 8887 G

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND TRANSFER REAR PARKING AID. CHECK FUNCTION.	S/N \$	280.00	
2	TO REMOVE AND TRANSFER REAR LID'S CONVENIENCE LOCK SYSTEM AND WIRE HARNESS FOR TAIL LIGHTS.	S/N \$	280.00	
3	TO DISMANTLE AND RENEW REAR BUMPER AND REAR LID. TO REPAIR REAR END PANELLING. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	2,500.00	
4	TO RESPRAY REAR BUMPER, REAR LID, HINGES AND REAR END PANELLING.	\$	3,500.00	
5	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$	192.00	
TOTAL LABOUR CHARGES		:	\$ 6,752.00	

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SJT 8887 G

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	REAR BUMPER	1	\$ 2,725.00	
2	REAR BUMPER SPOILER	1	\$ 235.00	
3	REAR BUMPER REINFORCEMENT BEAM	1	\$ 1,073.00	
4	REAR BUMPER HOLDER BRACKET - LH / RH	2	\$ 440.00	
5	REAR BUMPER HOLDING STRAP	1	\$ 95.00	
6	REAR BUMPER ADJUSTMENT PART - LH / RH	2	\$ 150.00	
7	REAR BUMPER GUIDE SECTION - LH / RH	2	\$ 122.00	
8	REAR LID	1	\$ 4,032.00	
9	REAR LID HINGE - LH / RH	2	\$ 458.00	
10	REAR LID LOCK	1	\$ 212.00	
11	REAR LID LOCK COVER	1	\$ 21.00	
12	REAR LID LOCK STRIKER	1	\$ 61.00	
13	REAR LID FLAP LOCK COVER CAP	1	\$ 13.00	
14	REAR LID GRIP MOLDING	1	\$ 455.00	
15	REAR LID FLAP GASKET	1	\$ 431.00	
16	REAR LID GRAB HANDLE - LH / RH	2	\$ 28.00	
17	REAR LID HANDLE RETAINING BAR - LH / RH	2	\$ 14.00	
18	REAR LID ADJUSTABLE STOP BUFFER - LH / RH	2	\$ 61.00	
19	AUDI EMBLEM	1	\$ 144.00	
20	"A6" INSCRIPTION	1	\$ 104.00	
SUB TOTAL SPARE PARTS		:	\$ 10,874.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SJT 8887 G

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	"2.0 T" INSCRIPTION	1	\$ 104.00	
22	REAR LID CHROME DECORATIVE TRIM	1	\$ 391.00	
23	REAR PARKING AID SENSOR - INNER / OUTER	2	\$ 531.00	
24	REAR TAIL LIGHT - LH / RH	2	\$ 1,402.00	
25	REAR LICENCE PLATE LIGHT - LH / RH	2	\$ 82.00	
26	REAR CROSS PANEL TRIM	1	\$ 290.00	
27	REAR LID TRIM PANEL	1	\$ 428.00	
28	REAR NO PLATE	S/N	\$ 60.00	
29	SUNDRIES		\$ 400.00	
TOTAL SPARE PARTS		:	\$ 14,562.00	
TOTAL LABOUR CHARGES		:	\$ 6,752.00	
GRAND TOTAL		:	\$ 21,314.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE
AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER
LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF
REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO
MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR
APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT