

ASS. REC. BY: _____ REP: _____

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop m/s _____
 of _____
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

Veh No: SJT8887G, Yr Regn: 2008, March
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or _____
 Make: Audi A6 c.c. 1984
 Colour: Silver A/C: Insured / Std / NI / NA
 Sp.Reading: 173648 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: WAU2224F68N060649
 Gen. Cond: (Good) Fair / Poor / Burnt
 Steering: (Inorder) Jammed / Leaked / Burnt or _____
 Brake: (Inorder) Jammed / Leaked / Burnt or _____
 Mod: Nil / S/Rim / STD A/Rim or _____

(Policy Condition)
 Remark: The veh had commenced its
 repair at the time of inspection.
 Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent?: Yes or No
 GIA / PR Seen: _____ Consistent?: Yes or No
 Est. Repairs: _____ days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No
 CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____
 Vehicle: IN / OUT

N/S	O/S

Tyre Size: F: 225/55R16
 R: 225/55R16
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or _____
 Front _____ Rear _____
 R/Bal. 06 mm R/Bal. 06 mm
 L/Bal. 06 mm L/Bal. 06 mm
 D.O.A. _____ D.O.I. 4/11/22
 Survey held at Premium
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or _____
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	TP Lon Pae
	COE Expiry: 26/03/28.
	MV: 58K (Depreciation @ 10.5K x 5.5Yr = 58K).
	PV: 24.3K
	Nett: 33.7K.

Date/Time, File Pass to? : Preli. Report
 : Final Report
 Date/Time, File Return to?
 1) _____
 2) _____
 Report Format: _____
 Days Of Repair: _____
 Resurvey No. of Trip: _____
 Add Fee: : Site Insp (\$) _____
 : Interview (\$) _____
 : Tech. Insp (\$) _____
 Survey Fee: _____
 Transportation: _____
 Photos _____
 Other: _____



PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/TP/0958/2022/EQ
DATE : 2-Nov-22
WIP : 48359

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 4/11/2022
YOUR INSURED VEH NO : GY 6545 R

Lonpac Insurance BHD
300 Beach Road
#17-04/07, The Concourse
Singapore 199555
Attn: Motor Claims Dept

OWNER'S NAME : MR YANG YAO CHUAN GARY
ADDRESS : 29B WEST COAST PARK
#11-20
SINGAPORE 127724
TELEPHONE : HP +65 94313408
TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : 2100205767-12
VEHICLE NO : **SJT 8887 G**
MODEL CODE : AUDI A6 2.0T FSI 4F208H
MODEL YEAR : 27/3/2008
ENGINE NO : BPJ074925
CHASSIS NO : WAUZZZ4F68N060649
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 29-Oct-22
PLACE OF ACCIDENT : ALONG COMMONWEALTH AVENUE NEXT
TO BUS STOP



55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

Xiao Tong.

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SJT 8887 G

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND TRANSFER REAR PARKING AID. CHECK FUNCTION.	S/N \$	280.00	✓ ✓
2	TO REMOVE AND TRANSFER REAR LID'S CONVENIENCE LOCK SYSTEM AND WIRE HARNESS FOR TAIL LIGHTS.	S/N \$	280.00	✓ ✓
3	TO DISMANTLE AND RENEW REAR BUMPER AND REAR LID. TO <u>REPAIR REAR END PANELLING</u> . RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	2,500.00	1600 + 400 } ✓ H/S ✓
4	TO RESPRAY REAR BUMPER, REAR LID, HINGES AND <u>REAR END PANELLING</u> .	\$	3,500.00	1600 + 800 } ✓ H/S ✓
5	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$	192.00	✓ ✓
TOTAL LABOUR CHARGES		:	\$ 6,752.00	

~~+ 1 day repair day~~
=

Total add 2 days of
 Repairs for repairs to
 end panel and
 Spare tyre panel.

*Adrian L
 H/S*



55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SJT 8887 G

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	REAR BUMPER <i>delnd</i>	1	\$ 2,725.00	✓
2	REAR BUMPER SPOILER <i>delnd</i>	1	\$ 235.00	✓ 234.50
3	REAR BUMPER REINFORCEMENT BEAM ?	1	\$ 1,073.00	? x NN
4	REAR BUMPER HOLDER BRACKET - LH / RH ?	2	\$ 440.00	? x NN
5	REAR BUMPER HOLDING STRAP <i>Rec</i>	1	\$ 95.00	✓ 94.40
6	REAR BUMPER ADJUSTMENT PART - LH / RH <i>new</i>	2	\$ 150.00	+
7	REAR BUMPER GUIDE SECTION - LH / RH <i>new RH Dmgd</i>	2	\$ 122.00	61 60.20
8	REAR LID <i>Delnd</i>	1	\$ 4,032.00	✓
9	REAR LID HINGE - LH / RH <i>new</i>	2	\$ 458.00	+
10	REAR LID LOCK <i>Dmgd</i>	1	\$ 212.00	✓
11	REAR LID LOCK COVER <i>new</i>	1	\$ 21.00	+
12	REAR LID LOCK STRIKER <i>new</i>	1	\$ 61.00	+
13	REAR LID FLAP LOCK COVER CAP <i>new</i>	1	\$ 13.00	+
14	REAR LID GRIP MOLDING <i>new</i>	1	\$ 455.00	+
15	REAR LID FLAP GASKET <i>new</i>	1	\$ 431.00	+
16	REAR LID GRAB HANDLE - LH / RH <i>new</i>	2	\$ 28.00	+
17	REAR LID HANDLE RETAINING BAR - LH / RH <i>new</i>	2	\$ 14.00	+
18	REAR LID ADJUSTABLE STOP BUFFER - LH / RH <i>new</i>	2	\$ 61.00	+
19	AUDI EMBLEM <i>3pc</i>	1	\$ 144.00	✓ 143.50
20	"A6" INSCRIPTION <i>3pc</i>	1	\$ 104.00	✓ 103.50
SUB TOTAL SPARE PARTS			\$ 10,874.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SIT 8887 G

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	"2.0 T" INSCRIPTION <i>new</i>	1	\$ 104.00	✓ 103.50
22	REAR LID CHROME DECORATIVE TRIM new NEC	1	\$ 391.00	✓
23	REAR PARKING AID SENSOR - INNER / OUTER <i>1 piece missing</i>	2	\$ 531.00	265 ✓ 265.50
(24)	REAR TAIL LIGHT (LH/RH) <i>cracked.</i>	(2)	\$ 1,402.00	✓ ✓ <i>Res.</i>
25	REAR LICENCE PLATE LIGHT - LH / RH <i>new</i>	2	\$ 82.00	+
26	REAR CROSS PANEL TRIM <i>new</i>	1	\$ 290.00	+
27	REAR LID TRIM PANEL <i>new</i>	1	\$ 428.00	+
28	REAR NO PLATE <i>Dented</i>	S/N	\$ 60.00	✓
29	SUNDRIES ?		\$ 400.00	✓ 21.00
TOTAL SPARE PARTS		:	\$ 14,562.00	
TOTAL LABOUR CHARGES		:	\$ 6,752.00	
GRAND TOTAL		:	\$ 21,314.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME : Adria Lj
SURVEYED DATE : 04/11/22
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS : Not Authorized, 04 Days

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT

PREMIUM AUTOMOBILES

55 Ubi Road 1, Singapore 408699
 Tel : 6366 2323 Fax : 6841 1183
 Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg



*TP Con Pac.
Xiao Tony.*

Supplementary Estimate

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 / Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PA/TP/0958/2022/EQ 21-Dec-22 Kee Siang 1 of 1 SJT 8887 G AUDI A6 2.0T FSI 4F208H
Quantity	Description	Unit Price	Amount
Labours			
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHHER ASSY. S/N	\$ 360.00	360.00 360.00
2	TO DISMANTLE AND RENEW FRONT BUMPER, RE-ORGANIZE CRASH MANAGEMENT COMPONENTS, REINSTALL ALL PARTS REMOVED.	1,200.00	500 800.00
3	TO RESPRAY FRONT BUMPER	1,000.00	550 800.00
Parts			
1	FRONT BUMPER <i>Renew</i>	\$ 2,664.00	2,664.00
2	FRONT BUMPER COVER <i>Renew</i>	\$ 126.00	126.00
3	RADIATOR GRILLE LISENCE PLATE TRIM <i>Renew</i>	\$ 217.00	217.00
4	RADIATOR GRILLE <i>Renew</i>	\$ 905.00	905.00
5	"CAUTION SIGN" <i>Renew</i>	\$ 16.00	16.00 15.50
GRAND TOTAL		\$ 6,488.00	

For Premium Automobiles Pte Ltd



Authorized Signature

*Adrian Ling
21/12/22
SLG*

Add 3 Days. For the repairs to the front portion.

PREMIUM AUTOMOBILES

55 Ubi Road 1, Singapore 408699
 Tel : 6366 2323 Fax : 6841 1183
 Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg



Supplementary Estimate

GST Reg No. 19-9902271-W

LONPAC INSURANCE BHD 300 Beach Road #17-04/07, The Concourse Singapore 199555 Attn: Motor Claims Dept Tel: 6841 0055 / Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PA/TP/0958/2022/EQ 5-Jan-23 GLORY 1 of 1 SJT 8887 G AUDI A6 2.0T FSI 4F208H
Quantity	Description	Unit Price	Amount
Labours			
1	TO REMOVE AND RENEW RHS REAR EHXAUST SILENCER AND ALIGN TO POSITION. S/N	\$ 480.00	✓
Parts			
1	RHS REAR EXHAUST SILENCER. <i>Best</i>	\$ 1,396.00	✓
2	DUAL CLIP <i>New</i>	\$ 66.00	✓
GRAND TOTAL		\$ 1,942.00	

For Premium Automobiles Pte Ltd

Authorized Signature

Adrian King

 **PREMIUM AUTOMOBILES**

55 Ubi Road 1, Singapore 408699
 Tel : 6366 2323 Fax : 6841 1183
 Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg



Supplementary Estimate

GST Reg No. 19-9902271-W

LONPAC INSURANCE BHD 300 Beach Road #17-04/07, The Concourse Singapore 199555 Attn: Motor Claims Dept Tel: 6841 0055 / Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PA/TP/0958/2022/EQ 23-Dec-22 GLORY 1 of 1 SJT 8887 G AUDI A6 2.0T FSI 4F208H
Quantity	Description	Unit Price	Amount
Labours			
1	TO REPAIR SPARE WHEEL HOUSING.	\$ 400.00	✓ ✓
2	TO RESPRAY SPARE WHEEL HOUSING.	\$ 800.00	✓ ✓
Parts			
1	FRONT NUMBER PLATE <i>Dented.</i>	\$ 60.00	✓ ✓
GRAND TOTAL		\$ 1,260.00	

For Premium Automobiles Pte Ltd

 Authorised Signature

*Adrian G
 H.S.*