

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SMJ 57874

at Workshop m/s

speed workz

of

Insured:

SJP 9894R

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

\$80k.

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

5

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

LTA 37665

Date / Time

Action / Instruction

27/11/22 - 13k

high mileage.

7/11/22 4/5 & 5000 informed km

Veh No:

SMJ 57874

Yr Regn:

12/03/19

Type: (M) Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

CA

Make:

Honda Vezel Hybrid c.c 1496

Colour

white

A/C: Insured / Std / NI / NA

Sp. Reading

282290

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

R431308866

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / SRim / STD A/Rim or

Tyre Size:

F:

R:

215/60R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Kapsen

Front

6

Rear

6

R/Bal.

mm

R/Bal.

mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

28/10/22

D.O.I.

1/11/22

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐

Preli. Report

1)

Date/Time, File Return to?

☐

Final Report

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

) S + RS, SI

) Photos

) Others

)

TOTAL

Report Format :

Lump Sum / I.B.I: (\$)

Hsiao Tony

Not Authorized
Her
1/11/22

SPEEDWERKZ PRIVATE LIMITED

1 KAKI BUKIT AVE 6, #01-73, AUTOBAY, SINGAPORE 417883

Tel: 96195936 / info@speedwerkz.biz

1/5 \$5000
5 days.

VEHICLE NUMBER: SMJ5797U
 MAKE & MODEL: HONDA VEZEL
 DOA: 28/10/2022
 CLAIM TYPE: TP CLAIM

ESTIMATION QUOTE

PARTS	QTY	PRICE (\$)	REMARKS
Rear boot lid <i>Body ID</i>	1	\$ 1,995.20	✓
Rear boot lock <i>TM</i>	1	\$ 495.20	✓
Rear boot lock catch <i>11</i>	1	\$ 56.80	X
Rear boot rubber <i>TM</i>	1	\$ 291.00	✓
Rear boot adsorber <i>11</i>	2	\$ 247.00	X
Rear boot emblem <i>vezel</i>	1	\$ 85.60	✓
Rear boot inner board <i>de/cu</i>	1	\$ 852.60	✓
Rear boot centre emblem <i>11</i>	1	\$ 93.10	X
Rear boot inner pull pocket <i>11</i>	1	\$ 102.20	X
Rear boot hinge @99.50 <i>11</i>	2	\$ 199.00	X
Rear boot reflector @625.20 <i>n/s cu</i>	2	\$ 1,250.40	✓
Rear boot centre garnish <i>11</i>	1	\$ 697.50	X
Rear wind screen glass moulding <i>11</i>	1	\$ 366.70	✓
Rear number plate lamp @88.50 <i>11</i>	2	\$ 177.00	X
Rear end panel <i>Body ID</i>	1	\$ 952.40	✓
Rear end panel trim <i>TM</i>	1	\$ 451.20	✓
Rear fender @1462.20 <i>11</i>	2	\$ 2,924.40	X
Rear floor panel <i>11</i>	1	\$ 996.30	X
Rear floor panel top cover board <i>11</i>	1	\$ 365.20	X
Rear fender trim @825.20 <i>n/s trim</i>	2	\$ 1,650.40	✓
Rear fender wheel arch @298 <i>n/s trim</i>	2	\$ 596.00	✓
Rear bumper <i>11</i>	1	\$ 1,652.00	✓
Rear bumper side @562.30 <i>n/s de</i>	2	\$ 1,124.60	✓
Rear bumper reflector @62.10 <i>n/s de</i>	2	\$ 124.20	✓
Rear bumper side retainer @65.30 <i>11</i>	2	\$ 130.60	X
Rear taillamp @ 836.50 <i>n/s cu</i>	2	\$ 1,673.00	✓
Rear taillamp panel @285 <i>11</i>	2	\$ 570.00	X
Rear exhaust silencer <i>11</i>	1	\$ 996.30	X
Rear exhaust rubber @35 <i>11</i>	2	\$ 70.00	X
Rear exhaust heat shield <i>11</i>	1	\$ 267.70	X
Rear tool tray <i>TM</i>	1	\$ 295.10	✓
Rear lock antenna <i>11</i>	1	\$ 287.20	X
Rear buzzer <i>11</i>	1	\$ 97.10	X
rear chassis member top panel <i>11</i>	1	\$ 330.00	X
Rear luggage panel under cover <i>de/cu</i>	1	\$ 147.20	✓

\$ 22,610.20

953
 180.20
 162.30
 65.00
 242.30
 280.40
 110.00
 517.30
 122.60
 366.20
 199.10
 762.00
 180.00
 62.10
 482.20

Less 20% \$ 4,522.04
 Sub Total \$ 18,088.16

SPECIAL NETT ITEMS	QTY	PRICE (\$)	REMARKS
Rear end panel sealant <i>nm</i>	1	\$ 100.00	<i>50</i>
Rear glass sealant <i>nm</i>	1	\$ 100.00	<i>50</i>
Rear number plate <i>nm</i>	1	\$ 45.00	<i>X</i>
Rear boot insulator clips @\$5 <i>nm</i>	10	\$ 50.00	<i>X</i>
Rear end panel top garnish clips @\$5 <i>nm</i>	3	\$ 15.00	<i>X</i>
Rear tail lamp clips @\$5 <i>nm</i>	8	\$ 40.00	<i>X</i>
Rear fender wheel arch clips @\$5 <i>nm</i>	20	\$ 100.00	<i>X</i>
Rear reversing camera <i>nm</i>	1	\$ 650.00	<i>X</i>
Rear reverse sensor <i>shorted</i>	1 <i>set</i>	\$ 450.00	<i>200</i>
Sub Total		\$ 1,550.00	

LABOUR CHARGE	QTY	PRICE (\$)	REMARKS
To check wiring		\$ 250.00	<i>20</i>
Apply anti rust chemical		\$ 250.00	<i>60</i>
Apply rear boot & rear luggage sound proof		\$ 350.00	<i>nm X</i>
Remove and refix rear trimming garnish etc		\$ 250.00	<i>80</i>
Remove and refix rear boot garnish mechanism item		\$ 150.00	<i>60</i>
Remove and refic rear windscreen glass		\$ 150.00	<i>120</i>
Remove and replace reverse sensor and wiring		\$ 150.00	<i>50</i>
Labour charge straighten rear chassis, cut welding, renew parts		\$ 1,800.00	<i>620</i>
To spray painting and etc		\$ 1,600.00	<i>900</i>
Sub Total		\$ 4,950.00	

Grand Total \$ 23,488.16

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

P- 5126.80
20%
4101.44
300
1890
6281.44
202
5033