



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

HSBC LIFE (SINGAPORE) PTE LTD
10 MARINA BOULEVARD
#48-01 MARINA BAY FINANCIAL CENTRE TOWER
2SINGAPORE 018983
ATTN:KITTY

Ref: CC4/ASM22010805/Kpa3q2

Date: 05/06/2023

Code: HSB

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	XE 2776X	Veh. Inspected	YP 5610B
Policy No.	GA561441	Coverage (\$)	0.00
Claim No.	S2M04DIW	Excess (\$)	0.00
Assign From		Assign Date	31/10/2022

2. Vehicle Particulars & Condition

Make & Model	ISUZU NQR75UL5A (M)	c.c	5193
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	JAAN1R75LH7100103	Colour	WHITE
Odometer	221631 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	215/75 R17.50	AUFINE	4 mm
L/H Front Tyre	215/75 R17.50	AUFINE	9 mm
R/H Rear Tyre	215/75 R17.50 (D)	AUFINE	6/6 mm
L/H Rear Tyre	215/75 R17.50 (D)	AUFINE	6/6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	25/10/2022	Inspection Date	03/11/2022
Survey held at	SYSTEMATIC AIRCONDITIONING PTE LTD 29 SENOKO WAY SINGAPORE 758059		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **4 Working Days**