

SMTA398S.

Toyota Estima. 2362 CC

TP111
Veron

ACR507007735

Front Bumper	Deformed	751.10.	✓
Front Bumper clips.	new	30(SN)	✓
Front Bumper Side Holder LH.	Deformed	38.50.	✓
Front Bumper Fog Lamp LH	new	285.10	+
Front Bumper Reinforcement	new	381.50	+
Front Bumper Sponge.	new	163.80	+
Headlamp LH.	Cracked	2245.10.	—
Front LH Fender	Deformed	685.90	✓
Front LH Fender Inner Shield.	Deformed	243.20.	—
Front LH Fender Inner Shield clips.	new	30(SN)	—
Front LH Fender Protector	Deformed	78.50	✓
Front LH Fender Protector clips.	new	10(SN)	✓
Front LH Fender Inner Enclosure.	Deformed	48.20.	—
Air Resonator Tank.	Deformed	185.20.	✓

SMT4398S.

Front LH Door	Reps	1481.40 +
Front LH Door Outer Protector	Reps	689.40 +
Front LH Door Outer Protector Clips.	^{nl} n	30(SN) +
Rear LH Door	Reps	1884.20 +
Rear LH Door Outer Protector	Reps	704.10 +
Rear LH Door Outer Protector Clips.	^{nl} n	30(SN) +
Rear LH Fender Protector	Reps	85.90 +
Rear LH Fender Protector Clips.	nl	10(SN) +
Rear Bumper	Reps	780.40 +
Rear Bumper Clips.	^{nl} n	30(SN) +
Rear Bumper Side Holder LH.	^{nl} n	48.90 +
Front LH Wheel Rim.	lt	880(SN) 500(SN)
Front LH Tyre.	nl	380(SN) +
Front LH Shock Absorber.	Best	680(SN) 400(SN)
Front LH Lower Arm	Best	398.60

SMT43985.

Front LH Knuckle Arm.	2nd	581.60	/
Front LH Wheel Hub c/w Bearing.	2nd	321.40	/
Rear LH Wheel Rim.	cut	880(SN)	SN(SN)
Rear LH Tyre	new	380(SN)	+
Rear LH Shock Absorber.	new	680(SN)	+
Rear LH Wheel Hub c/w Bearing.	2nd	581.40	/
Rear Axle Beam.	new	2017.60	+

Panel Beating	1600	200
Spray Painting.	1800.	1400
Wiring.	100	30
To apply tuff. Coat.	150	60
To transfer front door fittings.	150	+
To transfer rear door fittings.	150	+

SMT4398S.

To dismantle front undercarriage.

~~357~~ 220

To dismantle rear undercarriage.

~~480~~ 60

To perform wheel alignment.

~~150~~ 80

hist: 6159.10

len 25%: 4619.32

S.N: 1470

Labours: 2550

total: 8639.32

L/s: 6.9K ✓

06 Days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: