

TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 41 7921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200714616M
 GST Registration No. : 200714616M

*TP Budget Direct.
 Hui Rong.*

CHEN SIYING
 BLK 702 BEDOK RESERVOIR RD #04-3554
 SINGAPORE 470702

TAX INVOICE

Repair Code : CLM15705
 Date in : 27/10/2022
 Vehicle Num. : SLJ3972E
 Model : HONDA MOBILIO SV 1.5 CVT
 Chassis/Eng# : MRHDD4870GP000294/L15Z12873548

Contact : 80323431

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
FRONT BUMPER <i>Deformed</i>	1	482.50	✓ 482.50
FRONT BUMPER GRILLE <i>Not nec</i>	1	108.35	✗ 108.35
FRONT BUMPER LH FOGLAMP <i>crushed</i>	1	344.05	✓ 344.05
FRONT BUMPER LH FOGLAMP COVER <i>cut</i>	1	129.15	✓ 129.15
FRONT BUMPER SIDE RETAINER L/R <i>LH Damaged.</i>	2	16.15	16.15 ✗ 32.30
FRONT BUMPER TOW COVER <i>Not nec</i>	1	20.50	✗ 20.50
FRONT GRILLE <i>Not nec</i>	1	200.70	✗ 200.70
FRONT GRILLE 'H' LOGO <i>Not nec</i>	1	28.40	✗ 28.40
FRONT GRILLE CHROME MOULDING <i>Not nec</i>	1	237.00	✗ 237.00
FRONT LH FENDER <i>Buckled</i>	1	232.85	✗ 232.85
FRONT LH FENDER INNER FRAME PANEL <i>Repair</i>	1	117.40	✗ 117.40
FRONT LH FENDER INNER SHIELD <i>tom</i>	1	99.50	✓ 99.50
FRONT LH HEADLAMP <i>crushed.</i>	1	1088.70	✓ 1,088.70
FRONT LH KNUCKLE ARM <i>Damaged.</i>	1	254.60	✓ 254.60
FRONT LH KNUCKLE ARM BEARING <i>Damaged</i>	1	52.90	✓ 52.90
FRONT LH LOWER ARM <i>Best.</i>	1	211.70	✓ 211.70
FRONT LH SHOCK ABSORBER <i>Not nec</i>	1	253.40	✗ 253.40
FRONT LH SHOCK ABSORBER TOP MOUNTING <i>Not nec</i>	1	36.70	✗ 36.70

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200714616M
 GST Registration No. : 200714616M

CHEN SIYING
 BLK 702 BEDOK RESERVOIR RD #04-3554
 SINGAPORE 470702

Contact : 80323431

TAX INVOICE

Repair Code : CLM15705

Date in : 27/10/2022

Vehicle Num. : SLJ3972E

Model : HONDA MOBILIO SV 1.5 CVT

Chassis/Eng# : MRHDD4870GP000294/L15Z12873548

Part Description	Qty	Unit Price	Total Price	Remarks
FRONT LH SPORT RIM	1	877.40	877.40	450/SW
FRONT LH WHEEL HUB	1	172.40	172.40	✓
Subtotal before discount			4,980.50	
Percentage discount 20%			996.10	
Sub-total 1			3,984.40	
FRONT BUMPER CLIPS - SET	1	50.00	50.00	30 ✓
FRONT GRILLE CLIPS - SET	1	50.00	50.00	X
FRONT LH FENDER INNER SHIELD CLIPS - SET	1	50.00	50.00	30 ✓
FRONT LH TYRE	1	300.00	300.00	+ ✓
Subtotal before discount			450.00	
Percentage discount 0%			0.00	
Sub-total 2			450.00	
Parts-total			4,434.40	

LABOUR

To remove, reinstall electrical wiring harness, check lighting. (to FR)	30	60.00
To remove, reinstall front suspension undercarriage parts. (to FR)	180	250.00
To road test driving, check and resetting wheel alignments system.	80	100.00
To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.	400	1,000.00
To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.	500	1,000.00

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

CHEN SIYING
BLK 702 BEDOK RESERVOIR RD #04-3554
SINGAPORE 470702

Contact : 80323431

TAX INVOICE

Repair Code : CLM15705
Date in : 27/10/2022
Vehicle Num. : SLJ3972E
Model : HONDA MOBILIO SV 1.5 CVT
Chassis/Eng# : MRHDD4870GP000294/L15Z12873548

To apply anti-rust chemical on repaired and replaced panel.

1230

	<u>40</u> 50.00
Labour Total	2,460.00
Parts & Labour Total	6,894.40

*** This is a computer-generated document which requires no signature.***

page 3

total: 3991.32

L/S: 3.2k.

06 Days.

6 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

3.2k.