

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

INDIA INTERNATIONAL INSURANCE PL INV No. AC2206894

64 CECIL STREET INV Date 07/11/2022

#05-02 IOB BUILDING Reference CS3/GRB22010810/Svy3e2 SINGAPORE 049711

Code GRB

PROFESSIONAL SERVICE FEE

Vehicle No. GBE 4050D

Insured Veh. SLS 5273D

Claim No. MFL2022D0006564

Policy No. D21MFL0000447_01

Accident Date 26/10/2022

Inspection Date 31/10/2022

| Description | Total |
|---|--------|
| Pre-Repair Survey as per NIMA Protocol 2016 Admt 1 (Photo taking + Transport) | 120.00 |
| - First Inspection 31.10.2022 03.00pm | |
| - Dismantle Inspection 31.10.2022 03.00pm | |
| - After Repair Inspection 03.11.2022 02.30pm | |
| Merimen Fee | 11.00 |
| Subtotal | 131.00 |
| GST (7%) | 9.17 |
| Grand Total | 140.17 |

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

LKK Auto Consultants Pte Ltd

KHM