

Systematic Airconditioning Pte Ltd

29 Senoko Way Singapore 758059

Tel: 64847188 Fax: 64841334

GST No. 199800703G

Contact: Sha (64847188)

Email: shah@systematicaircon.com

*Not Authorized
Repairing B4 repair
6 days***Estimation**To: **SOMPO INSURANCE SINGAPORE PTE LTD**

DATE:	27-Oct-22
D.O.A:	24-Oct-22
Your ref:	GBF3748B

REPAIR FOR GBC5658E (WINSOME GREEN)

No.	Description	Qty	Unit Price	Amount
1	Supply and replace one (1) no. Rear METAL BUMPER	1	\$ 680.00	\$ 680.00
2	Supply and replace two (2) set BRACKET for metal bumper	2	\$ 255.00	\$ 510.00
	Supply and replace two (2) pc rear RUBBER STOPPER (BUMPER)	2	\$ 195.00	\$ 390.00
3	Supply and replace two (2) no CHASSIS RUNNER	2	\$ 380.00	\$ 760.00
4	Supply four (4) no. aluminium capping	4	\$ 480.00	\$ 1,920.00
5	Supply four (4) no. PVC corner capping	4	\$ 180.00	\$ 720.00
6	Supply one (1) no. UV treated GRP Board for the exterior of the rear box.	1	\$ 1,000.00	\$ 1,000.00
7	Supply fifteen (15) no. sealant tube	15	\$ 25.00	\$ 375.00
8	Logo Writing on rear ref box (Exactly Same as Old Box)		(Bill)	\$ 800.00
9	To supply labour to install and FIBER GLASS repair for aluminium capping, corner capping and GPR board.			\$ 300.00
10	To supply labour and material to PAINT BLACK the rear metal bumper, bracket and chassis bracket			\$ 750.00
11	To adjust and levelling refrigerated box			\$ 800.00
12	To supply labour and material to install and TIG WELDING rear metal bumper with bracket and chassis bracket			\$ 1,500.00

Sub Total \$ 10,505.00

7% gst \$ 735.35

Bal amount due \$ 11,240.35

Loss of Used 10 days x \$350.00

LKK Auto Con. the notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party supply is on a "Without Prejudice" basis
- No illegal modification(s) to be made
- Supply of any part(s) to be resurveyed and is subject to final approval in Insurance Company

I acknowledge the Repairer
signature: