



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SME 273Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	BOOT LID	BENT	2,350.00	2,293.00
1	BOOT LOCK	TO REPAIR SEE LABOUR	500.00	-
1	BOOT CATCH	TO REPAIR SEE LABOUR	215.00	-
1	REAR BUMPER	BUCKLED	2,150.00	1,874.00
1	REAR BUMPER TOW COVER	DENTED	190.00	79.00
1	REAR BUMPER LH BRACKET	CRACKED	160.00	160.00
1	REAR BUMPER RH BRACKET	CRACKED	160.00	160.00
1	REAR BUMPER CENTER BRACKET	CRACKED	365.00	258.00
1	REAR LOWER SPOILER	CRACKED	830.00	674.00
1	REAR LOWER SPOILER RH EXHAUST	DENTED	925.00	410.00
1	REAR LOWER SPOILER LH EXHAUST	DENTED	925.00	410.00
2	REAR REVERSE SENSOR	SHORTED (1PC ONLY)	720.00	234.00
1	REAR REINFORCEMENT	BENT	830.00	830.00
1	REAR END PANEL OUTER	BENT	1,650.00	1,604.00
1	REAR END PANEL INNER	TO REPAIR SEE LABOUR	820.00	-
1	REAR END PANEL TOP GARNISH (ADDITIONAL)	MTG CRACKED	280.00	280.00
1	REAR RH BUMPER REFLECTOR (ADDITIONAL)	CRACKED	88.00	88.00
1	REAR BUMPER UNDER BRACKET (ADDITIONAL)	CRACKED	160.00	160.00
	LESS 10% DISCOUNT		-1,331.80	-951.40
			11,986.20	8,562.60
	<b><u>LABOUR</u></b>			
	LABOUR CHARGES TO TRANSFER REAR BOOT LID WIRE HARNESS.		300.00	60.00
	TO PANEL BEAT ON THE AFFECTED AREA. INCLUSIVE OF THE REPAIR OF BOOT LOCK, BOOT CATCH & REAR END PANEL INNER.		2,000.00	700.00
	TO SPRAY PAINT ON THE AFFECTED AREA.		2,000.00	900.00



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	TO REMOVE THE REAR TRIM BOARD TO FACILITATE REPLACE THE REAR END PANEL.		300.00	60.00
			4,600.00	1,720.00
GRAND TOTAL			16,586.20	10,282.60
RECOMMENDED COST OF REPAIRS				10,282.60

Report Ref No. CS/AGI22010812/Kwy3m4

KONG SENG CHEONG

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.