



泛舟修理汽車私人有限公司
PUAN CHEW MOTOR WORK PTE LTD

BLK K, PANDAN LOOP INDUSTRIAL ESTATE #01-12 SINGAPORE 128230

TEL: 6773 0073 FAX: 6773 0928

GST REGN NO: 19-8700614-G

Date: 31.10.2022

Sompo Insurance Singapore Pte Ltd
50 Raffles Place #03-03
Singapore Land Tower
Singapore 048623

Attn: Motor Claims Dept

Dear Sir / Mdm,

OD CLAIM

INSURED'S NAME : MR, LARRY GOH CHAU CHZE
VEH. REG. NO : SLR9516H
MODEL : HONDA VEZEL
ACCIDENT DATE : 27.10.2022

Below are the estimate for SLR9516H

1	1 front bumper	✓ OR	\$	170.00	✓
2	1 front bumper o/s retainer	✓ OR	\$	10.00	✓
3	1 front bumper lower lid	✓ CUT	\$	120.00	✓
4	1 front o/s headlamp	✓ OR	\$	910.00	✓
5	1 front o/s fog lamp	✓ X NN	\$	115.00	
6	1 front o/s fog lamp grille	✓ CUT	\$	15.00	✓
7	1 front o/s fender	✓ OR	\$	180.00	✓
8	1 front o/s fender inner shield	✓ X NN	\$	75.00	
9	10 front o/s fender inner shield clips @ \$3	✓ X NN	\$	30.00	
10	1 front o/s wheel arch garnish	✓ CUT	\$	45.00	✓
			\$	1,670.00	
			Cost + 10%:	\$ 167.00	1450 +10%
			Total:	\$ 1,837.00	1595

Labour Charges

11	To remove and replace damaged parts, knock out, cut weld body panel parts where necessary, straighten and reshape, reposition and realign replacement parts to the original position.	\$	680.00	500
12	Spray painting of accident sections.	\$	680.00	600
			Grand Total:	\$ 3,197.00
				1100

PRICES QUOTED EXCLUDE GST CHARGES

LKK Auto Comp. Agents to be notified
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed

• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:

We Specialised in Servicing and Repairing all kinds of Motor Vehicles, Panel Beating, Spray Painting

專修各種汽車 噴漆打馬呷 燒焊汽車服務。

= 2695

L/S - 2156
= 2150