





INSURER: **Allianz Insurance Singapore Pte. Ltd. (HQ)**

PARTICULARS OF CLAIM			
Claim Type:	OD (Own Damage)	Ref. No:	
Policy No:	0	Date of Loss:	17/10/2022
Vehicle Reg. No.:	SMA2598U	Driveable?	
Driver Age/Info:		Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	OW KIM LENG, VINCENT		
Make/Model:	TOYOTA HARRIER, 2.0 (A)	Vehicle Reg. Date:	31/05/2018
Vehicle Colour:	Silver	Chassis No:	JTEZB3GH70J002123
Engine No:	8ARZ122484		
Odometer:	0 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	8		
Present Location:	MOVA AUTOMOTIVE PTE LTD (BUKIT MERAH)		

	Amount
<b>COST OF CLAIMS</b>	
Parts	1,694.00
Miscellaneous Items	0.00
Labour	850.00
Paintwork Labour	0.00
Towing	0.00
	<b>Gross Total (S\$) 2,544.00</b>
	<b>+ GST 7.00% (S\$) 178.08</b>
	<b>Nett Amount (S\$) 2,722.08</b>

This claim is handled by: KEONG

Generated using Merimen e-Claims Internet Estimation & Adjusting System

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

# REPAIR DETAILS

## Reference

Part Source: MRM-SG

Version: 1.0 (Last Synchronised: 31 Oct 2022)

Parts: M1-SUV

TOYOTA HARRIER 2.0 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's

(Price-denominated Standard List)

Print Code: Mova Automotive Pte Ltd/SMA2598U/31/10/2022 13:33

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*

## Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*REAR BUMPER <i>BR</i>	0.00	0.00	*750.00 F
2	1		*REAR BUMPER LOWER GARNISH <i>X NM</i>	0.00	0.00	*330.00 F
3	1		*REAR BUMPER SENSOR <i>X NM ?</i>	0.00	0.00	*220.00 F
4	1		*REAR BUMPER SIDE BRACKET RH <i>?</i>	0.00	0.00	*40.00 F
5	1		*REAR BUMPER RETAINER RH <i>?</i>	0.00	0.00	*65.00 F
6	10		*REAR BUMPER CLIPS <i>/ nec</i>	0.00	0.00	*25.00 F
7	1		*REAR BUMPER SIDE SHIELD RH <i>?</i>	0.00	0.00	*110.00 F
Sub Total (S\$)						1,540.00
+ Margin on L,N Items 10.00% (S\$)						154.00
Total Parts (S\$)						1,694.00

F Franchise part.

Mova Automotive Pte Ltd/SMA2598U/31/10/2022 13:33. Not valid without Reference section.  
Generated using Merimen e-Claims IEAS