



Main Office : No. 22, Jalan Kilang, Singapore 159410
Tel: 6476 3333 Fax: 6271 5691

Service Centre : Block 103B, Bukit Merah Lane 3,
#01-04/05/06/115, Singapore 159722
Tel: (65) 6476 3333 (8 Lines) Fax: (65) 6270 8314
www.mova.com.sg
GST Reg. No: M2-0068894-2

Mova Spray Centre
2K Oven Spray Painting System

Power-M Automotive Pte Ltd
Specialise in Car Air-con Services,
Car Audio & Hi-Fi System.

Hilton Car Rental Centre
Hilton Auto Trading
Dealing in New/Used Cars, Hire Purchase & Insurance.



INSURER: Allianz Insurance Singapore Pte. Ltd. (HQ)

PARTICULARS OF CLAIM			
Claim Type:	OD (Own Damage)	Ref. No:	
Policy No:	0	Date of Loss:	17/10/2022
Vehicle Reg. No.:	SMA2598U	Driveable?	
Driver Age/Info:		Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	OW KIM LENG, VINCENT		
Make/Model:	TOYOTA HARRIER, 2.0 (A)	Vehicle Reg. Date:	31/05/2018
Vehicle Colour:	Silver	Chassis No:	JTEZB3GH70J002123
Engine No:	8ARZ122484		
Odometer:	0 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	8		
Present Location:	MOVA AUTOMOTIVE PTE LTD (BUKIT MERAH)		

COST OF CLAIMS	Amount
Parts	1,694.00
Miscellaneous Items	0.00
Labour	850.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (\$\$)	2,544.00
+ GST 7.00% (\$\$)	178.08
Nett Amount (\$\$)	2,722.08

This claim is handled by: KEONG

Generated using Motimen e-Claims Internet Estimation & Adjusting System

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

REPAIR DETAILS

Reference

Part Source: MRM-SG

Parts: M1-SUV

Labour: Repairer's

Print Code: Mova Automotive Pte Ltd/SMA2598U/31/10/2022 13:33

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *

Version: 1.0 (Last Synchronised: 31 Oct 2022)
 TOYOTA HARRIER 2.0 (A) (Catalogue:Merimen Singapore 1.0)
 (Price-denominated Standard List)

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*REAR BUMPER <i>BR</i>	0.00	0.00	*750.00 F ✓
2	1		*REAR BUMPER LOWER GARNISH <i>X MM</i>	0.00	0.00	*330.00 F
3	1		*REAR BUMPER SENSOR <i>X MM ?</i>	0.00	0.00	*220.00 F
4	1		*REAR BUMPER SIDE BRACKET RH <i>?</i>	0.00	0.00	*40.00 F
5	1		*REAR BUMPER RETAINER RH <i>?</i>	0.00	0.00	*25.00 F
6	10		*REAR BUMPER CLIPS <i>X PC ?</i>	0.00	0.00	*110.00 F
7	1		*REAR BUMPER SIDE SHIELD RH <i>?</i>			
Sub Total (S\$)						1,540.00
+ Margin on L.N Items 10.00% (S\$)						154.00
Total Parts (S\$)						1,694.00

Extraneous part.

Mova Automotive Pte Ltd/SMA2598U/31/10/2022 13:33. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<u>Miscellaneous Items</u>			
1	1	REAR FENDER AIR VENT RH - TO CHECK	
2	1	REAR FENDER RH - TO REPAIR	
Sub Total (\$)			0.00

✓ RH
x R

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	TO REPAIR REAR FENDER RH, REMOVE & REFIX DAMAGED PARTS, STRAIGHTEN & REALIGN AFFECTED AREA	New	350.00
2	TO SPRAY REAR FENDER RH, REAR BUMPER & AFFECTED AREAS	New	500.00
Gross Labour Cost (\$)			850.00

900 ✓
200 ✓

Mova Automotive Pte Ltd/SMA2598U/31/10/2022 13:33. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Steve (LKK)
9/11/22, 1.30pm
OD- Not Authorise
Excess. ?
P/P
Resing Before Spray
3 days