

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG22010821/RNCE2**Date:** 04/05/2023**REFERENCE**

Insured/Claimant: PREMIUM AUTOMOBILES PTE LTD
Date of Loss: 15/09/2022

Policy No: 0999993555
Nature of Claim: OD Claim No: 8793472115SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SNF9592B**
Make & Model: AUDI A4, 2.0 TFSI S-TRONIC (A) Engine No: DEM032068
Reg. Date: 30/06/2022 (Man. Year: 2021) Chassis No: WAUZZZF48MA063310
Colour: White Odometer: 5329 km
Engine Capacity: 1984 cc
Market Value/New Car Price: S\$193,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/50 R17 Rear Tyre Size: 225/50 R17
Front Left Side: Hankook 6 mm Rear Left Side: Hankook 6 mm
Front Right Side: Hankook 6 mm Rear Right Side: Hankook 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	26,416.00	9,873.12	16,542.88	62.62
Miscellaneous Items	0.00	0.00	0.00	
Labour	20,852.00	7,202.00	13,650.00	65.46
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	47,268.00	17,075.12	30,192.88	63.88
- Excess (S\$)	4,800.00	4,800.00	0.00	0.00
(S\$)	42,468.00	12,275.12	30,192.88	71.10
+ GST 8.00/8.00% (S\$)	3,397.44	982.01	2,415.43	71.10
Nett Amount (S\$)	45,865.44	13,257.13	32,608.31	71.10

INSPECTION

Date of Assignment: 01/11/2022
Date Inspected: 31/10/2022 Inspected At: 24 Benoi Sector Singapore 629857
Estimated Period of Repair: 8.0 days Repairer: Premium Automobiles Pte Ltd

Adjuster: MOHD RASUL**Manager:** HUEY YON

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Repair	2,377.00 FS	*- FS
2	1		*FRONT BUMPER AIR GUIDE - LH	Not Necessary	51.00 FS	*- FS
3	2		*FRONT BUMPER SECURING STRIP - LH / RH	Not Necessary	79.00 FS	*- FS
4	1		*FRONT BUMPER GUIDE SECTION - LH	Not Necessary	41.00 FS	*- FS
5	1		*FRONT FENDER - LH	Bent	1,227.00 FS	*981.60 FS
6	1		*FRONT FENDER CLOSING ELEMENT - LH	Not Necessary	81.00 FS	*- FS
7	1		*FRONT FENDER BRACKET - LH FRONT	Not Necessary	41.00 FS	*- FS
8	1		*FRONT FENDER BRACE - LH	Not Necessary	132.00 FS	*- FS
9	1		*FRONT FENDER DEFORMATION ELEMENT BRACKET - LH	Not Necessary	55.00 FS	*- FS
10	1		*FRONT FENDER BRACKET - LH REAR	Not Necessary	36.00 FS	*- FS
11	1		*FRONT FENDER CLOSING ELEMENT - LH	Deformed	37.00 FS	*29.12 FS
12	1		*FRONT FENDER BRACKET - LH UPPER	Not Necessary	37.00 FS	*- FS
13	1		*FRONT WHEEL HOUSING LINER - LH	Cracked	256.00 FS	*204.80 FS
14	1		*FRONT WHEEL SPOILER - LH	Not Necessary	82.00 FS	*- FS
15	1		*FRONT WHEEL SPOILER END PLATE - LH	Not Necessary	39.00 FS	*- FS
16	1		*FRONT FENDER LEDGE COVER - LH LONG	Not Necessary	35.00 FS	*- FS
17	1		*HEADLIGHT COVER - LH	Not Necessary	49.00 FS	*- FS
18	1		*FRONT PILLAR A/B FRAME MEMBER - LH	Not Necessary	2,874.00 FS	*- FS
19	1		*FRONT WHEEL SPOILER SILL TRIM STRIP	Not Necessary	133.00 FS	*- FS
20	1		*AIRBAG / CHILDSEAT STICKER WITH PICTOGRAM	Necessary	27.00 FS	*21.28 FS
21	1		*FRONT DOOR - LH	Torn	3,431.00 FS	*2,744.80 FS
22	1		*FRONT OUTER DOOR SEAL - LH	Necessary	229.00 FS	*182.80 FS
23	1		*BONDING AGENT	Not Necessary	51.00 FS	*- FS
24	1		*CLEANING SOLUTION	Not Necessary	74.00 FS	*- FS
25	1		*APPLICATOR	Not Necessary	9.00 FS	*- FS
26	1		*FRONT DOOR CATCH - LH	Not Necessary	116.00 FS	*- FS
27	1		*FRONT DOOR HINGE - LH UPPER	Not Necessary	49.00 FS	*- FS
28	1		*FRONT DOOR HINGE HALVES - LH UPPER	Not Necessary	53.00 FS	*- FS
29	1		*FRONT DOOR HINGE - LH LOWER	Bent	53.00 FS	*42.32 FS
30	1		*FRONT DOOR HINGE HALVES - LH LOWER	Bent	51.00 FS	*40.16 FS
31	1		*FRONT INNER DOOR SEAL - LH	Not Necessary	229.00 FS	*- FS
32	1		*FRONT EXTERIOR WING MIRROR MOUNTING - LH	Scratched	1,201.00 FS	*960.80 FS
33	1		*FRONT WINDOW REGULATOR	Not Necessary	305.00 FS	*- FS
34	1		*FRONT WINDOW REGULATOR MOTOR	Not Necessary	346.00 FS	*- FS
35	1		*FRONT DOOR CONTROL UNIT	Not Necessary	672.00 FS	*- FS
36	1		*FRONT WINDOW GUIDE - LH	Not Necessary	501.00 FS	*- FS
37	1		*FRONT WINDOW GUIDE TRIM STRIP	Not Necessary	287.00 FS	*- FS
38	1		*FRONT PILLAR B TRIM - LH	Not Necessary	256.00 FS	*- FS
39	1		*FRONT WINDOW SLOT SEAL TRIM STRIP - LH	Not Necessary	344.00 FS	*- FS
40	1		*FRONT DOOR TRIM - LH	Not Necessary	2,372.00 FS	*- FS
41	1		*REAR DOOR - LH	Bent	3,431.00 FS	*2,744.80 FS
42	1		*REAR OUTER DOOR SEAL - LH	Necessary	229.00 FS	*182.80 FS
43	1		*BONDING AGENT	Not Necessary	51.00 FS	*- FS
44	1		*CLEANING SOLUTION	Not Necessary	74.00 FS	*- FS
45	1		*APPLICATOR	Not Necessary	9.00 FS	*- FS
46	1		*REAR DOOR SEALING STRIP	Not Necessary	19.00 FS	*- FS
47	1		*REAR DOOR CATCH - LH	Not Necessary	134.00 FS	*- FS
48	2		*REAR DOOR HINGE HALVES - LH LOWER	Bent	106.00 FS	*83.36 FS
49	1		*REAR PILLAR B TRIM - LH	Not Necessary	167.00 FS	*- FS
50	1		*REAR WINDOW GUIDE TRIM STRIP	Not Necessary	265.00 FS	*- FS
51	1		*REAR WINDOW SLOT SEAL TRIM STRIP - LH	Not Necessary	410.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
52	1		*FRONT ALUMINIUM RIM	Cut	1,292.00 FS	*1,033.60 FS
53	1		*FRONT ALUMINIUM RIM RUBBER VALVE	Necessary	4.00 FS	*2.96 FS
54	1		*ACRYLIC SEALANT	Not Necessary	180.00 FS	*- FS
55	1		*CAVITY WAX	Not Necessary	140.00 FS	*- FS
56	1		*METAL FILLER POWDER	Not Necessary	280.00 FS	*- FS
57	1		*STONE CHIP	Not Necessary	180.00 FS	*- FS
58	1		*SUNDRIES	Necessary	400.00 FS	*36.32 FS
59	1		*DOOR WIRING SET (Supplementary)	Cracked	727.00 FS	*581.60 FS
					Total Parts (S\$)	26,416.00 9,873.12

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	480.00	480.00
2	TO REMOVE AND TRANSFER LHS FRONT DOOR AND LHS REAR DOORS MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES	New	700.00	700.00
3	TO REMOVE AND REINSTALL LHS FRONT SEAT ASSY, ABCD PILLAR TRIMS, SILL TRIMS, FLOOR CARPETS, ELECTRONIC COMPONENTS AND FUSE TRAYS. DISENGAGE LHS SEAT BELT AND HEAD AIRBAG	New	1,800.00	0.00
4	TO REMOVE AND REINSTALL CENTER CONSOLE AND DASHBOARD ASSY FOR A-PILLAR RENEWAL. INSPECT FOR DAMAGES	New	3,200.00	0.00
5	TO DISMANTLE AND RENEW FRONT BUMPER, LHS FRONT FENDER, LHS FRONT DOOR AND LHS REAR DOOR. TO CUT OUT AND WELD LHS A-PILLAR, LHS SILL PANEL AND LHS B-PILLAR RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	7,700.00	2,500.00
6	TO RESPRAY FRONT BUMPER, LHS FRONT FENDER, LHS FRONT DOOR, DOOR HANDLE, LHS WING MIRROR COVER, DOOR HINGES, LHS REAR DOOR, LHS A-PILLAR, LHS SILL PANEL AND LHS B-PILLAR	New	6,500.00	3,050.00
7	TO RENEW LHS FRONT RIM AND CARRY OUT WHEEL ALIGNMENT	New	280.00	280.00
8	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (S\$)			20,852.00	7,202.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >