

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0935/2022/EQ
DATE : 28-Oct-22
WIP : 48048

VEHICLE IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 31/10/2022

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

*Hi Rasul
8 days exclude 1 S
Johnny Boo 21 Mc*

OWNER'S NAME : M/S PREMIUM AUTOMOBILES PTE LTD
ADDRESS : 55 UBI ROAD 1
SINGAPORE 408699

TELEPHONE : HP +65 66900293
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 0999993555-01/1220004598
VEHICLE NO : **SNF 9592 B**
MODEL CODE : AUDI A4 2.0 TFSI S-TRONIC
MODEL YEAR : 30/6/2022
ENGINE NO : DEM 032068
CHASSIS NO : WAUZZZF48MA063310
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 15-Sep-22
PLACE OF ACCIDENT : MUHAMMAD ALI LANE

unday - ok
r 23

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SNF 9592 B

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$	480.00	\$ 480.00
2	TO REMOVE AND TRANSFER LHS FRONT DOOR AND LHS REAR DOOR'S MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES.	S/N \$	700.00	\$ 700.00
3	TO REMOVE AND REINSTALL LHS FRONT SEAT ASSY, ABCD PILLAR TRIMS, SILL TRIMS, FLOOR CARPETS, ELECTRONIC COMPONENTS AND FUSE TRAYS. DISENGAGE LHS SEAT BELT AND HEAD AIRBAG.	S/N \$	1,800.00	
4	TO REMOVE AND REINSTALL CENTER CONSOLE AND DASHBOARD ASSY FOR A-PILLAR RENEWAL. INSPECT FOR DAMAGES.	S/N \$	3,200.00	
5	TO DISMANTLE AND RENEW FRONT BUMPER, LHS FRONT FENDER, LHS FRONT DOOR AND LHS REAR DOOR. TO CUT OUT AND WELD LHS A-PILLAR, LHS SILL PANEL AND LHS B-PILLAR. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	7,700.00	\$ 2,500.00
TOTAL LABOUR CHARGES		:	\$ 13,880.00	\$ 3,680.00



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SNF 9592 B

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
		<i>c/f</i>		\$ 3,680.00
6	TO RESPRAY FRONT BUMPER, LHS FRONT FENDER, LHS FRONT DOOR, DOOR HANDLE, LHS WING MIRROR COVER, DOOR HINGES, LHS REAR DOOR, LHS A-PILLAR, LHS SILL PANEL AND LHS B-PILLAR.	\$	6,500.00	\$ 3,050.00
7	TO RENEW LHS FRONT RIM AND CARRY OUT WHEEL ALIGNMENT.	S/N \$	280.00	\$ 280.00
8	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$	192.00	\$ 192.00
TOTAL LABOUR CHARGES		:	\$ 20,852.00	\$ 7,202.00

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SNF 9592 B

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
1	FRONT BUMPER	1	\$	2,377.00	
2	FRONT BUMPER AIR GUIDE - LH	1	\$	51.00	
3	FRONT BUMPER SECURING STRIP - LH / RH	2	\$	79.00	
4	FRONT BUMPER GUIDE SECTION - LH	1	\$	41.00	
5	FRONT FENDER - LH	1	\$	1,227.00	\$ 981.60
6	FRONT FENDER CLOSING ELEMENT - LH	1	\$	81.00	
7	FRONT FENDER BRACKET - LH FRONT	1	\$	41.00	
8	FRONT FENDER BRACE - LH	1	\$	132.00	
9	FRONT FENDER DEFORMATION ELEMENT BRACKET - LH	1	\$	55.00	
10	FRONT FENDER BRACKET - LH REAR	1	\$	36.00	
11	FRONT FENDER CLOSING ELEMENT - LH	1	\$	37.00	\$ 29.12
12	FRONT FENDER BRACKET - LH UPPER	1	\$	37.00	
13	FRONT WHEEL HOUSING LINER - LH	1	\$	256.00	\$ 204.80
14	FRONT WHEEL SPOILER - LH	1	\$	82.00	
15	FRONT WHEEL SPOILER END PLATE - LH	1	\$	39.00	
16	FRONT FENDER LEDGE COVER - LH LONG	1	\$	35.00	
17	HEADLIGHT COVER - LH	1	\$	49.00	
18	FRONT PILLAR A/B FRAME MEMBER - LH	1	\$	2,874.00	
19	FRONT WHEEL SPOILER SILL TRIM STRIP	1	\$	133.00	
20	AIRBAG / CHILD'S SEAT STICKER WITH PICTOGRAM	1	\$	27.00	\$ 21.28
SUB TOTAL SPARE PARTS		:	\$	7,689.00	\$ 1,236.80

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SNF 9592 B

				DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY		S/NETT	REMARKS
		<i>c/f</i>			<i>\$ 1,236.80</i>
21	FRONT DOOR - LH	1	\$	3,431.00	<i>\$ 2,744.80</i>
22	FRONT OUTER DOOR SEAL - LH	1	\$	229.00	<i>\$ 182.80</i>
23	BONDING AGENT	1	\$	51.00	
24	CLEANING SOLUTION	1	\$	74.00	
25	APPLICATOR	1	\$	9.00	
26	FRONT DOOR CATCH - LH	1	\$	116.00	
27	FRONT DOOR HINGE - LH UPPER	1	\$	49.00	
28	FRONT DOOR HINGE HALVES - LH UPPER	1	\$	53.00	
29	FRONT DOOR HINGE - LH LOWER	1	\$	53.00	<i>\$ 42.32</i>
30	FRONT DOOR HINGE HALVES - LH LOWER	1	\$	51.00	<i>\$ 40.16</i>
31	FRONT INNER DOOR SEAL - LH	1	\$	229.00	
32	FRONT EXTERIOR WING MIRROR MOUNTING - LH	1	\$	1,201.00	<i>\$ 960.80</i>
33	FRONT WINDOW REGULATOR	1	\$	305.00	
34	FRONT WINDOW REGULATOR MOTOR	1	\$	346.00	
35	FRONT DOOR CONTROL UNIT	1	\$	672.00	
36	FRONT WINDOW GUIDE - LH	1	\$	501.00	
37	FRONT WINDOW GUIDE TRIM STRIP	1	\$	287.00	
38	FRONT PILLAR B TRIM - LH	1	\$	256.00	
39	FRONT WINDOW SLOT SEAL TRIM STRIP - LH	1	\$	344.00	
40	FRONT DOOR TRIM - LH	1	\$	2,372.00	
SUB TOTAL SPARE PARTS		:	\$	10,629.00	<i>\$ 5,207.68</i>

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APROVED
 SPARE PARTS ARE SPECIAL NETT.

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SNF 9592 B

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
		<i>c/f</i>		\$	5,207.68
21	REAR DOOR - LH	1	\$ 3,431.00	\$	2,744.80
22	REAR OUTER DOOR SEAL - LH	1	\$ 229.00	\$	182.80
23	BONDING AGENT	1	\$ 51.00		
24	CLEANING SOLUTION	1	\$ 74.00		
25	APPLICATOR	1	\$ 9.00		
26	REAR DOOR SEALING STRIP	1	\$ 19.00		
27	REAR DOOR CATCH - LH	1	\$ 134.00		
28	REAR DOOR HINGE HALVES - LH LOWER	2	\$ 106.00	\$	83.36
29	REAR PILLAR B TRIM - LH	1	\$ 167.00		
30	REAR WINDOW GUIDE TRIM STRIP	1	\$ 265.00		
31	REAR WINDOW SLOT SEAL TRIM STRIP - LH	1	\$ 410.00		
32	REAR ALUMINIUM RIM	1	\$ 1,292.00	\$	1,033.60
33	REAR ALUMINIUM RIM RUBBER VALVE	1	\$ 4.00	\$	2.96
34	ACRYLIC SEALANT	S/N	\$ 180.00		
35	CAVITY WAX	S/N	\$ 140.00		
36	METAL FILLER POWDER	S/N	\$ 280.00		
37	STONE CHIP	S/N	\$ 180.00		
38	SUPPLEMENTARY		\$ 727.00	\$	581.60
39	SUNDRIES		\$ 400.00	\$	36.32
TOTAL SPARE PARTS			\$ 26,416.00	\$	9,873.12
TOTAL LABOUR CHARGES			\$ 20,852.00	\$	7,202.00
GRAND TOTAL			\$ 47,268.00	\$	17,075.12

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.
 BL-14/02/23



55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183
Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg



Supplementary Estimate-1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 / Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PA/OD/0935/2022/EQ 18-Jan-23 CHANG 1 of 1 SNF 9592 B AUDI A4 2.0 TFSI
Quantity	Description	Unit Price	Amount
<u>Parts</u>			
1	DOOR WIRING SET	\$ 727.00	\$ 581.60
	GRAND TOTAL	\$ 727.00	\$ 581.60

For Premium Automobiles Pte Ltd

Authorised Signature



PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

PLEASE NOTE :

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT