

Name & Address:

Motor Claims Department

INDIA INTERNATIONAL INSURANCE P/L

64 CECIL STREET

#04-#05 IOB BUILDING

SINGAPORE 049711

Email/Fax No:

Contact No:

Vehicle No:

SDV96K

Date:

28-Oct-22

Brand & Model:

Porsche Panamera PDK

Franchise:

PORSCHE

Chassis/VIN No:

WP0ZZZ97ZNL100287

Contact Person (Eurokars):

DEREK

Type of Claim:

THIRD PARTY

YEAR MODEL:

11/03/2022

WIP#:

37495

Contact No (Eurokars):

6331 0684

PARTS / MATERIAL CHARGES

MARK = Survey Marking [Key "A" if item is approved]

NO	DESCRIPTION	PART NO.	QTY	MARK	REVISED	PRICE
1	REAR BUMPER / DD	P971-807-983-Y-	1		-	\$ 4,687.60
2	TOWING COVER ? X nn	P971-807-442--G2X	1		-	\$ 103.40
3	REAR BUMPER LOWER SPOILER / CUT	P971-807-514-BY-	1		-	\$ 2,097.20
4	EXHAUST TRIM LH X / MC	P971-807-951--OK1 (phn)	1		-	\$ 316.60
5	EXHAUST TRIM RH X / MC	P971-807-952--OK1 (phn)	1		-	\$ 316.60
6	LICENSE PLATE BRACKET X nn	P971-807-287-K-OK1	1		-	\$ 181.80
7	BUMPER SOUND ABSORBER LH / MC	P971-825-477--	1		-	\$ 339.80
8	BUMPER SOUND ABSORBER RH / MC	P971-825-478--	1		-	\$ 339.80
9	BRACKET FOR PEDAL SENSOR ? X nn	P971-807-773-B-	1		-	\$ 112.70
10	SENSOR ? X nn	P5Q0-919-275-B-G2X	2		-	\$ 966.40
11	SENSOR GASKET / MC	P5Q0-919-133--9B9	4		-	\$ 13.60
12	REAR BUMPER CENTER BRACKET ? X nn	P971-807-863-A-	1		-	\$ 251.80
13	SUPPORT BRACKET LH ? X nn	P971-807-331-C-	1		-	\$ 1,051.10
14	SUPPORT BRACKET RH ? X nn	P971-807-332-C-	1		-	\$ 1,051.10
15	TAIL LIGHT BRACKET LH ? X nn	P971-807-125--	1		-	\$ 157.70
16	TAIL LIGHT BRACKET RH ? X nn	P971-807-126-A-	1		-	\$ 157.70
17	ANTENNA SENSOR X - MC	P971-035-510-E- (phn)	1		-	\$ 244.10
18	REAR BUMPER REINFORCEMENT ? X nn	PPAE-803-184-A-	1		-	\$ 2,116.60
19	WIRE HARNESS FOR PEDAL SENSOR X - MC	P971-962-253-C- (phn)	1		-	\$ 396.00
20						\$ -

Sub-Total (Parts Price) \$ - \$ 14,901.60

LABOUR / SERVICES CHARGES

NO	DESCRIPTION	REVISED	PRICE
1	TO REMOVE /REPLACE REAR BUMPER, REINFORCEMENT & ALL DAMAGED BODY PARTS. TO REPAIR ALL AREAS AFFECTED BY THE ACCIDENT.	1560 /	\$ 3,120.00
2	TO RESPRAY REAR BUMPER	1300 /	\$ 1,500.00
3	TO SUPPLY REAR LICENCE PLATE WITH CASING	nett	\$ X 150.00

4	TO TRANSFER THE REVERSE SENSORS.	150 /	\$ 300.00
5	TO APPLY SPECIAL CERAMIC COATING. (PRICE TO BE ADVISE)	11/1/22	nett 8 X
6	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.	150 /	\$ 250.00
7	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.	nett	\$ 600.00
8	SUNDRIES.	nett	\$ 20 / 50.00

Survey Date & Time:	Repair Days:	Excess:
---------------------	--------------	---------

Surveyor Remarks:

Store (LKK)
1/1/22, 2.00pm
go 4 dgs
in h
PIP, M PL by

Remarks:

- This is only an estimate based on visual inspection. Should there be more damages found during repair, it will be informed and quoted additionally.
- A fee of \$400 (excl. GST) will be chargeable for damage assessment and preparation of this estimate, if you choose not to proceed with repair.

Sub-Total (Labour Price)	\$ -	\$ 5,970.00
	REVISED	PRICE
Parts Price	\$ -	\$ 14,901.60
Labour Price	\$ -	\$ 5,970.00
Total (Initial Estimate)	\$ -	\$ 20,871.60
Supp 1	\$ -	\$ -
Supp 2	\$ -	\$ -
Supp 3	\$ -	\$ -
Total (Before Excess)	\$ -	\$ 20,871.60
Less Excess	\$ -	\$ -
TOTAL (After Excess)	\$ -	\$ 20,871.60
GST 7%	\$ -	\$ 1,461.01
GRAND TOTAL	\$ -	\$ 22,332.61

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to market price
- Third party survey is on a "no cure, no fee" basis
- No illegal modification of car
- Supplementary items not included in estimate is subject to final approval of the repairer

Acknowledged by Repairer
Signature: _____
Date: _____