

Name &amp; Address:

**Motor Claims Department**

INDIA INTERNATIONAL INSURANCE P/L

64 CECIL STREET

#04-#05 IOB BUILDING

SINGAPORE 049711

Vehicle No:

**SDV96K**

Brand &amp; Model:

Porsche Panamera PDK

Chassis/VIN No:

WP0ZZZ97ZNL100287

WIP#:

37495

Date:

29-Nov-22

Franchise:

PORSCHE

Contact Person (Eurokars):

DEREK

Contact No (Eurokars):

6331 0684

Email/Fax No:

Contact No:

Type of Claim:

THIRD PARTY

YEAR MODEL:

11/03/2022

**PARTS / MATERIAL CHARGES**

MARK = Survey Marking [Key "A" if item is approved]

| NO | DESCRIPTION                   | PART NO.            | QTY | MARK | REVISED     | PRICE       |
|----|-------------------------------|---------------------|-----|------|-------------|-------------|
| 1  | REAR BUMPER                   | P971-807-983- Y-    | 1   | A    | \$ 4,687.60 | \$ 4,687.60 |
| 2  | TOWING COVER                  | P971-807-442- -G2X  | 1   |      | -           | \$ 103.40   |
| 3  | REAR BUMPER LOWER SPOILER     | P971-807-514-BY-    | 1   | A    | \$ 2,097.20 | \$ 2,097.20 |
| 4  | EXHAUST TRIM LH               | P971-807-951- -OK1  | 1   | A    | \$ 316.60   | \$ 316.60   |
| 5  | EXHAUST TRIM RH               | P971-807-952- -OK1  | 1   | A    | \$ 316.60   | \$ 316.60   |
| 6  | LICENSE PLATE BRACKET         | P971-807-287-K -OK1 | 1   |      | -           | \$ 181.80   |
| 7  | BUMPER SOUND ABSORBER LH      | P971-825-477- -     | 1   | A    | \$ 339.80   | \$ 339.80   |
| 8  | BUMPER SOUND ABSORBER RH      | P971-825-478- -     | 1   | A    | \$ 339.80   | \$ 339.80   |
| 9  | BRACKET FOR PEDAL SENSOR      | P971-807-773-B -    | 1   |      | -           | \$ 112.70   |
| 10 | SENSOR                        | P5Q0-919-275-B -G2X | 2   |      | -           | \$ 966.40   |
| 11 | SENSOR GASKET                 | P5Q0-919-133- -9B9  | 4   | A    | \$ 13.60    | \$ 13.60    |
| 12 | REAR BUMPER CENTER BRACKET    | P971-807-863-A -    | 1   |      | -           | \$ 251.80   |
| 13 | SUPPORT BRACKET LH            | P971-807-331-C -    | 1   |      | -           | \$ 1,051.10 |
| 14 | SUPPORT BRACKET RH            | P971-807-332-C -    | 1   |      | -           | \$ 1,051.10 |
| 15 | TAIL LIGHT BRACKET LH         | P971-807-125- -     | 1   |      | -           | \$ 157.70   |
| 16 | TAIL LIGHT BRACKET RH         | P971-807-126-A -    | 1   |      | -           | \$ 157.70   |
| 17 | ANTENNA SENSOR                | P971-035-510-E -    | 1   | A    | \$ 244.10   | \$ 244.10   |
| 18 | REAR BUMPER REINFORCEMENT     | PPAE-803-184-A -    | 1   |      | -           | \$ 2,116.60 |
| 19 | WIRE HARNESS FOR PEDAL SENSOR | P971-962-253-C -    | 1   | A    | \$ 396.00   | \$ 396.00   |
| 20 |                               |                     |     |      |             | \$ -        |

Sub-Total (Parts Price) \$ 8,751.30 \$ 14,901.60

**LABOUR / SERVICES CHARGES**

| NO | DESCRIPTION                                                                                                           | REVISED     | PRICE       |
|----|-----------------------------------------------------------------------------------------------------------------------|-------------|-------------|
| 1  | TO REMOVE /REPLACE REAR BUMPER, REINFORCEMENT & ALL DAMAGED BODY PARTS. TO REPAIR ALL AREAS AFFECTED BY THE ACCIDENT. | \$ 1,560.00 | \$ 3,120.00 |
| 2  | TO RESPRAY REAR BUMPER                                                                                                | \$ 1,300.00 | \$ 1,500.00 |
| 3  | TO SUPPLY REAR LICENCE PLATE WITH CASING                                                                              | -           | \$ 150.00   |
| 4  | TO TRANSFER THE REVERSE SENSORS.                                                                                      | \$ 150.00   | \$ 300.00   |
| 5  | TO APPLY SPECIAL CERAMIC COATING. (PRICE TO BE ADVISE)                                                                | TBA         |             |

|   |                                                    |           |           |
|---|----------------------------------------------------|-----------|-----------|
| 6 | TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING. | \$ 150.00 | \$ 250.00 |
| 7 | TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.    | \$ 600.00 | \$ 600.00 |
| 8 | SUNDRIES.                                          | \$ 20.00  | \$ 50.00  |

|                                                        |                            |         |
|--------------------------------------------------------|----------------------------|---------|
| Survey Date & Time: <b>01/11/2022</b><br><b>2.00PM</b> | Repair Days: <b>4 DAYS</b> | Excess: |
|--------------------------------------------------------|----------------------------|---------|

Surveyor Remarks:

Remarks:

- This is only an estimate based on visual inspection. Should there be more damages found during repair, it will be informed and quoted additionally.
- A fee of \$400 (excl. GST) will be chargeable for damage assessment and preparation of this estimate, if you choose not to proceed with repair.

Sub-Total (Labour Price) \$ 3,780.00 \$ 5,970.00

|                          | <u>REVISED</u>      | <u>PRICE</u>        |
|--------------------------|---------------------|---------------------|
| Parts Price              | \$ 8,751.30         | \$ 14,901.60        |
| Labour Price             | \$ 3,780.00         | \$ 5,970.00         |
| Total (Initial Estimate) | \$ 12,531.30        | \$ 20,871.60        |
| Supp 1                   | \$ -                | \$ -                |
| Supp 2                   | \$ -                | \$ -                |
| Supp 3                   | \$ -                | \$ -                |
| Total (Before Excess)    | \$ 12,531.30        | \$ 20,871.60        |
| Less Excess              | \$ -                | \$ -                |
| TOTAL (After Excess)     | \$ 12,531.30        | \$ 20,871.60        |
| GST 7%                   | \$ 877.19           | \$ 1,461.01         |
| <b>GRAND TOTAL</b>       | <b>\$ 13,408.49</b> | <b>\$ 22,332.61</b> |