

ASS. REC BY: Taujan

REF:

NS/ INC 22010825/Tvc

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: **FBN 3018H**

Policy No. _____

Claims No. **MT/1195472-001**

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS WP

Date: _____ Person Contacted: Lim TS Vehicle: IN / OUT

Veh No: SH 8328K Yr Regn: 2017, July

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Toyota Prius C.C. 1798

Colour: Blue A/C: Insured / Std / NI / NA

Sp. Reading: 716932 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: 5T DK B3F4103560784

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195/65R15

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Washu

Front: _____ Rear: _____

R/Bal. 6 mm R/Bal. 8 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. 29/10/2022 D.O.I. 31/10/22

Survey held at Comfort Lodge

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear N/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
11/11/22	Lump Sum \$1600 (Red 1508.82, 48%)

Date/Time, File Pass to? ☐ : Prel. Report

1) ☐ : Final Report

Date/Time, File Return to?

2) 11/11/22-typist

Days Of Repair: 2

Resurvey No. of Trip: 1

Survey Fee:

Transportation:

S. + RS. \$

Photos

Others

TOTAL

Add Fee: ☐ : Site Insp (\$

☐ : Interview (\$

☐ : Tech. rvs (\$

☐ : Weekend (\$

Rep. Form: TP

Lump Sum / L.B. / TP \$1600

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

LKK

DATE: 31.10.22

INSURANCE: INCOME - 45

MODEL: Toyota Prius

MVA: LIM T S

VEHICLE NO.: SH 8328K

PART NO.	DESCRIPTION	QTY	UNIT PRICE	AMOUNT
	Rear Bumper	1		\$503.04 <i>de</i>
	Rear Bumper Reinforcement	1		\$378.32 ?
	Rear Bumper Lower Cover	1		\$654.96 <i>de</i>
	Rear Bumper Clips	10	\$2.20	\$22.00 <i>net</i>
	Rear Bumper Tow Cover	1		\$82.70 X
	TailLamp Upper LH	1		\$557.90 X
	TailLamp Lower LH	1		\$570.00 <i>ant</i>
	SUB TOTAL			\$2,768.92
	LESS 25%			\$692.23
	DISCOUNTED TOTAL			\$2,076.69
	Reverse Sensor	1		\$135.70 X
	LESS 10%			\$13.57
	S/NETT TOTAL			\$122.13
	Rear Bumper Adv.Sticker	1		\$50.00 <i>NETT ant</i>
	PARTS TOTAL			\$2,248.82
	Labour Charge			
	Panel Beating			\$400.00 <i>350</i>
	Spray Painting Charge			\$300.00 <i>250</i>
	Check Lightings			\$40.00 <i>30</i>
	Remove/Refix Reverse Sensor			\$120.00 <i>30</i>
	TOTAL LABOUR			\$860.00
	ESTIMATE TOTAL			\$3,108.82

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Taufik 97495744
WP 31/10/22 @ 330pm
2 days
4/5 Resurvey after repair
taufik@lkkauto.com

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insured

Acknowledged by Repairer

Signature:

Date:

Toyota Prius

COMFORTDELGRO ENGINEERING

A member of COMFORTDELGRO

ComfortDelGro Engineering Pte Ltd

205 Braddell Road Singapore 579701

Mainline + 65 6383 6280 Facsimile + 65 6280 9755

Workshops

59 Loyang Drive Singapore 508969

383 Sin Ming Drive Singapore 575717

45 Pandan Road Singapore 609286

320 Ubi Road Singapore 408940

24 Serangoon Loop Singapore 758156

7 Sungei Kadut Way Singapore 728791

501 Yishun Industrial Park A Singapore 768732

Date/Time: 31.10.2022 08:03

Page : 1

eam: ARC Repair TP(CLSO)1

JOB CARD Sales Order: 5131881

JC NO: 305534765

STOMER

MS COMFORT TRANSPORTATION PTE LTD

STOMER NO. 7010045

RESS 383 SIN MING DRIVE

Singapore SINGAPORE 575717

(R) 65508755

(P) (O)

OUNT CARD NO.

REGN NO.:

SH 8328K

MILEAGE

MAKE:

TOYOTA

FUEL

E.....1/2.....F

MODEL

PRIUS HYBRID(G4)29.10.2022 10:35

DATE/TIME IN

YR OF MANU.

26.07.2017

TARGET DATE

CHASSIS CODE

JTDKB3FU103560784

COMPLETION DATE/TIME:

ccident Date: 29.10.2022

ATURE: 3P 29.10.2022

LKK

/NO

00010


LABOR CODE

PB

JOB DESCRIPTION

DESCRIPTION

LUMPSUM REPAIR-SH 8328K TP



ICKED & PASSED OUT BY: •

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

edgement Slip

Exit Pass

Vehicle No.: SH 8328K

LIMITS

Vehicle No.:

SH 8328K

Service Advisor

Signature/Date

Name of Service Advisor

Date

urned to Service Reception upon collection

To be kept by Security Guard