

ASS. REC BY: Toupin

REF:

INC

ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: \_\_\_\_\_

at Workshop m/s \_\_\_\_\_

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

|     |     |
|-----|-----|
|     |     |
| N/S | O/S |
|     |     |

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Report: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: \_\_\_\_\_ days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: Lim TS Vehicle: IN / OUT

Veh No: SH8328K Yr Regn: 2017, July

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Prius C.C. 1798

Colour: Blue A/C: Insured / Std / NI / NA

Sp. Reading: 716932 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: 5TDKBSF4103560784

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195/65R15

R: \_\_\_\_\_

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Washin

Front: 6 mm R/Bal. 8 mm

R/Bal. 6 mm L/Bal. 6 mm

D.O.A. \_\_\_\_\_ D.O.I. 31/10/22

Survey held at Comfort Lodge

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear N/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Date/Time, File Pass to?

1) \_\_\_\_\_  
Date/Time, File Return to?

2) \_\_\_\_\_

Rep. Formet: \_\_\_\_\_

Lump Sum / L.B.R. / P

Days Of Repair: \_\_\_\_\_

Resurvey No. of Trip: \_\_\_\_\_

Add Fee: ☐ : Site Insp (\$ \_\_\_\_\_)

☐ : Interview (\$ \_\_\_\_\_)

☐ : Tech. rvs (\$ \_\_\_\_\_)

☐ : Weekend (\$ \_\_\_\_\_)

Survey Fee: \_\_\_\_\_

Transportation: \_\_\_\_\_

S. + RS. SI. \_\_\_\_\_

Photos \_\_\_\_\_

Others \_\_\_\_\_

TOTAL

# COMFORTDELGRO ENGINEERING PTE LTD

## REPAIR ESTIMATE

LKK

DATE: 31.10.22

INSURANCE: INCOME - 45

MODEL: Toyota Prius

MVA: LIM T S

VEHICLE NO.: SH 8328K

| PART NO. | DESCRIPTION                 | QTY | UNIT PRICE | AMOUNT                         |
|----------|-----------------------------|-----|------------|--------------------------------|
|          | Rear Bumper                 | 1   |            | \$503.04 <i>de</i>             |
|          | Rear Bumper Reinforcement   | 1   |            | \$378.32 ?                     |
|          | Rear Bumper Lower Cover     | 1   |            | \$654.96 <i>de</i>             |
|          | Rear Bumper Clips           | 10  | \$2.20     | \$22.00 <i>net</i>             |
|          | Rear Bumper Tow Cover       | 1   |            | \$82.70 X                      |
|          | TailLamp Upper LH           | 1   |            | \$557.90 X                     |
|          | TailLamp Lower LH           | 1   |            | \$570.00 <i>ant</i>            |
|          | <b>SUB TOTAL</b>            |     |            | \$2,768.92                     |
|          | <b>LESS 25%</b>             |     |            | \$692.23                       |
|          | <b>DISCOUNTED TOTAL</b>     |     |            | <b>\$2,076.69</b>              |
|          | Reverse Sensor              | 1   |            | \$135.70 X                     |
|          | <b>LESS 10%</b>             |     |            | \$13.57                        |
|          | <b>S/NETT TOTAL</b>         |     |            | <b>\$122.13</b>                |
|          | Rear Bumper Adv.Sticker     | 1   |            | <b>\$50.00</b> <i>NETT ant</i> |
|          | <b>PARTS TOTAL</b>          |     |            | <b>\$2,248.82</b>              |
|          | <u><b>Labour Charge</b></u> |     |            |                                |
|          | Panel Beating               |     |            | \$400.00 <i>350</i>            |
|          | Spray Painting Charge       |     |            | \$300.00 <i>250</i>            |
|          | Check Lightings             |     |            | \$40.00 <i>30</i>              |
|          | Remove/Refix Reverse Sensor |     |            | \$120.00 <i>30</i>             |
|          | <b>TOTAL LABOUR</b>         |     |            | <b>\$860.00</b>                |
|          | <b>ESTIMATE TOTAL</b>       |     |            | <b>\$3,108.82</b>              |

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Taufik 97495744  
 WP 31/10/22 @ 330pm  
 2 days  
 4/5 Resurvey after repair  
 Taufik@lkkauto.com

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Toyota Prius

# COMFORTDELGRO ENGINEERING

A member of COMFORTDELGRO

## ComfortDelGro Engineering Pte Ltd

205 Braddell Road Singapore 579701

Mainline + 65 6383 6280 Facsimile + 65 6280 9755

### Workshops

59 Loyang Drive Singapore 508969

383 Sin Ming Drive Singapore 575717

45 Pandan Road Singapore 609286

320 Ubi Road Singapore 408940

24 Serangoon Loop Singapore 758156

7 Sungei Kadut Way Singapore 728791

501 Yishun Industrial Park A Singapore 768732

Date/Time: 31.10.2022 08:03

Page : 1

eam: ARC Repair TP(CLSO)1

**JOB CARD** Sales Order: 5131881

JC NO: 305534765

STOMER

MS COMFORT TRANSPORTATION PTE LTD

STOMER NO. 7010045

RESS 383 SIN MING DRIVE

Singapore SINGAPORE 575717

(R) 65508755

(P) (O)

OUNT CARD NO.

REGN NO.:

SH 8328K

MILEAGE

MAKE:

TOYOTA

FUEL

E.....1/2.....F

MODEL

PRIUS HYBRID(G4)29.10.2022 10:35

DATE/TIME IN

YR OF MANU.

26.07.2017

TARGET DATE

CHASSIS CODE

JTDKB3FU103560784

COMPLETION DATE/TIME:

ccident Date: 29.10.2022

ATURE: 3P 29.10.2022

LKK

/NO

00010


LABOR CODE

PB

### JOB DESCRIPTION

DESCRIPTION

LUMPSUM REPAIR-SH 8328K TP



ICKED & PASSED OUT BY: •

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

edgement Slip

Exit Pass

No.: SH 8328K

LIMITS

Vehicle No.:

SH 8328K

Service Advisor

Signature/Date

Name of Service Advisor

Date

urned to Service Reception upon collection

To be kept by Security Guard