

ASS. REC BY: TP

REF:

NSI / IN 22010827/Tvc

ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / IS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: \_\_\_\_\_

at Workshop m/s \_\_\_\_\_

of \_\_\_\_\_

Insured: **FBL 1822B**

Policy No. \_\_\_\_\_

Claims No. **MT/1195012-002**

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its

repair at the time of inspection.

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Report: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: \_\_\_\_\_ days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

\_\_\_\_\_

Date: \_\_\_\_\_ Person Contacted: Lim TS

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

Veh No: SHB 4280B Yr Regn: 2020 Feb

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Prius C.C. 1798

Colour: Blue A/C: Insured / Std / NI / NA

Spl. Reading: 204604 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: STDUB3F4003091170

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: NI / S/Rim / STD A/Rim or

Tyre Size: F: 195/65R15

R: \_\_\_\_\_

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Westlake

\_\_\_\_\_

Front \_\_\_\_\_ Rear \_\_\_\_\_

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. 29/10/22 D.O.I. 31/10/22

Survey held at Gulfport Bayang

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear N/S

The U/C / Chassis frame / Body Structure affected due to collision.

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

Date/Time, File Pass 10?

☐ : Preli. Report

1) \_\_\_\_\_

☐ : Final Report

Date/Time, File Return to?

2) 8/11/22-typist

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

Days Of Repair: 2

Resurvey No. of Trip: 1

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

Survey Fee:

Transportation:

S + RS. \$

Photos

Others

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

☐

: \_\_\_\_\_

☐

: \_\_\_\_\_

☐

: \_\_\_\_\_

Report Format: TP

Lump Sum / L.B. / \$ \$1250

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

# COMFORTDELGRO ENGINEERING PTE LTD

## REPAIR ESTIMATE

SAS-KIV

DATE: 31.10.22

MODEL: Toyota Prius G4A

VEHICLE NO.: SHB4280S

INSURANCE: INCOME → FBL1822B

MVA: LIM T S

| PART NO. | DESCRIPTION                 | QTY | UNIT PRICE | AMOUNT              |
|----------|-----------------------------|-----|------------|---------------------|
|          | Rear Bumper                 | 1   |            | \$551.89 <i>th</i>  |
|          | Rear Bumper Lower Cover     | 1   |            | \$654.96 <i>x</i>   |
|          | Rear Bumper Clips           | 10  | \$2.20     | \$22.00 <i>net</i>  |
|          | Rear Bumper Side Bracket LH | 1   |            | \$112.70 <i>?</i>   |
|          | TailLamp Upper LH           | 1   |            | \$557.90 <i>x</i>   |
|          | TailLamp Lower LH           | 1   |            | \$570.00 <i>own</i> |
|          | <b>SUB TOTAL</b>            |     |            | \$2,469.45          |
|          | <b>LESS 25%</b>             |     |            | \$617.36            |
|          | <b>DISCOUNTED TOTAL</b>     |     |            | <b>\$1,852.09</b>   |
|          |                             |     |            |                     |
|          | Rear Bumper Mat             | 1   | <i>net</i> | <b>\$50.00</b>      |
|          |                             |     |            | <b>NETT</b>         |
|          | <b>PARTS TOTAL</b>          |     |            | <b>\$1,902.09</b>   |
|          | <b>Labour Charge</b>        |     |            |                     |
|          | Panel Beating               | 350 |            | \$400.00            |
|          | Spray Painting Charge       | 250 |            | \$300.00            |
|          | Check Lightings             | 30  |            | \$40.00             |
|          | Remove/Refix Reverse Sensor | 30  |            | \$120.00            |
|          | <b>TOTAL LABOUR</b>         |     |            | <b>\$860.00</b>     |
|          |                             |     |            |                     |
|          | <b>ESTIMATE TOTAL</b>       |     |            | <b>\$2,762.09</b>   |

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Taufik 97495749  
 'WP' 31/10/22 330pm  
 c/s Resurvey after repair  
 ~2 days  
 Taufik & Lkh auto wu

**KK Auto Consultants** hereby notify  
 the Repairer of the following:  
 • To resurvey before/after spray painting  
 • To display damaged part(s) during resurvey  
 • Parts prices are subject to market fluctuation  
 • Third party survey is on a non-binding basis  
 • No illegal modification is allowed  
 • Supplementary items are subject to final approval by the insurance company

Acknowledged by:  
 Signature:  
 Date:

# COMFORTDELGRO ENGINEERING

number of COMFORTDELGRO

## ComfortDelGro Engineering Pte Ltd

205 Braddell Road Singapore 579701

Mainline + 65 6383 6280 Facsimile + 65 6280 9755

### Workshops

59 Loyang Drive Singapore 508969

388 Sin Ming Drive Singapore 575717

45 Pandan Road Singapore 609286

320 Ubi Road 3 Singapore 408649

24 Senoko Loop Singapore 758156

7 Sungei Kadut Way Singapore 728791

501 Yishun Industrial Park A Singapore 768732

Date/Time: 31.10.2022 10:06

Page : 1

m: ARC Repair TP(CLSO)1

**JOB CARD** Sales Order: 5131981

JC NO305534874

MER

COMFORT TRANSPORTATION PTE LTD

7010045

MER NO.

SS 383 SIN MING DRIVE

Singapore SINGAPORE 575717

R) 65508755

(O)

P)

JNT CARD NO.

REGN NO:

SHB4280B

MILEAGE

MAKE:

TOYOTA

FUEL

E.....1/2.....F

MODEL

PRIUS HYBRID(G4A31.10.2022 08:10

DATE/TIME IN

YR OF MANU

28.02.2020

TARGET DATE

CHASSIS CODE

JTDKB3FU003091140

COMPLETION DATE/TIME:

### JOB DESCRIPTION

Ident Date: 29.10.2022

DURE: 3P 29.10.2022

IO

0010


LABOR CODE

PB

### DESCRIPTION

LUMPSUM REPAIR-SHB4280B-TP

FRONT



REAR

ID & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

gement Slip

Exit Pass

Vehicle No.:

SHB4280B

SHB4280B

LIMITS

Service Advisor

Signature/Date

Name of Service Advisor

Date

ed to Service Reception upon collection

To be kept by Security Guard