

TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

TAN HUI CHUN
BLK 32 ANCHORVALE LANE #08-23
SINGAPORE 544590

Contact : 98294684, 96829580

TAX INVOICE

TP Budget Direct
Xiao Chan.

Repair Code : CLM15709

Date in : 28/10/2022

Vehicle Num. : SLA8216U

Model : MAZDA BIANTE 5-DOOR WAGON 2.0L SP.6EAT

Chassis/Eng# : JM6CC1071G0109182/PE30860716

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
REAR BUMPER <i>Dehd</i>	1	1173.00	✓ 1,173.00
REAR BUMPER CENTER MOULDING <i>could</i>	1	135.00	✓ 135.00
REAR BUMPER SIDE MOULDING L/R <i>me</i>	2	82.00	✓ 164.00
REAR BUMPER SIDE RETAINER L/R <i>me</i>	2	32.00	✓ 64.00
REAR END PANEL <i>Dehd</i>	1	303.00	✓ 303.00
REAR END PANEL ANTENNA SENSOR <i>could</i>	1	260.00	✓ 260.00
REAR END PANEL INNER TOP GARNISH <i>could</i>	1	118.00	✓ 118.00
REAR EXHAUST PIPE ASSY <i>Reis</i>	1	1109.00	+ 1,109.00
REAR EXHAUST PIPE REPAIR KIT <i>Reis</i>	1	45.00	+ 45.00
REAR EXHAUST PIPE RUBBER MOUNTING <i>Reis</i>	2	30.00	+ 60.00
REAR LH FENDER INNER TRIM BOARD <i>could</i>	1	632.00	✓ 632.00
REAR LH TAILLAMP <i>could</i>	1	1117.00	✓ 1,117.00
REAR LH TAILLAMP SIDE GARNISH <i>me</i>	1	88.00	+ 88.00
REAR NUMBER PLATE LAMP L/R <i>me</i>	2	47.20	+ 94.40
REAR TAILGATE <i>Dehd</i>	1	1699.00	✓ 1,699.00
REAR TAILGATE 'SKYACTIV' EMBLEM <i>me</i>	1	48.00	✓ 48.00
REAR TAILGATE INNER PULL HANDLE <i>me</i>	1	26.00	+ 26.00
REAR TAILGATE INNER RUBBER GUIDE STOPPER L/R <i>me</i>	2	10.80	+ 21.60

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

TAN HUI CHUN
BLK 32 ANCHORVALE LANE #08-23
SINGAPORE 544590

Contact : 98294684, 96829580

TAX INVOICE

Repair Code : CLM15709

Date in : 28/10/2022

Vehicle Num. : SLA8216U

Model : MAZDA BIANTE 5-DOOR WAGON 2.0L SP.6EAT

Chassis/Eng# : JM6CC1071G0109182/PE30860716

REAR TAILGATE INNER TRIM BOARD	1	426.00	✓	426.00
REAR TAILGATE LOCK STRIKER	1	54.00	+	54.00
REAR TAILGATE MECHANISM LOCK	1	264.00	✓	264.00
REAR TAILGATE OUTER CHROME HANDLE	1	555.00	✓	555.00
REAR TAILGATE OUTER HANDLE	1	107.20	+	107.20
REAR TAILGATE REFLECTOR LAMP	1	2018.00	✓	2,018.00
REAR TAILGATE WEATHER STRIP	1	218.00	✓	218.00

Subtotal before discount

10,799.20

Percentage discount 20%

2,159.84

Sub-total 1

8,639.36

REAR BUMPER CLIPS - SET	1	50.00	30	50.00
REAR BUMPER REVERSE SENSOR - SET	1	250.00	20	250.00
REAR END PANEL INNER TOP GARNISH CLIPS - SET	1	40.00	20	40.00
REAR END PANEL SEALANT	1	80.00	60	80.00
REAR FENDER INNER TRIM BOARD CLIPS L/R - SET	2	50.00	30	100.00
REAR TAILGATE INNER TRIM BOARD CLIPS - SET	1	50.00	30	50.00
REAR TAILGATE OUTER CHROME HANDLE CLIPS - SET	1	35.00	10	35.00
REAR TAILGATE REVERSE CAMERA	1	500.00	+	500.00

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

TAN HUI CHUN
BLK 32 ANCHORVALE LANE #08-23
SINGAPORE 544590

Contact : 98294684, 96829580

TAX INVOICE

Repair Code : CLM15709
Date in : 28/10/2022
Vehicle Num. : SLA8216U
Model : MAZDA BIANTE 5-DOOR WAGON 2.0L SP.6EAT
Chassis/Eng# : JM6CC1071G0109182/PE30860716

REAR TAILGATE WINDSCREEN SEAL	1	80.00	30	80.00
REAR TAILGATE WINDSCREEN SEALANT	1	80.00	30	80.00
REAR TAILLAMP CLIPS L/R - SET	2	25.00	10	50.00
Subtotal before discount				1,315.00
Percentage discount 0%				0.00
Sub-total 2				1,315.00
Parts-total				9,954.36

LABOUR

- To remove, reinstall electrical wiring harness, check lighting and rewire for parking sensor.
- To remove, reinstall tailgate windscreen
- To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)
- To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.
- To remove and change exhaust silencer box with pipe, re-align where necessary consistent to the accident.
- To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.
- To apply anti-rust chemical on repaired and replaced panel.
- To remove, reinstall tailgate mechanism and check for function

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

*** This is a computer-generated document which requires no signature.***

page 3

Labour Total
Parts & Labour Total

3,350.00
13,304.36

total: 9845.20
L/S: 7.81c ✓

Adrian C
L/S 31/10/22
06 hrs.