

HUA MENG SPRAY PAINTING WORKSHOP

1, Kaki Bukit Avenue 6, Blk C #01-61 / 01-34, Singapore 417883

Autobay @ Kaki Bukit

Tel: 6747 8064, 6746 5519 / 9666 9680 Fax: 6743 4896

ESTIMATE

Vehicle No : SLZ3986G

Chassis No: KMHD841CMJU631650

Make/Model : HYUNDAI ELANTRA

Accident date : 17.10.2022

TP Likely. Xiao Chai.
KMHD841CMJU631650

No	DESCRIPTION	Qty	Amount (\$S)
List Items			
1	Rear windscreen rubber <i>Nec</i>	1	\$ 129.80
2	Rear bumper <i>Distorted.</i>	1	\$ 489.80
3	Rear bumper side holder @ \$58.90 <i>RH Damaged</i>	2	\$ 117.80
4	Rear bumper RH reflector <i>not nec</i>	1	\$ 78.40
5	Rear bumper RH lower mud flap <i>Not nec</i>	1	\$ 169.00
6	Rear RH bootlid reflector <i>cut</i>	1	\$ 598.20
7	Rear RH lamp <i>cracked.</i>	1	\$ 790.80
8	Rear RH lamp housing <i>Broken</i>	1	\$ 948.20
9	Rear RH fender <i>Broken</i>	1	\$ 1,679.80
10	Rear RH fender lower sticker <i>nec</i>	1	\$ 35.00
11	Rear RH air vent <i>cracked</i>	1	\$ 39.90
12	Rear RH fender inner shield <i>torn</i>	1	\$ 189.00
			\$ 5,265.70
			Less 20% Disc \$ 1,053.14
			Total \$ 4,212.56

Special Nett Items			
1	Rear RH sport rim <i>cut</i>	1	\$ 800.00
2	Rear RH tyre <i>not nec</i>	1	\$ 380.00
3	Rear RH fender inner shield clips (1 set) <i>nec</i>	1	\$ 50.00
4	Rear bumper clips (1 set) <i>nec</i>	1	\$ 50.00
5	Rear lamp clips (1 set) <i>nec</i>	1	\$ 40.00
			Total \$ 1,320.00

Labour Cost			
1	To supply rear windscreen sealant <i>nec</i>		\$ 50.00
2	Remove & reinstall rear windscreen		\$ 150.00
3	Remove & reinstall reverse sensor		\$ 150.00
4	Remove & reinstall bootlid inner garnish		\$ 200.00
5	Remove, replace & repair consistent to the accident		\$ 1,600.00
6	Respray painting		\$ 1,100.00
7	Tuff kote		\$ 150.00
			Total \$ 3,400.00

Grand Total \$ 8,932.56

As a condition of the estimate, the Repairee hereby notifies the Repairee of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairee

Signature:

Date:

1660

4.5K

total: 5614.24
h/s: HSK
05 Days