



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### TAX INVOICE

|                                     |           |                        |
|-------------------------------------|-----------|------------------------|
| CHINA TAIPING INSURANCE (S) PTE LTD | INV No.   | AC2300362              |
| 3 ANSON ROAD #16-00                 | INV Date  | 17/01/2023             |
| SPRINGLEAF TOWER                    | Reference | CC6/CTI22010833/Dpa3q2 |
| SINGAPORE 079909                    | Code      | CTI                    |

### PROFESSIONAL SERVICE FEE

|                 |                    |
|-----------------|--------------------|
| Vehicle No.     | SHC 7918X          |
| Insured Veh.    | SLB 975J           |
| Claim No.       | SNM22D207877/C02   |
| Policy No.      | DMPCSNW00201142203 |
| Accident Date   | 22/06/2022         |
| Inspection Date | 27/06/2022         |

| Description         | Total         |
|---------------------|---------------|
| Survey Inspection   | 280.00        |
| Resurvey Inspection |               |
| Digital Photographs |               |
| Transportation      |               |
| <b>Subtotal</b>     | <b>280.00</b> |
| <b>GST (8%)</b>     | <b>22.40</b>  |
| <b>Grand Total</b>  | <b>302.40</b> |

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

**LKM**



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile  |  |  |            |
|--|--|--|------------|
| CHINA TAIPING INSURANCE (S) PTE LTD<br>3 ANSON ROAD #16-00<br>SPRINGLEAF TOWERSINGAPORE 079909   |  | Ref: CC6/CTI22010833/Dpa3q2<br>Date: 17/01/2023<br>Code: CTI |            |
| 1. Policy Particulars :- THIRD PARTY CLAIM   |  |  |            |
| Insured Veh.   | SLB 975J   | Veh. Inspected   | SHC 7918X  |
| Policy No.   | DMPCSNW00201142203   | Coverage (\$)  | 0.00       |
| Claim No.  | SNM22D207877/C02   | Excess (\$)  | 0.00       |
| Assign From  |  | Assign Date  | 27/06/2022 |
| 2. Vehicle Particulars & Condition   |  |  |            |
| Make & Model   | HYUNDAI IONIQ  | c.c  | 1580       |
| Engine No.   | HIDDEN   | Year of Reg.   | 2019       |
| Chassis No.  | KMHC851CVLU181018  | Colour   | YELLOW     |
| Odometer   | 347980 KM  | Steering   | IN ORDER   |
| Brakes   | IN ORDER   | Modification   | SPORTS RIM |
| General  | GOOD   |  |            |
| 3. Conditions of Tyres   |  |  |            |
|  | Size   | Make   | Balance    |
| R/H Front Tyre   | 195/65 R15   | WEST LAKE  | 5 mm       |
| L/H Front Tyre   | 195/65 R15   | WEST LAKE  | 5 mm       |
| R/H Rear Tyre  | 195/65 R15   | WEST LAKE  | 5 mm       |
| L/H Rear Tyre  | 195/65 R15   | WEST LAKE  | 5 mm       |
| 4. Description of Damages  |  |  |            |
| THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION.<br>DAMAGES SEE DETAILS.  |  |  |            |
| 5. General Information   |  |  |            |
| Accident Date  | 22/06/2022   | Inspection Date  | 27/06/2022 |
| Survey held at   | BIFROST AUTO PTE LTD<br>8 KAKI BUKIT AVENUE 4<br>#01-49 PREMIER @ KAKI BUKIT<br>SINGAPORE 415875 |  |            |
| 5a. Remarks  |  |  |            |
| A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.<br>B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |  |  |            |
| 5b. Estimate Days of Repair  |  |  |            |
| ESTIMATED NORMAL PERIOD FOR REPAIR:  |  | 7 Working Days   |            |



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 7918X

| Qty | Description of Parts                                  | Condition                      | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----|---|--------------------------------|---------------------------|-------------------|
|     | <b><u>REPLACEMENT OF PARTS</u></b>                    |                                |                           |                   |
| 1   | BONNET  | NOT NECESSARY                  | 2,253.80                  | -                 |
| 2   | BONNET HINGE (LH/RH) @\$118.70                        | NOT NECESSARY                  | 237.40                    | -                 |
| 1   | BONNET MOULDING                                       | NOT NECESSARY                  | 41.40                     | -                 |
| 1   | BONNET LOCK   | SERVICEABLE                    | 127.30                    | -                 |
| 1   | BONNET INSULATOR                                      | NOT NECESSARY                  | 230.10                    | -                 |
| 1   | BONNET INSULATOR CLIPS                                | NOT NECESSARY                  | 15.00                     | -                 |
| 1   | RADIATOR GRILLE NEW MODEL                             | CUT                            | 1,568.60                  | 1,568.60          |
| 2   | FLAP ASSY ACTIVE AIR UPPER, (LH/RH) @\$824.60         | MTG CRACKED                    | 1,649.20                  | 1,649.20          |
| 1   | SPEAKER ASSY-VESS                                     | NOT NECESSARY                  | 554.40                    | -                 |
| 1   | FRONT NUMBER PLATE GARNISH                            | SERVICEABLE                    | 188.00                    | -                 |
| 1   | FRONT BUMPER COVER                                    | TORN                           | 481.10                    | 481.10            |
| 1   | FRONT BUMPER TOP COVER                                | SERVICEABLE                    | 476.30                    | -                 |
| 1   | FRONT BUMPER SPONGE                                   | TORN                           | 186.90                    | 186.90            |
| 1   | FRONT BUMPER REINFORCEMENT                            | DENTED                         | 1,136.70                  | 1,136.70          |
| 2   | FRONT BUMPER REINFORCEMENT ABSORBER (LH/RH) @\$186.50 | O/S BENT / N/S NOT NECESSARY   | 373.00                    | 186.50            |
| 1   | FRONT BUMPER TOWING COVER                             | SERVICEABLE                    | 29.00                     | -                 |
| 1   | FRONT BUMPER MOULDING CENTRE UPPER                    | DEFORMED / DISTORTED           | 368.50                    | 368.50            |
| 1   | FRONT BUMPER MOULDING                                 | NOT NECESSARY                  | 93.60                     | -                 |
| 1   | FRONT BUMPER LOWER STIFFNER                           | NOT NECESSARY                  | 285.10                    | -                 |
| 1   | FRONT BUMPER LOWER GRILLE                             | DEFORMED / DISTORTED           | 365.30                    | 365.30            |
| 1   | FRONT BUMPER LOWER GRILLE MOULDING                    | BENT                           | 127.60                    | 127.60            |
| 1   | FRONT BUMPER LIP                                      | NOT NECESSARY                  | 35.10                     | -                 |
| 2   | FRONT BUMPER BRACKET TOP (LH/RH) @\$35.00             | BROKEN                         | 70.00                     | 70.00             |
| 2   | FRONT BUMPER BRACKET (LH/RH) @\$28.00                 | O/S BROKEN / N/S NOT NECESSARY | 56.00                     | 28.00             |
| 2   | FRONT BUMPER RETAINER MOUNTING (LH/RH) @\$65.30       | NOT NECESSARY                  | 130.60                    | -                 |
| 10  | FRONT BUMPER CLIPS                                    | NECESSARY                      | 25.00                     | 25.00             |
| 2   | FRONT BUMPER GRILLE (LH/RH) @\$186.90                 | SERVICEABLE                    | 373.80                    | -                 |
| 2   | FRONT BUMPER AIR DUCT (LH/RH) @\$153.80               | NOT NECESSARY                  | 307.60                    | -                 |

Report Ref No. CC6/CTI22010833/Dpa3q2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

| Qty | Description of Parts                   | Condition                         | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----|--|-----------------------------------|---------------------------|-------------------|
| 1   | DAY LIGHT, LH                          | NOT NECESSARY                     | 642.50                    | -                 |
| 1   | DAY LIGHT, RH                          | MTG BROKEN                        | 642.50                    | 642.50            |
| 1   | HEADLAMP SUPPORT PANEL ASSY            | MTG BROKEN                        | 1,139.30                  | 1,139.30          |
| 2   | HEADLAMP (LH/RH) @\$3987.30            | CRACKED / MTG BROKEN              | 7,974.60                  | 4,220.60          |
| 2   | HORN UNIT (LH/RH) @\$72.80             | NOT NECESSARY                     | 145.60                    | -                 |
| 1   | RADIATOR INVERTER                      | BENT                              | 884.80                    | 884.80            |
| 1   | RADIATOR                               | BENT                              | 710.50                    | 710.50            |
| 1   | RADIATOR FAN BLOWER MOTOR ASSY         | CRACKED                           | 1,459.60                  | 1,459.60          |
| 2   | RADIATOR AIR GUARD (LH/RH) @\$76.40    | NOT NECESSARY                     | 152.80                    | -                 |
| 1   | AIRCON CONDENSER                       | BENT                              | 663.60                    | 663.60            |
|     | LESS 20% DISCOUNT                      |                                   | -5,240.44                 | -3,182.86         |
|     |  |                                   | 20,961.76                 | 12,731.44         |
|     | <b>NETT ITEMS</b>                      |                                   |                           |                   |
| 2   | EMBLEM-BLUE DRIVE (LH/RH) @\$26.60 (N) | O/S NECESSARY / N/S NOT NECESSARY | 53.20                     | 26.60             |
|     | LESS 20% DISCOUNT                      |                                   | -                         | -5.32             |
|     |  |                                   | 53.20                     | 21.28             |
|     | <b>SPECIAL NETT ITEMS</b>              |                                   |                           |                   |
| 1   | FRONT NUMBER PLATE (SN)                | SERVICEABLE                       | 25.00                     | -                 |
| 1   | FRONT NO PLATE TRIM COVER (SN)         | SERVICEABLE                       | 30.00                     | -                 |
| 1   | COOLANT (SN)                           | NOT NECESSARY                     | 45.00                     | -                 |
|     |  |                                   | 100.00                    | -                 |
|     | <b>LABOUR</b>                          |                                   |                           |                   |
|     | PANEL BEATING.                         |                                   | 1,600.00                  | 700.00            |
|     | SPRAY PAINTING CHARGE.                 |                                   | 1,400.00                  | 500.00            |
|     | WIRING CHARGE.                         |                                   | 100.00                    | 30.00             |
|     | TUFF KOTE.                             |                                   | 100.00                    | 40.00             |
|     | TOWING CHARGE.                         | NOT NECESSARY                     | 80.00                     | -                 |
|     | REMOVE / REFIX RADIATOR.               |                                   | 90.00                     | 50.00             |
|     | REMOVE / REFIX AIRCON & REFILL GAS.    |                                   | 130.00                    | 80.00             |



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

| Qty   | Description of Parts                        | Condition | Estimate By Workshop (\$) | Our Adjusted (\$) |
|---|---|-----------|---------------------------|-------------------|
|   | DIAGNOSTIC & RESETTING TO ERASE FAULT CODE. |           | 550.00                    | 150.00            |
|   |   |           | 4,050.00                  | 1,550.00          |
| <b>GRAND TOTAL</b>  |   |           | <b>25,164.96</b>          | <b>14,302.72</b>  |
| <b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b> |   |           |                           | <b>12,800.00</b>  |

Report Ref No. CC6/CTI22010833/Dpa3q2

**ANG BRYAN TANI**

**Automotive Assessor / Investigator**

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.**

**No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.**



# LKK Auto Consultants Pte Ltd


51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SHC 7918X

INSPECTION






# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R







# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R








# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R








# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R








# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SHC 7918X

RE-INSPECTION





# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R







# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R







# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

## PHOTOGRAPHS FOR VEHICLE NO. SHC 7918X

## RE-INSPECTION





# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R









# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

