

SPECIALISTS MOTOR PTE LTD

Block 3018A, Ubi Road 1, #01-24-26, Singapore 408711
 Tel: 67472112 (5 lines) Fax: 67438032
 Email: cardoc@singnet.com.sg
 Bus. Reg No: 199502604 E GST No: 19-9502604-E

SM/SMH4313A/2211149

01st November 2022

The Manager
 Motor Claim Department
 AIG Asia Pacific Insurance Pte Ltd
 CHARTIS Building
 78 Shenton Way #07-16
 Singapore 079120

*not allowed
 here
 wrong
 2/11/22
~~2/11/22~~
 6 days.
 take photo before repair.
 P/P @ 13196.36*

Date of Accident : 01st November 2022
 Location : Telok Blangah Road
 Third Party Claim Vehicle No : SMR 5493 D
 Repair Cost For Vehicle No : SMH 4313 A Nissan X-trail

Estimate Supply of Parts & Labours

1235-10x20

No.	Particulars	Qty	Price	Amounts
1	Rear boot cover (nett) <i>dis/cro</i>	1	4,728.00	\$ 4,728.00 ✓
2	Rear boot cover emblem "X-trail" (nett) <i>net</i>	1	118.70	\$ 118.70 ✓
3	Rear boot cover logo (nett) <i>11</i>	1	70.00	\$ 70.00 X
4	Rear boot cover lock (nett) <i>11</i>	1	662.10	\$ 662.10 X
5	Rear boot cover electrical damper L&RH (nett) <i>Diage/Hecky</i>	2	1,358.60	\$ 2,717.20 ✓ 2470-20
6	Rear boot cover hinge L&RH (nett) <i>11</i>	2	38.80	\$ 77.60 X
7	Rear boot cover w/strip (nett) <i>7m1</i>	1	167.20	\$ 167.20 ✓
8	Rear boot cover reflector L&RH (nett) <i>o/s cro</i>	2	412.90	\$ 825.80 lpc
9	Rear boot cover windscreen glass (nett) <i>11</i>	1	1,495.20	\$ 1,495.20 X
10	Rear boot cover windscreen moulding (nett) <i>net</i>	1	75.10	\$ 75.10 ✓
11	Rear boot cover inner board with clips (nett) <i>11</i>	1	511.90	\$ 511.90 X
12	Rear bumper fascia (nett) <i>Dis</i>	1	748.60	\$ 748.60 ✓
13	Rear bumper side retainer L&RH (nett) <i>o/s cro</i>	2	42.00	\$ 84.00 lpc
14	Rear bumper clips (nett) <i>net</i>	1set	60.00	\$ 60.00 ✓
15	Rear bumper reflector L&RH (nett) <i>o/s cro</i>	2	66.90	\$ 133.80 lpc
16	Rear bumper reinforcement beam (nett) <i>Dis</i>	1	643.30	\$ 643.30 ✓
17	Rear bumper chrome (nett) <i>cro</i>	1	185.20	\$ 185.20 ✓
18	Tail lamp RH (nett) <i>cro</i>	1	825.80	\$ 825.80 ✓
19	Rear fender RH (nett) <i>n</i>	1	1,247.60	\$ 1,247.60 X
20	Rear fender wheel arch garnish RH (nett) <i>11</i>	1	175.50	\$ 175.50 X
21	Rear end panel (nett) <i>Bobbin</i>	1	483.70	\$ 483.70 ✓
22	Rear end panel inner garnish (nett) <i>Dis</i>	1	85.00	\$ 85.00 ✓
				\$16,121.30
Less			10%	\$ 1,612.13
				\$14,509.17

SPECIALISTS MOTOR PTE LTD

Block 3018A, Ubi Road 1, #01-24-26, Singapore 408711

Tel: 67472112 (5 lines) Fax: 67438032

Email: cardoc@singnet.com.sg

Bus. Reg No: 199502604 E GST No: 19-9502604-E

SM/SMH4313A/2211149

01st November 2022

<u>No.</u>	<u>Particulars</u>	<u>Qty</u>	<u>Price</u>	<u>Amounts</u>
	Balance b/f			\$14,509.17
23	Rear fender quarter glass RH (s/nett) <i>11</i>	1	432.00	\$ 432.00 <i>X</i>
24	Rear fender quarter glass sealant (s/nett) <i>11</i>	1	60.00	\$ 60.00 <i>X</i>
25	Rear bumper parking sensor (s/nett) <i>shuld</i>	1set	380.00	\$ 380.00 <i>200</i>
				<u>\$15,381.17</u>

Labour Charges :-

	<u>Amounts</u>
Cut out, renew, knocking, welding, straighten & re-align rear end panel, rear boot tub floor panel, rear lamp panel, RH rear fender, RH rear chassis pillar, all affected parts & etc.	\$ 3,200.00 <i>1000</i>
Remove & refix rear boot mechanical lock assy, central locking system, wiper motor assy, electrical damper.	\$ 180.00 <i>100</i>
Remove & refix fuel tank assy to facilitate repairs	<i>11</i> \$ 250.00 <i>X</i>
Remove & refix rear windscreen glass	\$ 180.00 <i>120</i>
Remove & refix rear quarter glass	<i>11</i> \$ 120.00 <i>X</i>
Remove & refix interior upholstery, roof lining, seats, carpets, furnisher, trimming, safety belt, all affected parts & etc	\$ 280.00 <i>100</i>
Place vehicle on measuring bench	<i>11</i> \$ 480.00 <i>X</i>
Spray painting on damage parts	\$ 1,900.00 <i>1100</i>
Tuff-kote on damage parts	\$ 180.00 <i>60</i>
Check water seeping after repairs	<i>11</i> \$ 120.00 <i>X</i>
Remove & refix rear bumper sensor	\$ 280.00 <i>50</i>
Check all wiring & lighting after repairs	\$ 80.00 <i>30</i>
Diagnosis check & reset after repairs	\$ 200.00 <i>50</i>
Labour Charge	<u>\$ 7,450.00</u>
Total Amount	<u>\$22,831.17</u>

GST will be reflected in the final bills.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

2-11540-40
102
10286.36
200
2610
13196.30

SPECIALISTS MOTOR PTE LTD

Block 3018A, Ubi Road 1, #01-24-26, Singapore 408711

Tel: 67472112 (5 lines) Fax: 67438032

Email: cardoc@singnet.com.sg

Bus. Reg No: 199502604 E GST No: 19-9502604-E

SM/SMH4313A/2211149

01st November 2022

The Manager
Motor Claim Department
AIG Asia Pacific Insurance Pte Ltd
CHARTIS Building
78 Shenton Way #07-16
Singapore 079120

Date of Accident : 01st November 2022
Location : Telok Blangah Road
Third Party Claim Vehicle No : SMR 5493 D
Repair Cost For Vehicle No : SMH 4313 A Nissan X-trail

Supplementary Supply of Parts

<u>No.</u>	<u>Particulars</u>		<u>Qty</u>	<u>Price</u>	<u>Amounts</u>
1	Rear bumper bracket L&RH (nett) <i>bracket/ID</i>		2	211.40	\$ 422.80
2	Rear bumper inner side garnish LH (nett) <i>MCS</i>		1	30.00	\$ 30.00
					\$ 452.80
			Less	10%	\$ 45.28
					\$ 407.52

GST will be reflected in the final bills.