

Date: 01/11/2022
Vehicle No: SMM7174M
Model: TOYOTA NOAH HYBRID 1.8X
Chassis: ZWR800391245 - 2019
Reg.Year: 2019

Third Party Insurer: AIG
Third Party Veh No: SLW7602D
Date of Accident: 29/10/2022
Estimator: KIT
Surveyor:

ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	REAR TAILGATE	1		124 \$1,460.50
2	REAR TAILGATE WINDSCREEN MOULDING	1		Re \$95.10
3	REAR TAILGATE OUTER CHROME GARNISH	1		\$839.70
4	REAR TAILGATE "LOGO" EMBLEM	1		\$72.80
5	REAR TAILGATE "HYBRID" EMBLEM	1		Re \$75.40
6	REAR TAILGATE MECHANISM LOCK	1		Tr \$435.10
7	REAR TAILGATE INNER HANDLE COVER	1		\$32.40
8	REAR TAILGATE INNER TRIM BOARD	1		\$570.80
9	REAR TAILGATE WEATHERSTRIP	1		\$220.30
10	REAR TAILLAMP LH	1		\$876.90
11	REAR TAILLAMP RH	1		Re \$876.90
12	REAR SIDE GARNISH LH	1		Re \$196.40
13	REAR SIDE GARNISH RH	1		Re \$196.40
14	REAR SIDE GARNISH LOWER BRACKET LH	1		\$142.10
15	REAR SIDE GARNISH LOWER BRACKET RH	1		Re \$142.10
16	REAR BUMPER	1		Re \$781.60
17	REAR BUMPER SIDE RETAINER LH	1		DIY \$85.30
18	REAR BUMPER SIDE RETAINER RH	1		Re \$85.30
19	REAR BUMPER REFLECTOR LH	1		\$76.30
20	REAR BUMPER REFLECTOR RH	1		Re \$76.30
21	REAR BUMPER TOWING COVER	1		Re \$31.20
22	REAR BUMPER INNER ANTENNA SENSOR	1		\$97.50
23	REAR END PANEL	1		Re \$586.70
24	REAR END PANEL TOP GARNISH	1		\$207.10
25	REAR FLOOR PANEL	1		\$798.80
26	REAR FLOOR PANEL TOP CARD BOARD	1		\$830.40
27	REAR FENDER INNER TRIM BOARD LH	1		\$582.20
28	REAR FENDER INNER TRIM BOARD RH	1		\$582.20
29	REAR FENDER LH	1		REPAIR
SUB TOTAL				\$11,053.80
LESS 25%				-\$2,763.45
PARTS TOTAL				\$8,290.35

Head office

8 Kung Chong Road Singapore 159143
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500
Tel: (+65) 6484 9919 | Fax: (+65) 6481 1993

Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047
Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011



Date: 01/11/2022
Vehicle No: SMM7174M
Model: TOYOTA NOAH HYBRID 1.8X
Chassis: ZWR800391245 - 2019
Reg.Year: 2019

Third Party Insurer: AIG
Third Party Veh No: SLW7602D
Date of Accident: 29/10/2022
Estimator: KIT
Surveyor:

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$
1	REAR TAILGATE WINDSCREEN SEALANT	1		<i>rm</i> \$80.00
2	REAR NUMBER PLATE WITH HOLDER	1		<i>rm</i> \$50.00
3	REAR TAILGATE INNER TRIM BOARD CLIPS	1		<i>rm</i> \$40.00
4	REAR BUMPER CLIPS	1		<i>rm</i> \$50.00
5	REAR BUMPER REVERSE SENSOR	1		<i>rm</i> \$250.00
6	REAR END PANEL TOP GARNISH CLIPS	1		<i>rm</i> \$30.00
7	REAR END PANEL JOINT SEALANT	1		\$60.00
8	REAR FLOOR PANEL INSULATOR MAT	1		\$100.00
9	REAR FENDER INNER TRIM BOARD CLIPS LH	1		\$50.00
10	REAR FENDER INNER TRIM BOARD CLIPS RH	1		\$50.00
S/N TOTAL				\$760.00

LABOUR CHARGES:

LABOUR CHARGES TO REMOVE, REPLACE, REFIX & READJUST AT ACCIDENT AREAS. \$1,200.00 ?

LABOUR CHARGES FOR PAINTING & FURNISHING MATERIALS AT ACCIDENT AREAS. \$1,200.00 900/

LABOUR CHARGES TO REMOVE & REFIX REAR WINDSCREEN GLASS. \$120.00 ✓

LABOUR CHARGES TO REMOVE & REINSTALLED REAR TAILGATE INNER MECHANISM & ETC BACK TO ORIGINAL OPERATIONS. \$120.00 60/

LABOUR CHARGES TO REMOVE & REFIX 3RD ROW SEAT CUSHION & ETC. \$100.00 ?

LABOUR CHARGES TO REMOVE & REFIX REAR EXHAUST SILENCER BOX & ETC. *nn* \$100.00 X

LABOUR CHARGES TO REMOVE & REPLACE REAR BUMPER REVERSE SENSOR. \$100.00 30/

TO TUFF KOTE & UNDERSEAL MATERIALS. \$100.00 ?

TO CHECK WIRING & ELECTRICAL SYSTEM & ETC. \$80.00 20/

LABOUR TOTAL \$3,120.00

KIT TOTAL \$12,170.35

Head office

6 Kung Chong Road Singapore 159143
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554600
Tel: (+65) 6484 9019 | Fax: (+65) 6481 1993

Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047
Tel: (+65) 6481 1622 | Fax: (+65) 6481 1011

