



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

## DAMAGE ASSESSMENT REPORT

INCOME INSURANCE LTD

Ref: CS/INC22010841/Kvy3e2

75 BRAS BASAH ROAD  
INCOME CENTRESINGAPORE 189557

Date: 21/06/2023

ATTN: RODENIC YUEN

Code: INC

### 1. Policy Particulars :- THIRD PARTY CLAIM

<b>Insured Veh.</b>	GBG 9155S	<b>Veh. Inspected</b>	SDR 3338P
<b>Policy No.</b>		<b>Coverage (\$)</b>	0.00
<b>Claim No.</b>	MT/1194925-002	<b>Excess (\$)</b>	0.00
<b>Assign From</b>	HAZALYSA	<b>Assign Date</b>	01/11/2022

### 2. Vehicle Particulars & Condition

<b>Make &amp; Model</b>	TOYOTA WISH (A)	<b>c.c</b>	1798
<b>Engine No.</b>	HIDDEN	<b>Year of Reg.</b>	2016
<b>Chassis No.</b>	JTDGG20W80J004933	<b>Colour</b>	METALLIC ORANGE
<b>Odometer</b>	91656 KM	<b>Steering</b>	JAMMED
<b>Brakes</b>	IN ORDER	<b>Modification</b>	STANDARD ALLOY RIM
<b>General</b>	GOOD		

### 3. Conditions of Tyres

	Size	Make	Balance
<b>R/H Front Tyre</b>	195/65 R15	TOURADOR	2 mm
<b>L/H Front Tyre</b>	195/65 R15	TOURADOR	2 mm
<b>R/H Rear Tyre</b>	195/65 R15	GOODRICH	4 mm
<b>L/H Rear Tyre</b>	195/65 R15	GOODRICH	4 mm

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. THE UNDERCARRIAGE AND BODY STRUCTURE AFFECTED DUE TO COLLISION.

DAMAGES SEE DETAILS.

### 5. General Information

<b>Accident Date</b>	30/10/2022	<b>Inspect Date / Time</b>	01/11/2022 ( 01:30 PM )
<b>Survey held at</b>	SUPREME AUTO SERVICE PTE LTD 176 SIN MING DRIVE #02-01 SIN MING AUTOCARE SINGAPORE 575721		

### 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.  
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

### 5b. Estimate Days of Repair

<b>ESTIMATED NORMAL PERIOD FOR REPAIR:</b>	<b>21 Working Days</b>
--	------------------------