	FASTECH AUTO PTE LTD 1 Kaki Bukit Ave 6 #01-48 Autobay Singapore 417883 Tel No: 67452063/67467158 Fax No: 67458520 Tax Reg No: 200006262D VEHICLE No: GBG 8920G	Not Authorist 1/11/22 2/5 \$ 6200 Says.
1PC 1PC 2PCS 1PC 1PC 1PC 1PC 1PC	REAR WINDSCREEN TAILGATE TAILGATE INNER STOPPERS @\$21.00 TAILGATE INNER LOCK TAILGATE LOCK ACTUATOR TAILGATE 'NISSAN' LOGO TAILGATE 'NV 350' EMBLEM TAILGATE 'URVAN' EMBLAM	\$988.20 \(\) \(\
1PC 1PC 1PC 2PCS 2PCS 1PC 1PC 1PC 1PC 2PCS 2PCS 1PC	TAILGATE INNER TRIM TAILGATE RUBBER TAILGATE OUTER CHROME MOULDING REAR BUMPER REAR BUMPER SIDE RETAINERS @\$27.00 REAR BUMPER SIDE HOLDERS @\$28.00 REAR END PANEL REAR END PANEL INNER REAR END PANEL TOP PLATE REAR STEP PANEL TAILLAMPS @\$224.80 TAILLAMP HOUSING PANELS @\$408.00 REAR FENDER	\$417.80 \$134.40 \$482.30 \$667.20 \$54.00 \$56.00 X \$547.10 \$1,110.20 \$122.80 \$178.90 \$449.60 \$916.00 X \$2,915.00 X \$12,070.30
1PC	S.NETT REAR WINDSCREEN SEALANT ALL	\$50.00 \$
1PC 1SET 1SET 1SET 1PC 1SET 1PC 1PC	REAR WINDSCREEN INNER SEAL TAILGATE INNER TRIM CLIPS REAR BUMPER CLIPS REAR BUMPER REVERSE SENSOR REAR END PANEL SEALANT TAILGATE 70Km/h & 8 PAX STICKER REAR FLOOR PANEL TOP WOODEN REAR LICENCE PLATE	\$50.00 \$\varphi_0\$ \$50.00 \$\cappa_0\$ \$50.00 \$\cappa_0\$ \$50.00 \$\square\$ \$20.00 \$\square\$ \$20.00 \$\square\$
	TO CHECK WIRING TO DISMANTLE & REPLACED REVERSE SENSOR TO DISMANTLE & REFIX REAR WINDSCREEN TO TRANSFER TAILGATE MECHANISM TO SPRAY RUST PROOFING	\$50.00 20 \$80.00 50 \$150.00 120 \$100.00 60 \$100.00 60

LABOUR FOR PANEL BEATING & REPLACED PARTS TO PUTTY & SPRAY PAINTING

\$1,500.00 800 \$1,580.00 9 00 \$15,793.27

TOTAL

Acto Consultants hence notify

- the Repairer of the following:
- To resurvey before/after spray painting
 To display damaged part(s) during resurvey
- of arts prices are subject to confirmation
- * Turd party survey is on a "Without Prejudice" basis
- * No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P-6007 102 540630 410 7821.30