



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
HSBC LIFE (SINGAPORE) PTE LTD 10 MARINA BOULEVARD #48-01 MARINA BAY FINANCIAL CENTRE TOWER 2SINGAPORE 018983 ATTN:KHOR SAW THENG		Ref: CC4/ASM22010846/Rpa3q2 Date: 19/04/2023 Code: HSB	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHB 4947L	Veh. Inspected	SMQ 4762P
Policy No.	P2465703	Coverage (\$)	0.00
Claim No.	S2M04DTF	Excess (\$)	0.00
Assign From		Assign Date	01/11/2022
2. Vehicle Particulars & Condition			
Make & Model	TOYOTA NOAH HYBRID 1.8X	c.c	1797
Engine No.	HIDDEN	Year of Reg.	2019
Chassis No.	ZWR800409691	Colour	WHITE
Odometer	180076 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	195/65 R15	FIRENZA	6 mm
L/H Front Tyre	195/65 R15	FIRENZA	6 mm
R/H Rear Tyre	195/65 R15	FIRENZA	6 mm
L/H Rear Tyre	195/65 R15	FIRENZA	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	30/10/2022	Inspection Date	02/11/2022
Survey held at	MY CAR CONSULTANT PTE LTD 60 JALAN LAM HUAT #05-21 CARROS CENTRE SINGAPORE 737869		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		7 Working Days	