

Marked Estimate with Supplementary

Repair Estimate



VAG Singapore Pte Ltd

48 Toh Guan Road East

#05-136, Enterprise Hub

Singapore 608586

Tel: 6267 9916

Fax: 6267 9313

www.avantage.sg

STEVE (LKK) 8322 8813

3/11/22, 11:00L

m n

3 dys, PIP, my BR y

Date : 31-Oct-2022

Vehicle Num : SMX70S

Make/Model : Nissan Serena 1.2L Highway Stay Premium I

Chassis No : JN1EBAC27Z0000607

S/N	PARTS	QTY	PRICE	TOTAL
1	Rear Bumper / BR	1	\$ 1,800.96	\$ 1527 ✓ 1,800.96
2	RH Bracket, Rear Bumper X nn	1	\$ 63.68	\$ 63.68 X
3	RH Stay, Rear Bumper / BR	1	\$ 63.86	\$ 63.86 ✓
4	RH Rear Corner Garnish (below the Taillight) / BR	1	\$ 540.89	\$ 384 ✓ 540.89
1.	RH Rear Bumper Garnish <u>Supplementary</u> CUT	1	\$ 432.87	\$ 432.87 ✓
TOTAL PARTS			2407.73	\$ 2,469.39
Less 30%			-10% 2166.95	\$ 740.82
TOTAL AMOUNT				\$ 1,728.57
MISCELLANEOUS ITEM				
1	Sunderies nec		\$ 18.75	\$ 15 ✓ 18.75
LABOUR				
1	Remove and refit Rear Bumper, Bracket, Stay, RH Corner Garnish and other associate components.		\$ 200 320.00	\$ 320.00
2	Surface preparation, spray paint and polish Rear Bumper, RH Corner Garnish and other affected areas.		\$ 375.00	\$ 375.00 ✓
3	Diagnostic check and erase fault codes after the repair.		\$ 30 80.00	\$ 80.00
TOTAL			605	\$ 2,522.32
GST 7%				\$ 176.56
GRAND TOTAL				\$ 2,698.88

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____

P/P - 2786.95