

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Fievel Foo Wen Yao

Date: 16 Mar 2023

Preliminary Advice

Insured Vehicle No	: FBJ5301Y	Accident Date	: 27/10/2022
TP Vehicle No	: SMZ3727B	Assignment Date	: 01/11/2022
Make	: TOYOTA RAIZE	Est. Duration of Repair	: 7
Date of Inspection	: 01/11/2022		
Inspection At	: WIN AUTOMOTIVE SERVICES 60 JALAN LAM HUAT #04-53 SINGAPORE 737869		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	17,746.25
Revised Amount	:S\$	11,319.44
Check Items (Estimated)	:S\$	0.00
Total	:S\$	11,319.44

Lump Sum Repair	:S\$	9,050.00
-----------------	------	----------

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	98,000.00
COE / PARF Rebate	:S\$	39,329.00
Salvage Value	:S\$	
Margin for Repair	:S\$	58,671.00

Remarks

- () The vehicle is economical for repair
- () The vehicle is not economical for repair
- () Part-by-Part repair
- (X) Lump Sum repair

- (X) The above survey was conducted on a 'without prejudice' basis.
Please note that the preliminary advice amount (Revised & Check Items) stated are subject to consistency check, part prices and labour cost.