

SUPER-ZEE MOTOR SERVICE

BLK 14 DEFU LANE 10 #01-402 SINGAPORE 539195 TEL: 6383 1913 FAX: 6383 9565
EMAIL: superzeemotor@gmail.com

1 Nov 2022

Lonpac Insurance Bhd
300 Beach Road #17-04/06
The Concourse
Singapore 199555
Att: Motor Claims Dept

mt_claim@lonpac.com

not Audited
her
3/11/22
L/S # 6500
Sdng
Ch phb. Atkny

THIRD PARTY CLAIM

OWNER NAME : THALVINDERPAL SINGH SANDHU
VEHICLE REG NO : SMS9133L
DATE OF ACCIDENT : 28 OCT 2022
PLACE OF ACCIDENT : PIE
INVOLVING VEH NO : GW2273L

We append herewith our estimate for the repairs of SMS9133L as follows:

Materials Required

1 pc	Tailgate	Body 100	1398.95	S\$1,829.70	✓
1 pc	Tailgate Emblem	- Logo 11		S\$ 91.40	X
		X1		S\$ 78.60	✓
1 pc	Tailgate Inner Lock	shut 11		S\$ 315.20	✓
1 pc	Tailgate Weatherstrip	11		S\$ 248.30	✓
2 pcs	Tailgate Reflectors	n/s one	322.30	S\$ 798.60	12C
2 pcs	Taillamps	n/s one	486.20	S\$ 972.40	12C
1 pc	Rear Bumper	D15	1070.89	S\$1,285.20	✓
1 pc	Rear Bumper Middle Spoiler	D15		S\$ 413.60	✓
1 pc	Rear Bumper Lower Spoiler	D15		S\$ 358.50	✓
1 pc	Rear Bumper Smart Opener Sensor - Top	CU		S\$ 70.50	✓
		Bottom	CU	S\$ 78.50	✓
2 pcs	Rear Bumper Reflectors	11		S\$ 112.20	X
2 pcs	Rear Bumper Retainers	11		S\$ 466.80	X
1 pc	Rear Bumper Beam	523.75		S\$ 665.50	✓
1 pc	Rear Bumper Towing Cover	11		S\$ 57.70	X
10 pcs	Rear Bumper Clips	48.00		S\$ 65.00	✓
1 pc	Rear End Panel - Inner	20		S\$ 458.10	X
	- Outer	20	480.70	S\$ 588.70	✓
1 pc	Rear End Panel Top Garnish	11		S\$ 275.80	X
10 pcs	Rear End Panel Top Garnish Clips	11		S\$ 65.00	X
1 pc	Rear Exhaust Tailpipe	253.30		S\$ 253.30	✓
2 pcs	Rear Exhaust Mountings	78.40		S\$ 78.40	✓
1 pc	Rear Exhaust Insulating Covering	117.50		S\$ 117.50	✓
1 pc	Rear Windscreen Sealant	50.00		S\$ 50.00	40 S/W
2 pcs	Reverse Sensors	232x22-464		S\$ 607.60	✓
1 pc	Rear Number Plate c/w Frame	80.00SN		S\$ 80.00SN	40 S/W
				S\$10,482.10	

SUPER-ZEE MOTOR SERVICE

BLK 14 DEFU LANE 10 #01-402 SINGAPORE 539195 TEL: 6383 1913 FAX: 6383 9565
EMAIL: superzeemotor@gmail.com

SMS9133L

Page 2....

Labour Charges

To dismantle & replace damaged parts, panelbeat where necessary	S\$ 800.00	600
To remove/refit rear windscreen to facilitate change of tailgate	S\$ 150.00	120
To putty, apply primer & spraypaint affected portion	S\$ 900.00	800
To apply rustproofing on repaired, replaced panel	S\$ 180.00	60
To check electrical wiring functions	S\$ 60.00	30
		=====
	S\$12,572.10	
		=====

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

SUPER-ZEE MOTOR SERVICE

P - 6466.83

S.N - 80

L - 1610

8156.83

207

6525

P 6407.19