

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)
 51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
 Singapore 408933
 Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI22010862/KWP3Q2
Date: 21/11/2022

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMB1SNW00003222200
Claimant Vehicle No :	SMR3053D	Insured Vehicle No :	PC1217E
Date of Loss:	27/10/2022	Nature of Claim:	TP
		Claim No:	SNM22D207744/C02/TANCHC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMR3053D	Engine No:	2ZR2F32852
Make & Model:	TOYOTA NOAH HYBRID, 1.8 X CVT (A)	Chassis No:	ZWR800413868
Reg. Date:	27/12/2019 (Man. Year: 2019)	Odometer:	166232 km
Colour:	Metallic Black		
Engine Capacity:	1797 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Farroad 3 mm	Rear Left Side:	Farroad 8 mm
Front Right Side:	Farroad 3 mm	Rear Right Side:	Farroad 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,681.42	3,680.47	1,000.95	21.38
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,020.00	820.00	200.00	19.61
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	5,701.42	4,500.47	1,200.95	21.06
Approved Total (Overridden) (\$\$)		3,600.00		
Nett Amount (\$\$)	5,701.42	3,600.00	2,101.42	36.86

INSPECTION

Date of Assignment:	01/11/2022	
Date Inspected:	08/11/2022	Inspected At:
Estimated Period of Repair:	3.0 days	

BLK 5038 ANG MO KIO INDUSTRIAL PARK 2,
 #01-405
 SINGAPORE 569541.
 Repairer:Lian Her Motor Works (HQ)

Adjuster: KENNETH KONG

Manager: XinYu

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but

any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 21 Nov 2022)
Parts:	M1-MPV	TOYOTA NOAH HYBRID 1.8 X CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMR3053D)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT N/S FENDER	Buckled	988.50 FL	*911.20 FL
2	1		*FRONT N/S FENDER EMBLEM	Necessary	65.10 FL	*65.10 FL
3	1		*FRONT N/S FENDER INNERSHIELD	Serviceable	205.00 FL	*- FL
4	1		*FRONT N/S HEADLAMP ASSY	Mtg Cracked	2,750.80 FL	*2,750.80 FL
5	1		*FRONT N/S HEADLAMP GARNISH	Serviceable	155.20 FL	*- FL
6	1		*FRONT RADIATOR GRILLE	Serviceable	550.70 FL	*- FL
7	1		*FRONT BUMPER	Bent	1,255.70 FL	*1,025.00 FL
8	1		*FRONT N/S BUMPER SIDE RETAINER	Distorted	95.20 FL	*95.20 FL
9	1		*FRONT N/S FOG LAMP COVER	Serviceable	115.70 FL	*- FL
10	15		*BUMPER CLIP	Necessary	45.00 FS	*45.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	6,226.90	4,892.30
- List Item Discount on L Items 25.00/25.00% (\$\$)	1,545.48	1,211.83
Total Parts (\$\$)	4,681.42	3,680.47

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REMOVE/RENEW THE ABOVE PARTS INCLUDING KNOCKING ,WELDING & CUTTING	New	500.00	400.00
2	TO PUTTY & SPRAY PAINT ON ACCIDENT AFFECTED PORTION	New	500.00	400.00
3	CHECK /RECONNECT WIRING	New	20.00	20.00
Gross Labour Cost (\$\$)			1,020.00	820.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >