



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
HSBC LIFE (SINGAPORE) PTE LTD 10 MARINA BOULEVARD #48-01 MARINA BAY FINANCIAL CENTRE TOWER 2SINGAPORE 018983 ATTN:YVONNE		Ref: CC4/ASM22010864/Upa3q2 Date: 19/04/2023 Code: HSB	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHB 4070R	Veh. Inspected	SLN 3006Z
Policy No.	P2465679	Coverage (\$)	0.00
Claim No.	S2M04DUV	Excess (\$)	0.00
Assign From		Assign Date	01/11/2022
2. Vehicle Particulars & Condition			
Make & Model	SUBARU WRX (A)	c.c	1998
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	JF1VAGK85HG017795	Colour	BLUE
Odometer	82067 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	245/40Z R18	PIRELLI	6 mm
L/H Front Tyre	245/40Z R18	PIRELLI	6 mm
R/H Rear Tyre	245/40Z R18	PIRELLI	6 mm
L/H Rear Tyre	245/40Z R18	PIRELLI	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR & FRONT PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	31/10/2022	Inspection Date	01/11/2022
Survey held at	FASTECH AUTO PTE LTD 1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		15 Working Days	