

08/11/13) wef

ASS. REC. BY: Marcus

REF:

CC4/ASM 22010864/Upa3

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

SLN 30067

at Workshop m/s

Rf.

of

Insured:

SHB 4070R

Policy No.

Claims No.


Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

\$110k.

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

15

days

Res.:

Yes or No

Lum Sum:

20

%

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS

6222

Date:

Person Contacted:

Vehicle: IN / OUT
LTA 42825

Veh No:

SLN 30067

Yr Regn:

28/04/17

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

CA /

Make:

Subaru WRX

c.c

1998

Colour

Blue

A/C:

Insured / Std / NI / NA

Sp. Reading

82067

T/Radio:

Insured / Std / NI / NA

Eng/No:

JFIVAGK85HG 017795

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

245/40 22R

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

31/10/22

D.O.I.

1/11/22

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear & Rf.

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Rep 21k.

exhaust invidia brand

21/2/23 1/5 \$21.000 inboard Aler

Date/Time, File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

) S + RS SI

) Photos

) Others

TOTAL

Report Format :

Lump Sum / I.B.I. (\$))

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

FASTECH AUTO PTE LTD

1 Kaki Bukit Ave 6 #01-48 Autobay
Singapore 417883

Tel No: 67452063/ 67467158 Fax No: 67458520

Tax Reg No : 200006262D

VEHICLE No: SLN 3006Z

4/5 \$21,000
15 days

Not Authorised
1/11/22

4/5 \$21,000
15 days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

1PC	BOOTLID	Bent/Buc	1066.00	\$1,885.20
1PC	REAR WINDSCREEN MOULDING	11		\$126.30 X
1PC	BOOTLID REAR LOGO	ner		\$48.60
1PC	BOOTLID 'SUBARU' EMBLEM	ner		\$82.00
1PC	BOOTLID 'WRX' EMBLEM	ner		\$60.00
1PC	BOOTLID 'IMPREZA' EMBLEM	ner		\$80.00
1PC	BOOTLID 'AWD' EMBLEM	ner		\$60.00
1PC	BOOTLID OUTER GARNISH	11		\$341.80 X
1PC	BOOTLID LICENCE PLATE LAMP	11		\$42.00 X
1PC	BOOTLID INNER LOCK	Bent		\$299.00
2PCS	BOOTLID HINGES @\$160.00	11		\$320.00 X
1SET	BOOTLID INNER TRIM BOARD	11		\$250.00 X
1PC	BOOTLID WEATHERSTRIP	11		\$285.00
2PCS	TAILLAMPS @\$1050.00	11		\$2,100.00
2PCS	TAILLAMP LOWER BRACKETS @\$105.00	11		\$210.00
1SET	REAR BUMPER SPORT	Dis		\$2,500.00
1PC	REAR BUMPER LOWER SPOILER	Dis		\$1,500.00
1SET	REAR BUMPER LOWER SIDE SPOILER	Re/ner		\$600.00
2PCS	REAR BUMPER SIDE RETAINERS @\$68.00	Bent		\$136.00
1PC	REAR BUMPER REINFORCEMENT	Bent		\$425.10
1PC	REAR BUMPER SPLASH SHIELD N/S	11		\$98.00 X
1SET	REAR BUMPER CLIPS	ner		\$50.00
1PC	REAR END PANEL	Body		\$680.90
1PC	REAR END PANEL TOP GARNISH	11		\$281.20
2PCS	REAR BLIND SPOT SENSOR ASSY @\$2800.00	MS Daye/Tur		\$5,600.00 1PC
1PC	REAR FLOOR PANEL	crumpled/Buc		\$1,895.20
1PC	REAR FLOOR PANEL TOP BOARD	Torn		\$455.00
1PC	REAR FLOOR PANEL TOOL SPONGE	Torn		\$766.00
1PC	REAR FLOOR PANEL SPARE TYRE SPONGE	Torn		\$455.00
1PC	REAR FLOOR PANEL SPARE TYRE LOCK NUT	ner		\$110.00
2PCS	REAR EXHAUST HEAT SHIELDS @\$190.00	MS Bent		\$380.00 1PC
1PC	REAR FENDER N/S	n		\$1,255.00 X
2PCS	REAR FENDER INNER TRIMS @\$420.00	Re/Torn		\$840.00
1PC	REAR ANTENNA SENSOR	Daye		\$288.00
1PC	BONNET	n		\$2,240.00 X
1PC	BONNET LOCK	11		\$290.00 X
1PC	FRONT BUMPER SPORT	Re/ner		\$2,500.00
1PC	FRONT BUMPER LOWER SPOILER	ner		\$1,550.00
1PC	FRONT BUMPER BEAM	Bent		\$620.00
2PCS	FRONT BUMPER INNER BEAM SIDE GARNISHS @\$120.00	Torn		\$240.00
1PC	FRONT BUMPER TOP BEAM	Bent		\$520.00

202

2PCS	FRONT BUMPER SIDE RETAINERS @\$65.00	Buf		\$130.00	—
2PCS	FRONT BUMPER FOG LAMPS @\$530.00	0/5 cm	390	\$1,060.00	120
2PCS	FRONT BUMPER DAY LIGHT LAMPS @\$450.00	0/5 cm	325	\$900.00	120
1PC	FRONT BUMPER LOWER CENTRE GRILLE	7w1	145	\$345.00	—
1SET	FRONT BUMPER CLIPS	111		\$50.00	—
2PCS	HEADLAMP ASSYS @\$3500.00	holder one	2820x225640	\$7,000.00	—
2PCS	HEADLAMP LOWER BRACKETS @\$155.00	cm	105 x 2 = 210	\$310.00	—
1PC	FRONT GRILLE	cm	395	\$445.00	—
1PC	FRONT GRILLE OUTER GARNISH	20	280	\$520.00	—
1PC	FRONT GRILLE LOGO	111		\$85.00	—
1PC	FRONT SUPPORT PANEL	11		\$920.00	X
1PC	FRONT BRACE PANEL	11		\$151.00	X
1PC	AIR CON CONDENSER	11		\$880.00	X
1PC	RADIATOR	11		\$1,415.00	X
2PCS	FRONT FENDERS @\$650.00	R		\$1,300.00	X
2PCS	FRONT FENDER INNER SHIELDS @\$160.00	11	(202)	\$320.00	X
				\$48,296.30	

S.NETT

1PC	REAR WINDSCREEN SEALANT	11	\$50.00	X
1PC	REAR WINDSCREEN INNER SEAL	11	\$50.00	X
1PC	REAR LICENCE PLATE	11	\$50.00	X
1SET	REAR BUMPER REVERSE SENSOR	shuttl	\$280.00	200
1SET	REAR EXHAUST ASSY 'INVIDIA'	Buf/111	\$3,200.00	2800
1PC	REAR END PANEL SEALANT	111	\$50.00	—
1SET	REAR FLOOR PANEL INSULATOR	111	\$250.00	120
1PC	BOOTLID SEALANT	111	\$50.00	—
1PC	FRONT LICENCE PLATE	Buf	\$50.00	40
1BOL	RADIATOR COOLANT	11	\$50.00	X

TO CHECK WIRING	\$50.00	30
TO DISMANTLE & REPLACED REAR REVERSE SENSOR	\$80.00	50
TO DISMANTLE & REFIX REAR WINDSCREEN	11 \$150.00	X
TO DISMANTLE & REFIX BOOTLID MECHANISM	\$100.00	60
TO DISMANTLE & REFIX CUSHION UPHOLSTERY	\$120.00	80
TO SPRAY RUST PROOFING	\$180.00	100
TO CONDUCT WHEEL ALIGNMENT	11 \$100.00	X
TO RESET & REPROGRAMME SYSTEM	\$480.00	80
TO DISMANTLE & REPLACED REAR EXHAUST	\$220.00	120
TO DISMANTLE & REFIX FUEL TANK	\$100.00	60
TO REFILL AIR CON GAS	11 \$100.00	X
LABOUR FOR PANEL BEATING & REPLACED PARTS	\$3,500.00	2200
TO PUTTY & SPRAY PAINTING	\$2,500.00	1800
TOTAL	\$60,056.30	

23044.8
202
18435.84 3260