

金興(龔)汽車私人有限公司

K. KIM HIN AUTO PTE LTD

160 Sin Ming Drive #02-18/19/20/21

Sin Ming AutoCity

Singapore 575722

Tel: 6452 7018 (5 Lines) Fax: 6458 3895

No. : 32611

Your Reference : Z22VC05012830

Accident Date : 05-Oct-2022

Date : 01-Nov-2022

Our Ref : 022356 / ANGIE

PAGE : 1

LONPAC INSURANCE BHD

300 BEACH ROAD

#17-04/07 THE CONCOURSE

Singapore 199555

ESTIMATED COST OF REPAIR FOR MITSUBISHI CANTER (2998cc) (2014) YN8868R

|       |                                     |             |           |
|-------|-------------------------------------|-------------|-----------|
| 1 pc  | front cabin assy                    | 10,500.00 c |           |
| 1 pc  | dashboard assy                      | 7,500.00 c  |           |
| 1 pc  | dashboard reinforcement             |             |           |
| 1 pc  | air con blower                      |             |           |
| 1 pc  | air con cooling coil                |             |           |
| 1 pc  | air con heater unit                 |             |           |
| 4 pcs | dashboard louver                    |             |           |
| 1 pc  | dashboard louver inner duct         |             |           |
| 1 pc  | dashboard meter                     |             |           |
| 1 pc  | cabin seats assy                    |             |           |
| 1 pc  | steering wheel                      |             |           |
| 1 pc  | steering wheel cover                |             |           |
|       | - (top/lower)                       |             |           |
| 1 pc  | steering column                     |             |           |
| 1 pc  | steering column shaft               |             |           |
| 1 pc  | steering column cone                |             |           |
| 1 pc  | signal/wiper hand indicator         |             |           |
| 1 pc  | steering box                        | 3,200.00 c  |           |
| 1 pc  | wooden flatbed partition            | 3,500.00 c  |           |
|       |                                     | 24,700.00   |           |
|       | Add 15% :                           | 3,705.00    | 28,405.00 |
|       |                                     |             |           |
|       | Labour to remove/replace above      |             | 4,000.00  |
|       | parts and re-align affected portion |             |           |

Con't Page 2 ...

金興(龔)汽車私人有限公司  
K. KIM HIN AUTO PTE LTD  
160 Sin Ming Drive #02-18/19/20/21  
Sin Ming AutoCity  
Singapore 575722  
Tel: 6452 7018 (5 Lines) Fax: 6458 3895

Your Reference : Z22VC05012830  
Our Ref : 022356

Page : 2  
No. : 32611

|                                           |                     |
|-------------------------------------------|---------------------|
| To putty and respray affected<br>portion. | 1,800.00            |
| chassis alignment.                        | 1,200.00            |
| wheel alignment.                          | 80.00               |
| Total :                                   | <u>S\$35,485.00</u> |

Singapore Dollars Thirty Five Thousand Four Hundred  
and Eighty Five Only

Note: Amount quoted above is subject to prevailing GST at time of tax invoice.