

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22010867/UQY3Q2**Date:** 10/11/2022REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSNW00065502200

Claimant Vehicle No : SKX2727S **Insured Vehicle No :** SLJ5112H

Date of Loss: 29/10/2022 Nature of Claim: TP Claim No: SNM22D207820/C02/LEEPG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKX2727S**

Make & Model: MAZDA BIANTE, 2.0 SKYACTIV-G SP.6EAT (A) Engine No: PE31040375

Reg. Date: 29/05/2017 (Man. Year: 2017) Chassis No: JM6CC1071H0110799

Colour: Blue Odometer: 75386 km

Engine Capacity: 1998 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/60 R16 Rear Tyre Size: 205/60 R16

Front Left Side: Yokohama 7 mm Rear Left Side: Yokohama 7 mm

Front Right Side: Yokohama 7 mm Rear Right Side: Yokohama 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,454.00	1,404.00	50.00	3.44
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,059.74	955.95	103.79	9.79
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	2,513.74	2,359.95	153.79	6.12
Approved Total (Overridden) (S\$)		2,350.00		
(S\$)	2,513.74	2,350.00	163.74	6.51
+ GST 7.00/7.00% (S\$)	175.96	164.50	11.46	6.51
Nett Amount (S\$)	2,689.70	2,514.50	175.20	6.51

INSPECTION

Date of Assignment: 01/11/2022

Date Inspected: 01/11/2022 Inspected At: Jin Auto Services Pte Ltd (Defu)
Blk 14 Defu Lane 10, #01-410/412
Singapore 539195

Estimated Period of Repair: 5.0 days

Adjuster: MARCUS CHUA**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 10 Nov 2022)

Parts: M1-MPV MAZDA BIANTE 2.0 SKYACTIV-G SP.6EAT (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SKX2727S)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Dented / Deformed	500.00 FL	*500.00 FL
2	1		*BOOTLID /TAILGATE	Badly Dented	850.00 FL	*850.00 FL
3	1		*BADGE MAZDA	Necessary	30.00 FL	*30.00 FL
4	1		*BADGE MODEL (NPA)	Necessary	0.00 FL	*- FL
5	1		*MANUFACTURER BADGE (NPA)	Necessary	0.00 FL	*- FL
6	1		*REAR SCREEN BOND KIT (NPA)	Necessary	0.00 FL	*- FL
7	1		*UPP R-SCREEN SEAL (NPA)	Necessary	0.00 FL	*- FL
8	1		*SET REAR SCREEN FIX (NPA)	Necessary	0.00 FL	*- FL
9	1		*MOUNTING CLAMP (NPA)	Necessary	0.00 FL	*- FL
10	1		*SPACER (NPA)	Necessary	0.00 FL	*- FL
11	1		*REVERSE SENSOR	Shorted	250.00 FS	*200.00 FS
12	1		*SUNDRY	Necessary	100.00 FS	*100.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	1,730.00	1,680.00
- List Item Discount on L Items 20.00/20.00% (\$\$)	276.00	276.00
Total Parts (\$\$)	1,454.00	1,404.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	105.0 WU X 42.00 SGD/H	New	441.00	357.00
2	LABOUR COST 100.0 WU X 42.00 SGD /H	New	420.00	403.20
3	MATERIAL COST	New	198.74	195.75
Gross Labour Cost (S\$)			1,059.74	955.95

Report was unsubmitted during this print-out.

< END OF ESTIMATES >