

# THIAM HENG HUAT PTE LTD

176 Sin Ming Drive  
#05-14 Sin Ming AutoCare  
Singapore 575721  
Phone 82636295  
GST registration number: 201605960N

**Bill To:**

Kelyn Wong Xin Hui  
c/o 176 Sin Ming Drive  
#05-14 Sin Ming Autocare  
Singapore 575721

# TAX INVOICE

**DATE** 22-Mar-23  
**Invoice No** THH230326  
**Vehicle No** SNG8340M  
**Make/Model** Mercedes B180  
**Date of Accident** 31-Oct-22

| NO    | DESCRIPTION                                 | AMOUNT       |
|-------|---------------------------------------------|--------------|
|       | Lump sum repair costs                       | 11,800.00    |
|       | (Surveyor recommended repair days : 7 days) |              |
|       |                                             | 11,800.00    |
|       | 8% GST                                      | 944.00       |
|       |                                             | \$ 12,744.00 |
| TOTAL |                                             | \$ 12,744.00 |

THIAM HENG HUAT PTE LTD

