

ASS. REC. BY:

REF: ASM/ 220108731kyp

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MY

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

872k

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

06

days

Res.:

Yes or No

Lum Sum:

20

%

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

1 GNA & EM not ready

10/3 6:15pm @ 11, Pod Cars

Date/Time, File Pass to?

☐

: Prel. Report

1)

Date/Time, File Return to?

☐

: Final Report

2)

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Survey Fee:

Transportation

S + RS. \$

Fees

Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$

Veh No:

SNG 8340M Yr Regn: 09, 16

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Mer 3180 C.C. 1593

Colour

White

Sp. Reading

93185

A/C: Insured / Std / NI / NA

Eng No:

T/Radio: Insured / Std / NI / NA

C/No:

WDD 2462422J403892

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

205/55 R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal

P

mm

Rear

R/Bal

P

mm

L/Bal

P

mm

L/Bal

P

mm

D.O.A.

31/10/22

D.O.I.

1/11/2022

Survey held at

Des. of Damages: Frt Rear O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Repair Estimate


Thiam Heng Huat Pte Ltd

176 Sin Ming Drive #05-14 Sin Ming Autocare Singapore 575721
Mobile: 82636295 Email: thiamhenghuat@gmail.com

Make/Model: MERCEDES BENZ B180
Engine/Chassis No.: WDD2462422J403892
Date of accident:
Damaged area: Front & Rear

Date: 01/11/2022
Claim Type: TP
VRN: SNG8340M

Not Authorized
6/11/2022
Running After Rain
7 days



List Items				
S/N	Parts description	QTY	UNIT PRICE	AMOUNT
1	Tailgate	1	\$ 1,841.00	\$ 1,841.00
2	Tailgate hinge	2	\$ 184.00	\$ 368.00
3	Tailgate lift absorber	2	\$ 221.00	\$ 442.00
4	Tailgate lock	1	\$ 386.00	\$ 386.00
5	Tailgate lock striker	1	\$ 82.00	\$ 82.00
6	Tailgate lock striker cover	1	\$ 65.00	\$ 65.00
7	Tailgate lamp	2	\$ 643.00	\$ 1,286.00
8	Tailgate centre chrome garnish	1	\$ 365.00	\$ 365.00
9	Tailgate "MERCEDES BENZ STAR" emblem	1	\$ 97.00	\$ 97.00
10	Tailgate "B180" emblem	1	\$ 76.00	\$ 76.00
11	Tailgate "C&C" emblem	1	\$ 98.00	\$ 98.00
12	Tailgate inner trim	1	\$ 411.00	\$ 411.00
13	Tailgate licence plate lamp	2	\$ 153.00	\$ 306.00
14	Rear bumper	1	\$ 1,318.00	\$ 1,318.00
15	Rear bumper lower panel	1	\$ 603.00	\$ 603.00
16	Rear bumper lower panel chrome moulding	1	\$ 236.00	\$ 236.00
17	Rear bumper tow cover	1	\$ 45.00	\$ 45.00
18	Rear bumper side retainer	2	\$ 136.00	\$ 272.00
19	Rear bumper reinforcement	1	\$ 790.00	\$ 790.00
20	Rear bumper reinforcement bracket	2	\$ 349.00	\$ 698.00
21	Rear bumper lower guide bracket	2	\$ 177.00	\$ 354.00
22	Rear bumper inner bracket	1	\$ 391.00	\$ 391.00
23	Rear bumper upper mount bracket	4	\$ 62.00	\$ 248.00
24	Taillamp	2	\$ 898.00	\$ 1,796.00
25	Taillamp lower bracket	2	\$ 85.00	\$ 170.00
26	Taillamp side garnish	2	\$ 79.00	\$ 158.00
27	Tailgate licence plate lamp garnish	1	\$ 137.00	\$ 137.00
28	Tailgate weatherstrip	1	\$ 189.00	\$ 189.00
29	Rear bumper chrome protector	1	\$ 398.00	\$ 398.00
30	End panel	1	\$ 719.00	\$ 719.00
31	End panel top garnish	1	\$ 372.00	\$ 372.00
32	Spare tyre floor panel	1	\$ 883.00	\$ 883.00
33	Spare tyre top board	1	\$ 365.00	\$ 365.00
34	Bonnet	1	\$ 1,520.00	\$ 1,520.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Repair Estimate

35	Bonnet hinge	1360.40	2	\$ 211.00	\$ 422.00	X
36	Bonnet logo		1	\$ 99.00	\$ 99.00	X
37	Bonnet spring		2	\$ 85.00	\$ 170.00	X
38	Bonnet actuator		2	\$ 375.00	\$ 750.00	X
39	Bonnet lock lever		1	\$ 85.00	\$ 85.00	X
40	Front bumper	1360.40	1	\$ 1,452.00	\$ 1,452.00	X
41	Front bumper reinforcement		1	\$ 756.00	\$ 756.00	X
42	Front bumper reinforcement bracket		2	\$ 276.00	\$ 552.00	X
43	Front bumper sponge		3	\$ 175.00	\$ 525.00	X
44	Front bumper retainer		2	\$ 194.00	\$ 388.00	X
45	Front grille	640.70	1	\$ 940.00	\$ 940.00	X
46	Front grille logo		1	\$ 98.00	\$ 98.00	X
47	Front bumper lower grille		1	\$ 445.00	\$ 445.00	X
48	Headlamp	02340	2	\$ 2,372.00	\$ 4,744.00	X
49	Headlamp panel		2	\$ 294.00	\$ 588.00	X
50	Headlamp garnish		2	\$ 173.00	\$ 346.00	X
51	Support panel center		1	\$ 514.00	\$ 514.00	X
52	Support panel center top garnish		1	\$ 332.00	\$ 332.00	X
53	Front bumper tow hook cover		1	\$ 93.00	\$ 93.00	X
54	Front bumper lower chrome moulding		1	\$ 364.00	\$ 364.00	X
55	Front grille inner bracket		1	\$ 98.00	\$ 98.00	X
Subtotal					\$ 31,246.00	
List discount					10.00%	
Total					\$ 28,121.40	

Special nett items					
No.	Parts description	QTY	UNIT PRICE	AMOUNT	
1	Tailgate centre chrome garnish clips	6	\$ 5.50	\$ 33.00	X
2	Tailgate inner trim clips	14	\$ 5.50	\$ 77.00	X
3	Rear bumper clips	12	\$ 5.50	\$ 66.00	X
4	Rear bumper sensor	4	\$ 280.00	\$ 1,120.00	X
5	Rear bumper sensor holder	4	\$ 67.00	\$ 268.00	X
6	Rear bumper sensor harness	1	\$ 783.00	\$ 783.00	X
7	End panel sealant	1	\$ 120.00	\$ 120.00	X
8	End panel top garnish clips	6	\$ 5.50	\$ 33.00	X
9	Spare tyre floor panel sealant	1	\$ 120.00	\$ 120.00	X
10	Rear licence plate & frame	1	\$ 55.00	\$ 55.00	X
11	Bonnet insulator clips	10	\$ 5.50	\$ 55.00	X
12	Front bumper sensor	2	\$ 280.00	\$ 560.00	X
13	Front bumper sensor holder	2	\$ 22.00	\$ 44.00	X
14	Front bumper clips	12	\$ 5.50	\$ 66.00	X
15	Front licence plate & frame	1	\$ 55.00	\$ 55.00	X
16	Support panel center top garnish clips	6	\$ 5.50	\$ 33.00	X
17	Front bumper lower lip	1	\$ 800.00	\$ 800.00	X
18	Rear bumper lower lip	1	\$ 800.00	\$ 800.00	X
19	Sundries	1	\$ 50.00	\$ 50.00	X
Total				\$ 5,138.00	

Repair Estimate

Labour			
No.	Description	Work unit	Amount
1	To dismantle / renew the accident damaged portion. To panel beat, reshape, straighten, orientate and align repair / replacement parts.	11	\$ 2,200.00
2	To disconnect front & rear wire harness of electrical components to facilitate repairs, reconnect and check functions including headlamp / taillamp lightings.	0.5	\$ 100.00
3	To remove, refit tailgate components and replace tailgate, check and re-adjust close gap, alignment and water seepage.	0.5	\$ 100.00
4	Supply spray paint material and necessary items to respray affected area / panel.	10	\$ 2,000.00
5	To rust proof all affected portions after repair.	0.5	\$ 100.00
Total labour			\$ 4,500.00

8001

401

601

8801

301

Estimate Grand Total	\$ 37,759.40
----------------------	--------------

Repair Estimate

Thiam Heng Huat Pte Ltd

176 Sin Ming Drive #05-14 Sin Ming Autocare Singapore 575721

Mobile: 82636295 Email: thiamhenghuat@gmail.com

Make/Model: MERCEDES BENZ B180

Engine/Chassis No.: WDD2462422J403892


Date of accident:

Damaged area: Front & Rear

Date: 01/11/2022

Claim Type: TP

VRN: SNG8340M



Supplementary list items				
S/N	Parts description	QTY	UNIT PRICE	AMOUNT
1	Front distance radar	1	\$ 1,541.00	\$ 1,541.00
2	Exhaust heatshield	1	\$ 399.00	\$ 399.00
3	Front licence plate base	1	\$ 194.00	\$ 194.00
Subtotal				\$ 2,134.00
List discount				10.00%
Total				\$ 1,920.60
Supplementary Estimate Grand Total			\$	1,920.60