

 $51\; UBI\; AVE\; 1, \#02-25\; PAYA\; UBI\; INDUSTRIAL\; PARK, SINGAPORE\; 408933\;\; TEL: (065)\; 62563561\;\; FAX: (065)\; 62564315\;\; FAX: (065)\; 6256415\;\; FAX: (065)\; FAX$

Immediate Advice

To: HSBC Life (Singapore) Pte. Ltd. Date: 23/03/2023

Survey Details:

Date of loss	31-Oct-22
Date of appointment	1-Nov-22
Date of survey	1-Nov-22
Location of survey	THIAM HENG HUAT PTE LT

Vehicle Details:

Claim Type:	Third pa	rty	
Vehicle number	SNG834	SNG8340M	
Make and Model	MERCED	MERCEDES B180 (1595c	
Date of registration	23/9/20	23/9/2016	
Excess			
Market Value/ Book Value	\$	72,000.00	(est)
Parf/COE Rebate	\$	35,408.00	(est)
Nett Value/ ERV	\$	36,592.00	(est)

Repair details:

Initial Estimate	\$ 39,680.00

Proposed/Revised repair cost:

Parts	\$ 13,351.59
Check items (estimate)	NIL
Labour	\$ 1,810.00
Supplementary	NIL
Total	\$ 15,161.59
Lump Sum(if applicable)	\$ 11,800.00

Number of days for repair	<u>6</u>



 $51\ UBI\ AVE\ 1,\#02-25\ PAYA\ UBI\ INDUSTRIAL\ PARK, SINGAPORE\ 408933\ \ TEL: (065)\ 62563561\ \ FAX: (065)\ 62564315$

Remarks:

SHD6665B (OI) -> SNG8340M (TP) -> SJN6208L. BOLA 28		

Mandate:

Liability(TP)	100%	
Proposed repair cost	\$ 12,744.00	(WITH 8% GST)
Loss of use	\$ 480.00	8DAYS X \$60.00
Loss of rental	NIL	
Loss of income	NIL	
LTA/GIA search fees	\$ 7.45	
Others	NIL	
Proposed Total	\$ 13,231.45	