

Section A - Accident Details

Registration Number	SHC4101E
Case Reference Number	TAX/10/22/2097
Registration Date	12/12/2017
Company Type	Strides Taxi Pte Ltd
Make	TOYOTA
Model	PRIUS4
Name of Driver	TANG CHEK FONG
Type of Accident	Head to Rear
Accident Date and Time	29/10/2022 6:10 PM
Accident Reported Date and Time	31/10/2022 3:46 PM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24116706
Special Instruction to ARC, if any	DAMAGE TO THE FRONT RIGHT DOOR (DRIVER'S SIDE)
Prepared Date and Time	1/11/2022 8:23 AM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$845.00	\$300.00
Total Spray Cost	\$1,674.00	\$470.00
Total Spare Part Cost	\$7,780.54	\$1,086.83
Total Other Cost	\$620.00	(\$306.83)
TOTAL COST	\$10,919.54	\$1,550.00 (L/S)
Lump Sum Total	\$0.00	\$0.00
Number of Repair Days	6.0	4.0
Prepared / Adjusted By	Boon Chew Tay	RASUL (LKK) / AXA
ARC / Surveyor Sign Off Date	02/11/2022 8:55 AM	01/11/2022 4:59 PM
Signature		
Remarks		LUMP SUM REPAIR / RESURVEY AFTER REPAIR

Section C - Quotation and Accident Invoice Details

Quotation Number	QN-2211-0440	Invoice Number	
Quotation Date	30.11.2022	Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates

Part 1 - Labour Works		
Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR FRONT RH PORTION	\$845.00	\$300.00 ✓
Total Labour	\$845.00	\$300.00

Part 2 - Spray Painting & Panel Beating Related Works		
Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY FRONT BUMPER	\$378.00	\$0.00
TO RESPRAY FRONT FENDER RH	\$378.00	\$200.00 ✓
TO RESPRAY FRONT DOOR RH	\$378.00	\$200.00 ✓
TO RESPRAY VIEW MIRROR	\$180.00	\$70.00 ✓
TO RESPRAY ROCKER PANEL MOULDING	\$180.00	\$0.00
TO RESPRAY RIM	\$180.00	\$0.00
Total Spray Painting & Panel Beating	\$1,674.00	\$470.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense		
Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
Lump Sum Adjustment by Surveyor	\$0.00	(\$406.83)
TO WASH AND VACUUM	\$60.00	\$0.00
TO CHECK WIRING AND SYSTEM FUNCTION	\$120.00	\$0.00
TO APPLY RUST-PROOFING ON AFFECTED AREA	\$100.00	\$40.00 ✓
TO DO WHEEL ALIGNMENT / TYRE BALANCING	\$120.00	\$0.00
TO TRANSFER DOOR MECHANISM	\$120.00	\$60.00 ✓
TO REPLACE SUNDRY PARTS	\$100.00	\$0.00
Total Other Costs	\$620.00	(\$306.83)

Part 4 - Spare Parts / Material Usage										
Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved	
		5211947962	COVER, FR BUMPER	0.00	\$560.30	0.00	\$0.00	Replace	Not Given	X
		5380147080	FENDER SUB-ASSY, FR , RH	1.00	\$1,060.70	100.00	\$0.00	Replace	Repair	R
		7537447140	EMBLEM, SIDE PANEL (HYBRID)	1.00	\$59.10	30.00	\$41.37	Replace	Replace	✓ NEC
		5387547070	LINER, FR FENDER, RH	0.00	\$223.50	0.00	\$0.00	Replace	Not Given	X
		5385147061	PAD, FR WHEEL RH	0.00	\$65.00	0.00	\$0.00	Replace	Not Given	X
		4261147450	WHEEL, DISC FRONT	0.00	\$2,036.30	0.00	\$0.00	Replace	Not Given	X
		7585047910	MOULDING ASSY, BODY ROCKER PANEL , RH	0.00	\$649.10	0.00	\$0.00	Replace	Not Given	X
		8791547070A1	COVER, OUTER MIRROR, RH	1.00	\$117.80	100.00	\$0.00	Replace	Repair	R

STRIDES Accident Vehicle Repair Estimates

STRIDES Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 04/12/2022

User ID : PohSuan

	87910474 50	MIRROR ASSY, OUTER REAR VIEW , RH	0.00	\$1,556.00	0.00	\$0.00	Replace	Not Given	X
	67001471 52	PANEL SUB-ASSY, FRONT DOOR RH	1.00	\$1,407.80	30.00	\$985.46	Replace	Replace	√ BT
		STICKER STRIDES TAXI (DOOR)	1.00	\$60.00	0.00	\$60.00	Replace	Replace	√ NEC
	68610470 40	CHECK ASSY, FRONT DOOR	0.00	\$199.40	0.00	\$0.00	Replace	Not Given	X
	68710121 51	HINGE ASSY, FRONT DOOR , UPPER RH	0.00	\$105.50	0.00	\$0.00	Replace	Not Given	X
	68730121 20	HINGE ASSY, FRONT DOOR , LOWER RH	0.00	\$120.00	0.00	\$0.00	Replace	Not Given	X
	69801210 20	DOOR FRONT WINDOW REGULATOR SUB-ASSY, RH	0.00	\$257.80	0.00	\$0.00	Replace	Not Given	X
	85710471 40	DOOR FRONT MOTOR ASSY, POWER WINDOW	0.00	\$996.60	0.00	\$0.00	Replace	Not Given	X
	69030471 00	LOCK ASSY, FRONT DOOR RH	0.00	\$655.30	0.00	\$0.00	Replace	Not Given	X
	69410201 10	DOOR LOCK STRIKER	0.00	\$42.60	0.00	\$0.00	Replace	Not Given	X
Total				\$10,172.80		\$1,086.83			

*All XX = NN

Added Spare Parts / Material Usage After Surveyor Signed off									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

	1,086.83	
+	300.00	L/S \$1,550/-
+	570.00	
	<u>1,956.83</u>	
	-20%	
	<u>1,565.46</u>	